



MISSING TOOLS DECLARATION

WARNING	
ENGINEERING MANAGER (EM)/ CHIEF ENGINEER (CE)/ LICENSED AIRCRAFT ENGINEER (LAE) SHALL NOT RELEASE THE AIRCRAFT UNTIL A THOROUGH SEARCH OF RELATED WORK AREA IS PERFORMED AND INVESTIGATION IS CONDUCTED TO CONFIRM THE TOOL IS NOT IN THE AIRCRAFT/EQUIPMENT.	
DATE	08/02/2023
AIRCRAFT REGISTRATION	
TOOL DETAILS	
G4405 - Plier MKK stapler	
LOANER DETAILS	
NAME	UMK
STAFF NUMBER	UMK
WORK AREA	UMK
TASK	UMK
LAE IN CHARGE	UMK
ACTION TAKEN BY (EM / CE / LAE)	
N/A	
SEARCH TEAM (NAME)	
1	MUSTAFA BINA B. MAJLUM
2	IZRA MUMUKAT BINI ISKANDAR
3	MUHAMMAD FARIS HAJIMI BIN MUHYI JUSDI
4	
AREA SEARCH	
All Area Hangar checked	
REMARKS	
Nil tools found	

I HEREBY DECLARE THAT ALL AREA HAS BEEN CHECKED THOROUGHLY WHERE RELATED WORK AREA IS PERFORMED AND INVESTIGATION IS CONDUCTED TO CONFIRM THE TOOL IS NOT IN THE AIRCRAFT/EQUIPMENT.

NAME	MUHAMMAD JAMIL SAMSUBIN
POSITION	AVIONICS CONTROLLER
DATE	8/2/2023
SIGNATURE & STAMP (if available)	 

NOTE

- Form to be filled up by Engineering Manager / Chief Engineer / Licensed Aircraft Engineer.
- Completed form to be submitted to QAM and kept in respective staff personal file