

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p>Address: Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p>Attention: Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my</p>	<p>Work Order Number: 2022-11184</p> <p>Work Pack Reference: 9M-BOC-11184</p> <p>Date Issued: 18/05/2022</p> <p>A/C Registration / SN: 9M-BOC/31289</p> <p>Sheet: 1 of 1</p>
--	---

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	300H//1Y SBA139-661 REV.B PART II (EASA AD NO.: 2021-0044 PARA (2)) <i>Due at 05/08/2022</i>		_____ (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxyaerospace.my



CLIENT/OWNER: JABATAN BOMBA DAN PENYELAMAT MALAYSIA AIRCRAFT TYPE: AW139 REGISTRATION: 9M-BOC BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	11184-001	
	AIRCRAFT	31289	REFER WORKPACK		WORK/INSP/DESC:	300H//1Y SBA139-661
	#1 ENGINE:	PCE-KB0661	REFER WORKPACK		WORKPACK REF:	9M-BOC-11184
	#2 ENGINE:	PCE-KB0659	REFER WORKPACK		AJL REF NO.:	REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1	

Reason for raising: 300H//1Y SBA139-661 REV.B PART II (EASA AD NO.:2021-0044 PARA (2)) TO BE CARRIED OUT IN ACCORDANCE WITH JBPM/CAMO/AMP/AW139 ISSUE 02 REVISION 01 AW139 IETP - 40TH ISSUE: 2021-12-10 UPDATED: 2022-03-07 EMM PT6C-67C ISSUE NO. 29.0 DATED MAY-09-2022 OR LATEST APPROVED REVISION 300H//1Y SBA139-661 REV.B PART II (EASA AD NO.:2021-0044 PARA (2))	Raised by and date: CAMO: Mohd Haffiz Ismail 18/05/2022	Other requirements/information: NIL
--	---	--

Item	Description	Technician	* Eng. CRS	Date
1	300H//1Y EASA AD NO.: 2021-0044 PARA (2), SBA139-661 REV.B PART II PERFORM A RECURRENT INSPECTION INSIDE THE OVERHEAD PANEL IN ORDER TO CHECK THE TAPE CONDITION AND THE ABSENCE OF CHAFING. REFERENCES: EASA AD NO. 2021-0044 DATED 05 FEBRUARY 2021, SBA 139-661 DATED 09 MAY 2022 REMARKS:			

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK.	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD.RECORD BOOK
--------------------------	-------------	-----------------	------------	-------------	-------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date:
	Number:	
	Revision:	

Customer Name and Address:	Telephone:
	Fax:
	B.T. Compliance Date:

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.

Remarks:

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.