

TIC-AW139-21-0273 (JPM ONLY)

SB NO. 139-643, NEW ISSUE

ATA 25 - SINGLE TO DOUBLE HOIST CONVERSION

AD/SB ID: 8324

General | Config List | Aircraft List | Task List | Linked To | BOM

Type :	SBS ▾ <input type="checkbox"/> Repetitive
Reference/Number:	ATA 25 - SINGLE TO DOUBLE HOIST CONVERSION
Title/Subject:	SB NO. 139-643, NEW ISSUE
Version No:	
Reason For Raising:	

Edit Limitation

Edit Limitation

 Cancel  Save

Linked To:

Based On:

Warning:

Warning Unit:





























Completed:

Due At:

Status:

Limitation Notes:

TIC-AW139-21-0273
APPLICABILITY: NOT APPLICABLE DUE TO AIRCRAFT S/N NOT AFFECTED
OPTIONAL SE

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	Not Applicable	-		0	-	-	Required	
	9M-BOC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-BOD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMA	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMB	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMD	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PME	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-SAAS	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-SBH	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	