

Aircraft Registration: 9M-PTA Date of Values: 30/11/2021 | Airframe: 5875.27 Save to template Close Update Save & Close

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADS SBs Flight History Documents SORS Jobs History Notes Rates Users												
With Selected						Show N/A	Add SB	Sortable	Locked			
Repetitive SBs [View All] History												
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining		
SERVICE BULLETINS - AIRFRAME												
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	25/09/2021 ↗	24/09/2022 ↗	298 days +	Complete ↗	
Standard SBs [View All] History												
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status		
SERVICE BULLETINS - AIRFRAME												
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	-	CANCELLED ↗	

Aircraft Registration: 9M-PTB Date of Values: 29/11/2021 | Airframe: 5413.16 Save to template Close Update Save & Close

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADS SBs Flight History Documents SORS Jobs History Notes Rates Users												
With Selected						Show N/A	Add SB	Sortable	Locked			
Repetitive SBs [View All] History												
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining		
SERVICE BULLETINS - AIRFRAME												
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	23/07/2021 ↗	22/07/2022 ↗	234 days +	Complete ↗	
Standard SBs [View All] History												
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status		
SERVICE BULLETINS - AIRFRAME												
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	-	CANCELLED ↗	

Aircraft Registration: 9M-PTC Date of Values: 01/12/2021 | Airframe: 3981.26 Save to template Close Update Save & Close

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADS SBs Flight History Documents SORS Jobs History Notes Rates Users												
With Selected						Show N/A	Add SB	Sortable	Locked			
Repetitive SBs [View All] History												
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining		
SERVICE BULLETINS - AIRFRAME												
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	22/10/2021 ↗	21/10/2022 ↗	324 days +	Complete ↗	
Standard SBs [View All] History												
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status		
SERVICE BULLETINS - AIRFRAME												
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	-	CANCELLED ↗	

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected						Show N/A Add SB Sortable Locked					
Repetitive SBs [View All]										History	
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	30/08/2021 ↗	02/09/2022 ↗	275 days +	Complete ↗
Standard SBs [View All]											History
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	CANCELLED ↗	

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users											
With Selected						Show N/A Add SB Sortable Locked					
Repetitive SBs [View All]										History	
<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	26/07/2021	01/08/2022 ↗	244 days +	Complete ↗
Standard SBs [View All]											History
			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status	
<input type="checkbox"/>				MTL-32-02, REV 1 LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT			-	-	-	CANCELLED ↗	

Edit Limitation MTL-32-02, REV 1 -LANDING GEAR- MAIN LANDING GEAR TORQUE- K... Cancel Save

Based On:

Warning:

Warning Unit:

Completed:

Due At:

Status:

Limitation Notes: