

**Edit Limitation MTL-25-03 REV. /-EQUIPMENT/FURNISHINGS - ANNOUNCEMENT OF IP...** Cancel Save

Based On:

Warning:

Warning Unit:

Completed:

Due At:

Status:

Limitation Notes:

Aircraft Registration: 9M-PTA Date of Values: 08/12/2021 | Airframe: 5903:11 Save to template Close Update

General Log Book **Inspections** Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
SERVICE BULLETINS - AIRFRAME											
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	25/09/2021 ↗	24/09/2022 ↗	290 days +	Complete ↗

Standard SBs [View All]

<input type="checkbox"/>				PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>					MTL-25-03 REV. / EQUIPMENT/FURNISHINGS - ANNOUNCEMENT OF IPECO SB480-25-01 CARRIER AND BRAKE IMPROVEMENT FOR PASSENGER SEATS		-	-	-	-	NOT APPLICABLE ↗

Aircraft Registration: 9M-PTB Date of Values: 08/12/2021 | Airframe: 5417:11 Save to template Close Update

General Log Book **Inspections** Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	23/07/2021 ↗	22/07/2022 ↗	226 days +	Complete ↗

Standard SBs [View All]

<input type="checkbox"/>				PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>					MTL-25-03 REV. / EQUIPMENT/FURNISHINGS - ANNOUNCEMENT OF IPECO SB480-25-01 CARRIER AND BRAKE IMPROVEMENT FOR PASSENGER SEATS		-	-	-	-	NOT APPLICABLE ↗

Aircraft Registration: 9M-PTC Date of Values: 08/12/2021 | Airframe: 3988.37

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	22/10/2021 ↕	21/10/2022 ↕	317 days +	Complete ↕

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				MTL-25-03 REV. / EQUIPMENT/FURNISHINGS - ANNOUNCEMENT OF IPECO SB480-25-01 CARRIER AND BRAKE IMPROVEMENT FOR PASSENGER SEATS		-	-	-	-	NOT APPLICABLE ↕

Aircraft Registration: 9M-PTD Date of Values: 25/11/2021 | Airframe: 1185.50

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	30/08/2021 ↕	02/09/2022 ↕	268 days +	Complete ↕

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				MTL-25-03 REV. / EQUIPMENT/FURNISHINGS - ANNOUNCEMENT OF IPECO SB480-25-01 CARRIER AND BRAKE IMPROVEMENT FOR PASSENGER SEATS		-	-	-	-	NOT APPLICABLE ↕

Aircraft Registration: 9M-PTE Date of Values: 22/11/2021 | Airframe: 2024.56

General Log Book Inspections Components Airframe Engine 1 Engine 2 Modifications ADs SBs Flight History Documents SORs Jobs History Notes Rates Users

With Selected Show N/A Add SB Sortable

Repetitive SBs [View All]

<input type="checkbox"/>			PDF	SB Number/Subject ▲	Based On	Period	Warning	Last SB	Next SB	Remaining	
<input type="checkbox"/>				SB 27-3459 REV. 2 ATA 27 - FLIGHT CONTROLS - FLIGHT CONTROL GUST LOCK INSPECTION/ REPLACEMENT (RECURRING INSP)	Date (Months)	12.0	3.0 Months	26/07/2021	01/08/2022 ↕	236 days +	Complete ↕

Standard SBs [View All]

			PDF	SB Number/Subject ▲	Based On	Warning	Completed	Due At	Remaining	Status
<input type="checkbox"/>				MTL-25-03 REV. / EQUIPMENT/FURNISHINGS - ANNOUNCEMENT OF IPECO SB480-25-01 CARRIER AND BRAKE IMPROVEMENT FOR PASSENGER SEATS		-	-	-	-	NOT APPLICABLE ↕