



1200 E. 151st Street
Olathe, KS 66062
913-397-8200

AVIATION SERVICE DOCUMENT NOTIFICATION

TO: Garmin GI 275 Owner and Operators
DATE: September 24, 2021
SUBJECT: GI 275 Multi-Function Instrument Software Version v2.41 Update
CERTIFICATION AUTHORIZATION: STC SA02658SE MDL Revision 13

COMPLIANCE

Mandatory: This STC Service Bulletin must be incorporated for affected installations. This service bulletin is recommended for all other installations.

WARRANTY INFORMATION

This modification is only warranty reimbursable for installations described in the Products Affected section.

Warranty reimbursement deadline is February 28, 2022.

Note: Installations completed after September 24, 2021 are not eligible for warranty reimbursement.

PURPOSE

This STC Service Bulletin provides notification of STC SA02658SE Master Drawing List Revision 13 update which includes GI 275 Expansion Board Software improvement to provide additional robustness for the GI 275 ADAHRS solution.

PRODUCTS AFFECTED

Aircraft modified with the GI 275 Multi-Function Instrument AML STC SA02658SE, MDL Revision 12 or earlier with a single pitot-static system that are equipped with dual GI 275 ADAHRS (Air Data & Attitude Heading Reference System) products [011-04489-10, 011-04489-20] installed as the only means to determine aircraft attitude.

Please contact your local Garmin Avionics Dealer (<http://www.garmin.com/dealers/>) for additional information or for questions regarding this notification. This service notification and associated bulletin/advisory product changes can only be implemented through Garmin's authorized dealer and service center network. This document is not a substitute for and cannot be used in lieu of the document(s) referenced above for airworthiness approval.