

# SERVICE BULLETIN

**Reference:** 342-49-050 – SERVICE BULLETIN**Title:** Introduction of New Rear Mount Reference**Issue number:** 001**Issue Date:** 27-apr-2023**Responsible Partner Company:** A0126**Originator:** F1989**Category:** 5 - Spare parts information**Applicability:** All**Related SB:** 342-49-051**Related Documents:** None**Accomplishment:**  Once only  Recurring**Planned to be incorporated in Technical Publications:**  
 Yes  No

---

**SAFRAN POWER UNITS PROPRIETARY INFORMATION**

All information and data appearing in this document are the exclusive property of SAFRAN POWER UNITS. They are made available to any person required to comply with the terms of the instructions for maintaining the airworthiness of the APU.

Any other use of said information and data, including, but without limitation, design, manufacture, development, or derivation of any repairs, modifications, spare parts or configuration changes or to obtain EASA or any other government regulatory approval to do so, is subject to prior agreement from SAFRAN POWER UNITS. This document shall not be used, copied, reproduced, duplicated, modified or disclosed in whole or in part for any purpose other than maintaining the airworthiness of the APU without the express written consent of SAFRAN POWER UNITS. If such consent is given, this notice and the notice set forth on each page of this document shall also be reproduced.

All information and data contained herein, with respect to assembly and disassembly, cleaning, inspection methods and limits, repair methods and limits, operational limits, life limits and the like, have been developed and approved for use with equipment and parts that have been manufactured and/or approved by SAFRAN POWER UNITS and that have been maintained in accordance with SAFRAN POWER UNITS technical documentation and recommendations. SAFRAN POWER UNITS has no contractual or legal obligation for, nor knowledge of, parts and repairs not approved by SAFRAN POWER UNITS. Accordingly, this document is not intended to apply to parts and repairs not approved by SAFRAN POWER UNITS.

---

**© 2023 Safran Power Units All rights reserved. Confidential and Proprietary.**

---

# SERVICE BULLETIN

**342-49-050**

## 1. Revision information

Issue	Date	Reason for update
001	27-apr-2023	Original issue

## 2. Planning information

### 2.1. Applicability

This Service Bulletin (SB) is applicable to all APU power plant fitted on Leonardo Helicopters AW189/AW149 helicopters.

### 2.2. Reason

The purposes of this modification is to introduce new rear mount reference to improve the interface between the carrier and the APU.

The purpose of this Service Bulletin is to introduce modifications n°342/419.

### 2.3. Description

The Service Bulletin introduces new rear mount reference.

### 2.4. Compliance

#### 2.4.1. Compliance category

Comply with compliance category 5 - Spare parts information.

#### 2.4.2. Time of compliance

Not applicable

### 2.5. Approval

The technical content of this document is approved under the authority of DOA No. EASA 21J214.

### 2.6. Manpower

Not applicable.

### 2.7. Material

Not applicable.

### 2.8. Tooling

Not applicable.

### 2.9. Weight and balance

The weight is not affected.

The centre of gravity is not affected.

# SERVICE BULLETIN

**342-49-050**

## 2.10. Publication affected

DT 13-02 – Engine Manual ML3

## 2.11. Previous modifications

Not applicable.

## 3. Accomplishment Instructions

Not applicable.

## 4. Material information

### 4.1. Support equipment

Not applicable.

### 4.2. Material requirements

Not applicable.

### 4.3. List of components

Old Part Number	Name	Qty Old/New	New Part Number	Operation Code	Change Code	Support Code
342-50-11 F1989	APU Power Plant	1/1	341-50-11 F1989	RM	-	-
. 341-01-12 F1989	Gas Generator	1/1	. 341-01-12 F1989	RM	-	-
.. 341-01-238-01 F1989	Engine Mount	1/1	.. 341-01-238-02 F1989	RE	1	B
... E341-01-241-01 F1989	Bushing	1/1	... E341-01-241-02 F1989	RE	1	A
... E341-01-242-01 F1989	Bushing	1/1	... E341-01-242-02 F1989	RE	1	A
... E341-01-239 F1989	Engine mount	1/1	... E341-01-239 F1989	RM	-	-
... E341-01-240 F1989	Bushing	4/4	... E341-01-240 F1989	RM	-	-

- Operation Code  
RE = Replaced  
RM = Remains
- Change codes. These codes give the interchangeability of the new part with the old one.  
1 = One-way interchangeable
- Support codes. These codes are used to determine parts availability.  
A = Old parts will no longer be supplied.  
B = Old parts will be supplied until inventory is depleted.

### 4.4. Interchangeability

Physical interchangeability: ..... Not affected

Functional interchangeability: ..... Not affected

**SERVICE BULLETIN****342-49-050**

Restriction of mixability:..... Restriction as indicated below

**4.4.1. Restriction of mixability:**

At first rear mount inspection opportunity in MRO center, a retrofit of the rear mount shall be performed when removing the bushings. Only new bushings will be installed on rear mount after the inspection.

**4.5. Parts disposition**

Not applicable.

**4.6. Procurement conditions**

The new parts will be provided at conditions indicated in Safran Power Units' price catalogue.

**END OF SERVICE BULLETIN**