

- (1) Particulars of all maintenance work
- (2) Particulars of all overhauls, repairs,
- (3) Particulars of any defects occurring
- (4) Certificate that in carrying out the

done on the aircraft.
 replacements, modifications and mandatory inspections relating to the aircraft or its equipment.
 in the aircraft or its equipment and of the rectification of such defects including a reference to the relevant entries in the technical log,
 overhaul, repairs, etc. all mandatory requirements applicable thereto have been complied with.
 (5)

CERTIFICATE OF MAINTENANCE REVIEW

QMR NO: 44
 NATIONALITY AND REGISTRATION MARK: 9M-PEA
 SERIAL NO: 1234



LOG BOOK ENTRY

A/C Type	A/C SN	A/C TT	A/F Cye		
EC120B	1275	3893.20	5673		
Engine Type & S/N:		TT	NG	NF	NP
#1 : 34241		2197.00	2450.10	3177.95	-
N/A		N/A	N/A	N/A	-

For details of work performed, refer to AHM Work Order No.:

9M-PEA
 M-PEA
 2014 395 001
 2014 395 002

14 477 001

9M-PEA	
or details of work performed, refer to AHM Work Order No.:	2014 573 001

9M-PEA	
or details of work performed, refer to AHM Work Order No.:	2014 537 001

N/A Airframe / N/A Engine inspection performed i.a.w the requirements of the Malaysian Civil Aviation Regulation / FAA Regulation for the time being in force and in that respect the aircraft/equipment is considered fit for Release to Service under CRS-SMI # N/A

Defect / Rectification / Out of Phase Inspection:

- Engine oil performed.
- Helicopter pre-flight self-test performed.
- Helicopter fuel tanks drained.
- Helicopter fuel cell replaced. P/N: 501009, S/N: 105965 (OFF) P/N: 7050C4281041, S/N: 121897 (ON)
- Helicopter fuel cell removed. P/N: 501101, S/N: 107163 (OFF) P/N: 7050C4281042, S/N: 122362 (ON)
- Helicopter Tailboom inner skin repaired.

AD / SR performed during this inspection:

-N/A

Engine AD / SR performed during this inspection:

-N/A

Place and date: Subang, 15-September-2014

Sign and stamp: [Signature]

AHM.51.019a Rev 2 (06/06/2014)

51.019a Rev 2 (06/06/2014)



AHM.51.019a Rev 2 (06/06/2014)

AHM.51.019a Rev 2 (06/06/2014)



LOG BOOK ENTRY

A/C Type	A/C SN	A/C TT	A/F Cye		
EC120B	1275	3896.35	5696		
Engine Type & S/N:		TT	NG	NF	NP
#1 : 34241		2200.15	2453.85	3184.69	-
N/A		N/A	N/A	N/A	-

For details of work performed, refer to AHM Work Order No.:

9M-PEA
 M-PEA
 2015 030 001

9M-PEA	
or details of work performed, refer to AHM Work Order No.:	2014 566 001

9M-PEA	
or details of work performed, refer to AHM Work Order No.:	2014 537 001

N/A Airframe / N/A Engine inspection performed i.a.w the requirements of the Malaysian Civil Aviation Regulation / FAA Regulation for the time being in force and in that respect the aircraft/equipment is considered fit for Release to Service under CRS-SMI # N/A

Defect / Rectification / Out of Phase Inspection:

- Performed battery replacement. P/N: 151CH1 S/N: 002544 (OFF) S/N: 104362 (ON)

AD / SR performed during this inspection:

-N/A

Engine AD / SR performed during this inspection:

-N/A

Place and date: Subang, 15-OCTOBER-2014

Sign and stamp: [Signature]



AHM.51.019a Rev 2 (06/06/2014)

51.019a Rev 2 (06/06/2014)

51.019a Rev 2 (06/06/2014)