



DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
CAMO DEPARTMENT
Lot 11, MRO Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor
Malaysia.
Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/22/PMA-177
OUR REFERENCE : 9M-PMA-12169
WO REFERENCE : 2022-12169
DATE COMPLETION: 30 JULY 2022
AJL NUMBER : AJL 00089

A/C TYPE	AW139	A/C REG	9M-PMA	A/C S/N	31807
OWNER / OPERATOR	ROYAL MALAYSIA FORCE	A/C TOTAL TIME	1469:50	LANDINGS	2416
ENGINE #1 S/N	PCE-KB2069	T.S.N	1469:50	T.S.O	-
ENGINE #2 S/N	PCE-KB2067	T.S.N	1469:50	T.S.O	-

EASA AD 2022-0152-E PARA (1), (SBEA 139-725 REV./PART I), ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT BFF AND EVERY 10FH)	001	1	1	-	-	2	-

*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE:

NAME	ROLENZO ROBERT	SIGNATURE		DATE	02 AUG 2022
VERIFIED AND ACCEPTED BY			ZULKARNAEN BIN IBRAHIM Technical Record and Publication Officer Galaxy Aerospace (M) Sdn Bhd (1040262-D)		
DATE			02 AUG 2022		

- *WS – WORKSHEET
- *PR – PART REPORT
- *ARC – AUTHORISED RELEASE CERTIFICATE
- *S – SERVICEABLE LABEL
- *SBC – SERVICE BULLETIN COMPLIANCE
- *OTH – OTHERS

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia
 International Aerospace Centre, SAAS Airport,
 Subang
 Malaysia

Attention: Mr. Syafrul Yamani
 Engineering Manager
 syafrul@galaxy aerospace.my

Work Order Number: 2022-12169

Work Pack Reference: 9M-PMA-12169

Date Issued: 26/07/2022

A/C Registration / SN: 9M-PMA/31807

Sheet: 1 of 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	EASA AD 2022-0152-E PARA (1), (SBEA 139-725 REV./ PART I), ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT BFF AND EVERY 10FH)	EASA AD 2022-0152-E PARA (1), (SBEA 139-725 REV./ PART I)	<u>2</u> (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxy aerospace.my



CLIENT/OWNER: ROYAL MALAYSIA POLICE AIRCRAFT TYPE: AW139 REGISTRATION: 9M-PMA BASE/FACILITY: WBKK DATE IN: 30/07/22 OUT: 30/07/22		SERIAL NO.	HOURS	LDG/CYCLE	WORKPACK NO: 9M-PMA-12169	
	AIRCRAFT	31807	1469:50	2416	WORK/INSP/DESC: AD 2022-0152-E EASB	
	#1 ENGINE:	PCE-KB2069	1469:50		AERONET JOB NO.: 2022-12169	
	#2 ENGINE:	PCE-KB2067	1469:50		AJL REF NO.: 00089	
				NG / N1	NF / N2	SHEET: PAGE 01 OF 01

Reason for raising: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0152-E NEW ISSUE DATED 26-JULY-2022, EASB 139-725 NEW ISSUE DATE 25-JULY-2022, AW139 IETP - 41TH ISSUE DATED 2022-06-28 UPDATE 001 DATE 2022-07-20 OR LATER APPROVED REVISION	Raised by and date: CAMO; Zulkarnaen Ibrahim 26/07/2022	Other requirements/information: NIL
--	---	--



List of scheduled inspection and all work carried out under this workpack including individual reference			DATE INSPECTION COMPLETED	Master Signature Schedule		
NO.	INSPECTION / WORK	WORKSHEET REF		NAME	SIGNATURE	APP/STAMP
1	EASA AD 2022-0152-E NEW ISSUE PARA (1), (SBEA 139-725 NEW ISSUE PART 1)	12169-001	30/07/22	WONG K SIEN	[Signature]	
				JOSHUA	[Signature]	8109

PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND <input checked="" type="checkbox"/> * OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE <input type="checkbox"/> * IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION..... <input type="checkbox"/> * TICK ✓ WHERE APPLICABLE	NAME	WONG K SIEN
	SIGN & APPROVAL	[Signature]
	FIRM	GAM
	DATE	30/7/2022

PART M - CAMO ACCEPTANCE STATEMENT THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE.	NAME	WAN KHAIKUL FAHMI BIN WAN SAMSUDIN
	SIGN & APPROVAL	[Signature]
	DATE	02/08/2022

CLIENT/OWNER: ROYAL MALAYSIA POLICE AW139 AIRCRAFT TYPE: REGISTRATION: 9M-PMA BASE/FACILITY: WBKK DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	12169-001
	AIRCRAFT	31807	REFER WORKPACK		WORK/INSP/DESC:	EASA AD 2022-0152-E
	#1 ENGINE:	PCE-KB2069	REFER WORKPACK		WORKPACK REF:	9M-PMA-12169
	#2 ENGINE:	PCE-KB2067	REFER WORKPACK		AJL REF NO.:	REFER WORKPACK
			NG / N1	NF / N2	SHEET:	1 OF 1

Reason for raising: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0152-E NEW ISSUE DATED 26-JULY-2022, EASB 139-725 NEW ISSUE DATE 25-JULY-2022, AW139 IETP - 41TH ISSUE DATED 2022-06-28 UPDATE 001 DATE 2022-07-20 OR LATER APPROVED REVISIONS.	Raised by and date: CAMO; Zulkamaen Ibrahim 26/07/2022	Other requirements/information: NIL
--	---	--

Item	Description	Technician	* Eng. CRS	Date
1	EASA AD 2022-0152-E PARA (1), (SBEA 139-725 REV./ PART I) COMPLIANCE TO PERFORM EASA AD 2022-0152-E PARA (1), (SBEA 139-725 REV./ PART I) COMPLIANCE I.A.W. ACCOMPLISHMENT INSTRUCTION OF THE EASA AD 2022-0152-E PARA (1), (SBEA 139-725 REV./ PART I) PART I REQUIRES TO APPLY A SLIPPAGE MARK BETWEEN THE PCR AND THE TRUNNION INSTALLED ON THE BACK-END OF THE TRA AND TO PERFORM REPETITIVE INSPECTIONS FOR ABSENCE OF ROTATION OF THE PARTS. IF THE INSPECTION FAILS, THE BEARING MUST BE REPLACED IMMEDIATELY. COMPLIANCE: BEFORE NEXT FLIGHT AFTER THE EFFECTIVE DATE OF THIS AD, AND, THEREAFTER, AT INTERVALS NOT TO EXCEED 10 FH REMARKS: <i>CHART SAYS</i>	<i>J</i> 8109		30/7/2022 

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.



TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	CEM/COMP LOG CARD	MOD RECORD BOOK
--------------------------	------------	-----------------	------------	-------------	------------	----------------------	------------------	-------------------	--------------	---------------	------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 30/7/2022
	Number: SBEA 139-725.	
	Revision: -	

Customer Name and Address: GALAXY AEROSPACE (M) SDN BHD (GADING GROUP OF COMPANIES) Suite 11-14, Helicopter Centre, GALAXY AEROSPACE (M) SDN BHD Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN	Telephone: 603-7734 7226
	Fax: 603-7734 7226
	B.T. Compliance Date: 30/7/2022

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW139	31807	1	1469;50	-

Remarks: clear SATIS  

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.

SB 139-725 Rev. 1 – Inspection Report

Date	30/7/2022		
Helicopter	S/N	FH	Landings e.t.c.
	31807	1469:50	2413 2416
Sliding Control Assembly where bearing is installed	S/N	FH	
	781	1469:50	
TR Duplex Bearing	P/N	S/N	FH
	36430V00153	17196	1469:50
TR Duplex Bearing previously removed and reinstalled	YES		NO
	<input checked="" type="checkbox"/>		<input type="checkbox"/>



SB Part performed	Part I	Part II	Part III	Part IV				
	<input checked="" type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	A	B	C	D	E
				<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>	<input type="checkbox"/>
* For Part I, Part II or Part III please also fill the applicable parts of the table below. * For Part IV flag the Effectivity/Compliance applicable case.								

PROCEDURE STEP FAILED	DESCRIPTION OF FINDINGS
Part I Step 3 or Part III Step 5	N/A
Parts II or III Step 3.1	
Parts II or III Step 3.2	
Parts II or III Step 3.4	
Parts II or III Step 3.5	
Part II Step 3.6	
Notes: NIL	



Figure 4

S.B. N°139-725 EMERGENCY ALERT
DATE: July 25, 2022
REVISION: /



CLIENT/OWNER: ROYAL MALAYSIA POLICE AIRCRAFT TYPE: AW139 REGISTRATION: 9M-PMA BASE/FACILITY: WBKK DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 12169-001
	AIRCRAFT	31807	REFER WORKPACK		WORK/INSP/DESC: EASA AD 2022-0152-E
	#1 ENGINE:	PCE-KB2069	REFER WORKPACK		WORKPACK REF: 9M-PMA-12169
	#2 ENGINE:	PCE-KB2067	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

REASON FOR RAISING: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0152-E NEW ISSUE DATED 26-JULY-2022, EASB 139-725 NEW ISSUE DATE 25-JULY-2022, AW139 IETP - 41TH ISSUE DATED 2022-06-28 UPDATE 001 DATE 2022-07-20 OR LATER APPROVED REVISIONS.	Raised by and date: CAMO: Zulkarnaen Ibrahim 26/07/2022	Other requirements/information: NIL
---	--	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
(The entire table body is crossed out with a diagonal line)									

NAME	FIRM	SIGN & APPROVAL	DATE
YONG K. SIEN	GAM		30/7/2022

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABELED & RETURNED	D.D. RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D.D. STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	DEMCOMP LOG CARD	MOD RECORD BOOK
--------------------------	-------------	-----------------	------------	-------------	------------	----------------------	------------------	-------------------	--------------	---------------	-------------	-------------------	-----------------	--------------------	----------	------------------	-----------------