DELIVERY NOTE WP



DELIVER TO:

GALAXY AEROSPACE (M) SDN. BHD.

CAMO DEPARTMENT

Lot 11, MRO Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport,

47200 Subang, Selangor

Malaysia.

Attn: Zaty Nadhira binti Mohamed Zuhari

DN NUMBER: GAM/DN/22/PMA-018

OUR REFERENCE: 9M-PMA-9431

WO REFERENCE: 2022-9431

DATE COMPLETION: 06 JANUARY 2022

AJL NUMBER: 05520

			A/C	DETAIL	S				
A/C TYPE	AW	139	A/C REG	9M-PMA 1254:20		A/C S/N		31807 2041	
OWNER / OPERATOR		IALAYSIA RCE	A/C TOTAL TIME			LANDINGS			
ENGINE #1 S/N	PCE-K	B2069	T.S.N	1	254:20	T.S.O		-	
ENGINE #2 S/N	PCE-K	B2067	T.S.N	1	254:20	T.S.O			
LIST OF TASK PER	FORMED	WP			NUMB	ER OF PAGES			
LIST OF TASK PER	PORIVIED	NUMBER	*WS	*PR	*ARC	*S	*SBC	*OTH	
SB 139-601 REV. COMPLIAN		001	1	1	-	-	1	17.	
THIS IS TO CERTIFY 1	LI SASAT TAUL	ISTED AROVE I	HAS REEN ACCOME	DUSHED A	AS PER PO//WOR	K ORDER/SERVICE	ORDER NO. AS	ABOVE.	
	FAWATI ABI		SIGNATURE		DATE			13 JAN 2022	
		VERIF	IED AND ACCEPT	ED BY	Khalis	AHMAD KHALIS CAMO Planne Galaxy Aerospace (104026	M) Sdn Bhd		
				DATE	1	3/01/2	-		

*WS – WORKSHEET

*PR - PART REPORT

*SBC - SERVICE BULLETIN COMPLIANCE

*ARC – AUTHORISED RELEASE CERTIFICATE *OTH – OTHERS

GAM/E-015



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

www.gala.lva.arbspace.mv lienguiry i galaxyaerospicosimy

WORK ORDER



GALAXY AEROSPACE (M) SDN. BHD.

Address: Lot 11-14, MRO Centre, Malaysia

International Aerospace Centre, SAAS Airport,

Subang

Malaysia

Attention: Mr. Syafrul Yamani

Engineering Manager

syafrul@galaxyaerospace.my

Work Order Number:

2022-9431

Work Pack Reference:

9M-PMA-9431

Date Issued:

05/01/2022

A/C Registration / SN:

9M-PMA/31807

Sheet:

1

of

1

Description:

Item

Description/Task/Inspection

SB 139-601 REV. / PART I COMPLIANCE

DUE: 1343:05 FH // 26 MARCH 2022

Reference SB 139-601 REV. /

DATED 27 DECEMBER 2021

Man Hours

1.0 (PLEASE ADVISE)

Remark/Notes:

- 1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.

 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- 6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards.

Zaty Nadhira Mohamed Zuhari

Continuing Airworthiness Management Manager

Email: zaty@galaxyaerospace.my



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

WORKPACK

			1	0.00	1		I IRRUIT II		HARIN INILI EINEN HINLIINI HAI
CLIENT/OWNER: ROYAL MALAYSIA POLICE AIRCRAFT TYPE: AW139 AIRCRAFT		SERIAL NO.	HOURS	LDG/CYCLE		WORKPACK N	O: 9M-PMA-	9M-PMA-9431	
		AIRCRAFT	31807	1254:20	204	†)	WORK/INSP/D	777 7777	01 REV. / PART I
	RATION: 9M-PMA	#1 ENGINE:	PCE-KB2069		-	_	AERONET JOE	NO.: 2022-943	1
	ACILITY: WBKK	#2 ENGINE:	PCE-KB2067		-	-	AJL REF NO.:	05520)
DATE IN	16/1/22 OUT:6/1/22				NG / N1	NF/N2	SHEET:	1 OF 1	
Reason SB 139-	of or raising: 601 REV. / PART I COMPLIANCE TO 27 DECEMBER 2021	I.A.W SB 139-60	A.W SB 139-601 REV. /		and date: IPH; Ahmad nalis	Other requirements/information: NIL			
List	of scheduled inspection and all w		under this			Master	Signature Scheo	lule	
NO.	workpack including individ		WORKSHI	EET REF	N.A	AME	TECH(INITIAL	SIGNATURE	APP/STAMP
1	SB 139-601 REV. / PART I COMPL		9431-	001	MA	RRT	h	1/	MOO4
					nav	40	2	70	HALAVSI .
							4		
-									
								1-	
				- 14					
			1						
									=
								· · · · · · · · · · · · · · · · · · ·	
PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN							FIRM	SIGN & APPROVAL	- DATE
INSPECT	ED AND ACCOMPLISHED IN ACCORDANC CTED AMO EXPOSITION AND PROCEDUR	E LATEST	Lan	224	JOIN	10	GAM	A REPOS	6/1/72
REVISIO	N, AND BLICATION/REVISION \$18 39 - 60 DECEMBER 2021) Pev. 1	41111					MOO4	
PART M	N, AND		NAME				FIRM	SIGN & APPROVAL	_ DATE



GALAXY AEROSPACE (M) SDN. BHD. [1040282-D]

WORKSHEET

CLIENT/OWNER: ROYAL MALAYSIA			SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET	0: 9431-001			
	POLICE	AIRCRAFT	31807	REFER W	VORKPACK	WORK/INSP/DE	SC: ATA 33 - IN	NSPECTION AND		
	FT TYPE: AW139 RATION: 9M-PMA	#1 ENGINE:	PCE-KB2069	REFER W	VORKPACK	WORKPACK REF: 9M-PMA-9431 AJL REF NO.: REFER WORKPAC		131		
	ACILITY: WBKK	#2 ENGINE:	PCE-KB2067	REFER W	VORKPACK			ORKPACK		
					NG / N1 NF / N2	SHEET: 1	OF	1		
Reason SB 139-60	NATE IN: REFER WORKPACK OUT: REFER WORKPACK Reason for raising: B 139-601 REV. / PART I COMPLIANCE TO BE CARRY OUT I.A.W SB 139-601 REV. / DATED 27 ECEMBER 2021 ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT Raised by and date: CAMO RMPH; Ahmad Khalis 05/01/2022					Other requirements/information:				
Item		Desc	ription			Technician	* Eng. CRS	Date		
1	SB 139-601 REV. / PART I COMP		in paori				1			
	ATA 33 - INSPECTION AND REII	NFORCEMENT OF		SUPPORT		No.	De	611/27		
	SB 139-601 REV. / PART I COMP	PLIANCE TO BE CA	RRY OUT							
	REFERENCE: SB 139-601 REV.	/ DATED 27 DECEM	MBER 2021				MOO4 IN			
	REMARKS: (10. S	A115								
	work recorded above has been e and in that respect the aircraft					ivil Aviation Regula	ation for the time	being in		
☐ *The	e and in that respect the aircran work recorded above has been the time being in force and in the	n carried out in ac	cordance with	the require	ements of the	vice.				
	✓ WHERE APPLICABLE	ice respect tile dir	o.a.r. oquipine	2.11.10 001131	and made revenue to some					



Information:

Please send to the following	SERVIC	E BULLETIN COMP	Date: 06/01/2022						
LEONARDO S.p.A.					00/01/0002				
CUSTOMER SUPPORT & SERV	ICES - ITALY	Number:	1.1						
PRODUCT SUPPORT ENGINEERIN	IG & LICENSES DEPT.	SB 139 - 601 Revision:							
Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (Tel.: +39 0331 225036 Fax: +39 033									
Customer Name and Address			Telephon						
GALAXY AEROSPACE				7734 7226					
(GADING GROUP OF C Suite 11-14, Helicopter (Fax:						
GALAXY AEROSPACE	(M) SDN BHD			7734 7226					
Malaysia International Ad Sultan Abdul Aziz Shah	Airport, 47200 S	, ubang,		pliance Date:					
SELANGOR DARUL EH	ISAN			6/01/2022					
Helicopter Model	S/N		Total Number	Total Hours	T.S.O.				
AW139	31807		1	1254:20	~				
Remarks:					_1_				
CID SI	2115								
(10)	111/								
It									
	EROS								
1/ 60	1004 K								
V 🗞	ALANST								

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

PARTS REPORT



REASON FOR RAISING: SB 139-601 REV. / PART I COMPLIANCE TO BE CARRY OUT I.A.W SB 139-601 REV. / DATED 27 DECEMBER 2021 ATA 33 - INSPECTION AND REINFORCEMENT OF SEARCHLIGHT SUPPORT Serial Number CT. Graden Page 1. Lifed Item	NO: 9431-001
## 1 ENGINE POEK-RE2007 ## 1 ENGINE POEK-RE2007 ## 1 ENGINE POEK-RE2007 ## 2 ENGINE POEK-RE20	DESC: ATA 33 - INSPECTION A
REGISTRACILITY. WBKK ATE IN-REPREVAMENCE OUT REFER WORKPROCK AND IN INF / NO. SHEET CAAC REPREVAMENT OUT Relieved by sand date: CAAC REPREVAMENT OUT RELIEVED BY SAND OUT RELIEVED BY SAN	REF: 9M-PMA-9431
THE INFORMATION OF RAISING SET 139-601 REV. / PART I COMPILANCE TO BE CARRY OUT Relieved by and date: CAMP RIMENTAL AND CAMP REPORT OF SEARCHLIGHT SUPPORT THE INFORMATION OF SEARCHLIGHT SUPPORT Senal Number Off Off Off Off Off Off Off Off Off Of	REFER WORKPACK
ASON FOR RAISING: SB 139-601 REV. / PART I COMPILANCE TO BE CARRY OUT WS 8 139-601 REV. / DATE DZ DECEMBER 2021 ATA 33 - INSPECTION AND Khalis O501/2022 The Market Marke	1 OF 1
NAME FIRM SIGN & PROMAL The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regit force and in that respect the aircraft / equipment is considered fit for release to service.	ments/information:
Farked JOIN GAM The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the	Information Release Reference
*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation force and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	,
The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulatoric and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	
Farked JOIN GAM The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the	
Figure 2 (China Carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service.	
Farked JOIN GAM The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the	
Figure 2 (China Carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service. The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service.	
*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulatoric and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	
*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulatoric and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	
*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulatoric and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	
*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation force and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	
*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulators and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	DATE
force and in that respect the aircraft / equipment is considered fit for release to service. *The work recorded above has been carried out in accordance with the requirements of the	6/1/22
	ulation for the time being in
TICK ✓ WHERE APPLICABLE	