DELIVERY NOTE WP



DELIVER TO:

GALAXY AEROSPACE (M) SDN. BHD.

CAMO DEPARTMENT Lot 11, MRO Centre,

Malaysia International Aerospace Centre,

Sultan Abdul Aziz Shah Airport,

47200 Subang, Selangor

Malaysia.

Attn: Zaty Nadhira binti Mohamed Zuhari

DN NUMBER: GAM/DN/23/PMF-058

OUR REFERENCE: 9M-PMF-15135

WO REFERENCE: 2023-15135

DATE COMPLETION: 4 APRIL 2023

AJL NUMBER: 02247

			A/	DETAILS					
A/C TYPE	AW13	9	A/C REG	9M-	-PMF	A/C S/N		31913	
OWNER / OPERATOR			a visit in the second of the s		2:25	LANDINGS		1628	
ENGINE #1 S/N	N PCE-KB2	399	T.S.N	93:	2:25	T.S.O			
ENGINE #2 S/N	N PCE-KB2	395	T.S.N	933	2:25	T.S.O		14	
LIST OF TASK	PERFORMED	NUMB		*PR	NUMBE *ARC	R OF PAGES	*SBC	*OTH	
PHYSICAL INSPECTION FOR APPLICABILITY PART 1 EASB 139-754 EASB 139-754 PART 1 COMPLIANCE		001		1	- Ans	-	-	1	
		002	1	1		- 4	2	5	
THIS IS TO CERTIF	FY THAT TASKS LIST	ED ABOVE	HAS BEEN ACCOM	PLISHED AS	PER PO/WORK C	ORDER/SERVICE	ORDER NO. AS A	ABOVE.	
NAME	ME AMIRUL ASYRAF		SIGNATURI	= =	An DATE		25	25 MAY 2023	
		VERIF	FIED AND ACCEPT	ED BY		NIS BINTI RAH CAMO Plannei		22	
				DATE	Garaxy	Aerospace (M) (1040262-D)	San Bhd 267	105/23	

*WS - WORKSHEET

*S - SERVICEABLE LABEL

*PR - PART REPORT

*SBC - SERVICE BULLETIN COMPLIANCE

*ARC - AUTHORISED RELEASE CERTIFICATE *OTH - OTHERS

Page: 1 GAM/E-015



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia. Tel: +603 7734 7226 | Pax. +603 7734 7526 www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORK ORDER



To:	GALAXY AEROSPACE (M) SDN. BHD.		
Address:	Lot 11-14, MRO Centre, Malaysia	Work Order Number:	2023-15135
	International Aerospace Centre, SAAS Airport,		Control of the State of the
	Subang	Work Pack Reference:	9M-PMF-15135
	Malaysia	Date Issued:	01/04/2023
Attention:	Mr. Syafrul Yamani	Date Issued.	01/04/2023
	Engineering Manager	A/C Registration / SN:	9M-PMF/31913
	syafrul@galaxyaerospace.my	Sheet:	1 OF 1

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	PHYSICAL INSPECTION FOR APPLICABILITY PART I EASB 139-754	EASB 139-754 DATED 31 MARCH 2023	(PLEASE ADVISE)
2	EASB 139-754 PART I COMPLIANCE	EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023	D.T (PLEASE ADVISE)

Remark/Notes:

- State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
- 2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
- 3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
- 4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
- 5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
- Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
- 7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you. Best Regards.

Zaty Nadhira Mohamed Zuhari Continuing Airworthiness Management Manager Email: zaty@galaxyaerospace.my



POLICE

REGISTRATION: 9MPMF

CLIENT/OWNER: ROYAL MALAYSIA

AIRCRAFT TYPE: AW139

BASE/FACILITY: WHISAWEDG DATE IN: 4 4 23 OUT: 4 4 23

GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14. Helicopter Centre. Malaysia International Aerospace Centre.
Suitan Abdul Aziz Shah Airport. 47200 Subang. Selangor, Malaysia
Tel. +603 7734 7226 [Faxi +603 7734 7526]
www.galaxyaerospace.my | enquiry@galaxyaerospace.my

WORKPACK

	SERIAL NO.	HOURS	LDG	CYCLE
AIRCRAFT	31913	932:25		528
#1 ENGINE:	PCE-KB2399	932:25	-	-
#2 ENGINE:	PCE-KB2395	932:25	_	-
			NG / N1	NE / NO

WORKPACK NO: 9M-PMF-15135 WORK/INSP/DESC: EASB 139-754 AERONET JOB NO.: 2023-15135 AJL REF NO .: 02747

SHEET:

Other requirements/information:

NIL

Reason for raising:

INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42ND

CAMO; Hanis 01/04/2023

Raised by and date:

ISSUE DATE 2022-12-01 UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS. List of scheduled inspection and all work carried out under this workpack Master Signature Schedule DATE including individual reference INSPECTION COMPLETED WORKSHEET REF NAME SIGNATURE APP/STAMP NO. INSPECTION / WORK PHYSICAL INSPECTION FOR APPLICABILITY 15131-001 1 AMALLUDIN PART I EASB 139-754 M101 EASB 139-754 PART I COMPLIANCE 15131-002 2 8108 AMALLUPIN NAME PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND AMO /2016/01 SIGN & APPROVAL * OEM PUBLICATION/REVISION AS PER REASON FOR RAISING ABOVE *IF DIFFERENT FROM ABOVE. OEM PUBLICATION/REVISION. FIRM 4/4/23 DATE * TICK WHERE APPLICABLE SIGN & APPROVAL

PART M - CAMO ACCEPTANCE STATEMENT

AND UPDATED IN THE MAINTENANCE SOFTWARE.

NURUL HUSNA BINTI ZAINOLEABIDIN

THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION CAMO Planner Galaxy Aerospace (M) Sdn Bhd (1040262-D)



17/04/2023



GALANY AEROSPACE (M) SDN. BHD. [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre.
Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia.
Tel: +603 7734 7226 | Fax: +603 7734 7528.
www.galanyaerospace.my | enquiry@galaxyaerospace.my

Tools Report



Work Pack No: 9M-PMF-15135 31913 Aircraft Serial No: INSPECTION TO BE Aircraft Type: AW139 DESC: Aircraft Reg: 9M-PMF PAGE: OF

Worksheet Ref No. / Description Part No Serial Number Calibration Due Date Item No.





Sulle 11-14 Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Subang, Selangia, Malaysia Tel: +603-7734-7226 | Fax: +603-7734-7526

WORKSHEET

CLIENT/OWNER: ROYAL MALAYSIA WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 15135-001 POLICE WORK/INSP/DESC: 31913 REFER WORKPACK PHYSICAL INSPECTION AIRCRAFT AIRCRAFT TYPE: AW139 WORKPACK REE-REFER WORKPACK 9M-PMF-15135 PCE-KB2399 #1 ENGINE: REGISTRATION: 9M-PME AJL REF NO .: BASE/FACILITY: WANGE OF BE REFER WORKPACK #2 ENGINE: PCE-KB2395 REFER WORKPACK SHEET: DATE IN: REFER 1 OF 3 NG/N1 NF/N2 Reason for raising: Raised by and date: Other requirements/information: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-CAMO; Hanis MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42ND ISSUE DATE 2022-12-01 01/04/2023 UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS. Technician * Eng. CRS Description Date Item PHYSICAL INSPECTION FOR APPLICABILITY PART I EASB 139-754 PERFORM PHYSICAL CHECK FOR PART NUMBER AND SERIAL NUMBER OF MAIN ROTOR PITCH LINK ROD END ASSY TO COMPLY EASB 139-754. NOTE: PLEASE PROVIDE PICTURE WITH CLEAR PART NUMBER AND SERIAL NUMBER OF THE COMPONENT. REFERENCE: EASB 139-754 PART I PITCH LINK (ORANGE) PART NUMBER: 3G6230A01033 SERIAL NUMBER: AWS 63954 UPPER ROD END ASSY PART NUMBER: 366230 A01133 SERIAL NUMBER: AWS 64069 APPLICABILITY TO EASB 139-754: NA REMARKS: NIA DIFFERENT SERIAL NO 2 PHYSICAL INSPECTION FOR APPLICABILITY PART I EASB 139-754 PERFORM PHYSICAL CHECK FOR PART NUMBER AND SERIAL NUMBER OF MAIN ROTOR PITCH LINK ROD END ASSY TO COMPLY EASB 139-754. NOTE: PLEASE PROVIDE PICTURE WITH CLEAR PART NUMBER AND SERIAL NUMBER OF THE COMPONENT. REFERENCE: EASB 139-754 PART I PITCH LINK (RED) PART NUMBER: 3G6230A01033 SERIAL NUMBER: AW563952 UPPER ROD END ASSY PART NUMBER: 36-6230A 01133 SERIAL NUMBER: AW564065 APPLICABILITY TO EASB 139-754: N/A REMARKS: N/A DIFFERENT SERIAL NO *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. Ams / 22/6 / t2 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service.



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D]

Suite 11-14. Helicopter Centre, Malaysia International Aerospace Suitan Abdul Aziz Shah Airport, 47200 Subang, Selangor, Malaysia Tel: |803 7734 7228 | Fax: +603 7734 7626



CLIENT/OWNER: ROYAL MALAYSIA WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 15135-001 POLICE WORK/INSP/DESC: PHYSICAL INSPECTION 31913 REFER WORKPACK (M101) % AIRCRAFT AIRCRAFT TYPE: AW139 WORKPACK REF: REGISTRATION: 9M-PMF 2mo 4/4/23 9M-PMF-15135 PCF-KB2399 REFER WORKPACK #1 ENGINE: AJL REF NO .: REFER WORKPACK BASE/FACILITY: WMSA WBGG REFER WORKPACK #2 ENGINE: PCF-KB2395 OUT: REFER SHEET: 2 OF 3 DATE IN: REFER WORKPACK NG/NT NF/N2 Reason for raising: Raised by and date: Other requirements/information: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-CAMO; Hanis MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42ND ISSUE DATE 2022-12-01 01/04/2023 UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS. Description Technician * Eng. CRS Item Date 3 PHYSICAL INSPECTION FOR APPLICABILITY PART I EASB 139-754 PERFORM PHYSICAL CHECK FOR PART NUMBER AND SERIAL NUMBER OF MAIN ROTOR PITCH LINK ROD END ASSY TO COMPLY EASB 139-754. NOTE: PLEASE PROVIDE PICTURE WITH CLEAR PART NUMBER AND SERIAL NUMBER OF THE COMPONENT. REFERENCE: EASB 139-754 PART I PITCH LINK (WHITE) PART NUMBER: 3G6230A01033 SERIAL NUMBER: AWS 63 953 UPPER ROD END ASSY PART NUMBER: 36-6230A01133 SERIAL NUMBER: AW564066 APPLICABILITY TO EASB 139-754: N/P REMARKS: N/A DIFFERENT SERIAL NO PHYSICAL INSPECTION FOR APPLICABILITY PART I EASB 139-754 4 PERFORM PHYSICAL CHECK FOR PART NUMBER AND SERIAL NUMBER OF MAIN ROTOR PITCH LINK ROD END ASSY TO COMPLY EASB 139-754. NOTE: PLEASE PROVIDE PICTURE WITH CLEAR PART NUMBER AND SERIAL NUMBER OF THE COMPONENT. REFERENCE: EASB 139-754 PART I PITCH LINK (BLUE) PART NUMBER: 3G6230A01033 SERIAL NUMBER: AW563950 UPPER ROD END ASSY PART NUMBER: 36-6230A01133 SERIAL NUMBER: AWS64068 APPLICABILITY TO EASB 139-754: N/A REMARKS: N/A DIFFERENT SERIPLNO

Certifies that the work specified above, except as otherwise specified, was carried out in accordance to the aircraft / aircraft component is considered ready for release to service. AMV 12 e 16 02 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance to and in respect to that work the aircraft / aircraft component is considered ready for release to service.	with
TICK ✓ WHERE APPLICABLE	



WORKSHEET

GALAXY AEROSPACE (M) SDN. BHD. [1040252-D].
Suite 11-14, Helicopter Centre, Malaysia International Aerospaca C
Suitan Abdul Aziz Shah Airpori, 47200 Subang, Selangor, Malaysia
Tel +803.7734.7256 | Fazir-4603.7734.7256 www.gataxyaerospace.my | anquiry@galaxyaerospace.my CLIENT/OWNER: ROYAL MALAYSIA WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 15135-001 POLICE WORK/INSP/DESC: PHYSICAL INSPECTION AIRCRAFT 31913 REFER WORKPACK AIRCRAFT TYPE: AW139 WORKPACK REF: 9M-PMF-15135 PCE-KB2399 #1 ENGINE: REFER WORKPACK REGISTRATION: 9M-PMF AJL REF NO .: 4/4/23#2 ENGINE: BASE/FACILITY: WMSA WIGGG PCE-KB2395 REFER WORKPACK REFER WORKPACK SHEET: 3 OF 3 OUT: REFER WORKPACK DATE IN: REFER WORKPACK NF/N2 NG/N1 Reason for raising: Raised by and date: Other requirements/information: INSPECTION TO BE CARRIED OUT LAW EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-CAMO; Hanis NIL MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42ND ISSUE DATE 2022-12-01 01/04/2023 UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS. Technician * Eng. CRS Item Date 5 PHYSICAL INSPECTION FOR APPLICABILITY PART I EASB 139-754 PERFORM PHYSICAL CHECK FOR PART NUMBER AND SERIAL NUMBER OF MAIN ROTOR PITCH LINK ROD END ASSY TO COMPLY EASB 139-754. NOTE: PLEASE PROVIDE PICTURE WITH CLEAR PART NUMBER AND SERIAL NUMBER OF THE COMPONENT. REFERENCE: EASB 139-754 PART I 4/4/23 PITCH LINK (BLACK) PART NUMBER: 3G6230A01033 SERIAL NUMBER: AWS63951 UPPER ROD END ASSY PART NUMBER: 36-6230A61133 SERIAL NUMBER: AUS64067 APPLICABILITY TO EASB 139-754: N/A REMARKS: N/A DIFFERENT SERIAL NO

									-						
the	aircraft /	aircraft	componer	nt is con	sidered re	eady for rel	ease to servi	ce. Amo	1 5016/1	2	Ialaysia Requir	ements and	in respec	t to that wo	rk
							e specified, w it is consider								
TIC	K √ WHER	E APPLIC	ABLE												
					-1	-			1						-
			-/			N.							GAM	C-005 Rev	3 (06/22)



GALAXY AEROSPACE (M) SDN. BHD, [1040262-D]
Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Arroott 47200 Subang, Selangor, Malaysia. Tet. +603 7734 7526 Faxx +603 7734 7526 www.gataxyaerospace.my | enquiry@gataxyaerospace.my

PARTS REPORT



	OUNTED DOUG	MALAVOIA		OCDIAL MO	LISTIN.		DC/CV	OLE	1	DIADUET 115	- V.S.	
CLIENT/OWNER: ROYAL MALAYSIA POLICE AIRCRAFT TYPE: AW139			AIDODA	SERIAL NO		HOURS LDG/CYCLE REFER WORKPACK					15135-001	
AIRCRAF	T TYPE; AW139	()	AIRCRAFT	PCE-KB239	-	WORKPA					IYSICAL INSPECTION	
REGISTE		4 41412									I-PMF-15135	
BASE/FA	CILITY: MISA	JT: REFER WORKPACK	#2 ENGINE:	PCE-KB239	HEFER	WORKPA	1	NESSE	- 200		FER WORKPACK OF 1	
DALE IN:	HEFER WORKS OF	JI: HEFER WORKPACK				NG.	/ N1	NF / N2	SH	1	UF 1	
Reason for raising: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2023-0071-E PAI MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42NI UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS.		3, IETP - 42ND ISS				CAMO; 01/04/2		Other requirements/information:				
Item	Part No	Des	cription		Serial Nu	umber On	Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX		
	-					011					/	
											/	
							-					
										/		
							+					
									/			
							+					
							/					
						/			100			
					-	_	1					
			_									
			_/									
		,										
		/										
	/											
	_/						1					
NAME		1		FIRM	1			SIGN &	APPROVAL		DATE	
	SAN PERSON		0.5 (11.5					1				
AW	ALLUDIN 6	3. ABOUL R	LAHIM	0	AM			(J/m	M101	100	4/4/23	
that w	vork the aircraft /	k specified above, aircraft component k specified above, work the aircraft /	nt is considere except as oth	ed ready for re erwise specif	elease to se fied, was ca	ervice. A arried out	Mt ≀ in acco	il(@1 ordance w		Malaysia Requireme	nts and in respect to	
	WHERE APPLICABL											
	WILLEATELOAD			10.0	10075						0.00	
41-	-						-	3				



GALAXY AEROSPACE (M) SDN, BHD. [1040262-D] WORKSHEET Sulte 11-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aziz Shah Airport, 47200 Sultang, Selangor, Malaysia, Teh: =863.7734.7226 | Fax: -603.7734.7526 Www.gatangaerospace my | enquiry@galangaerospace my CLIENT/OWNER: ROYAL MALAYSIA WORKSHEET NO: SERIAL NO. HOURS LDG/CYCLE 15135-002 POLICE WORK/INSP/DESC: EASB 139-754 PART I 31913 REFER WORKPACK AIRCRAFT AIRCRAFT TYPE: AW139 REGISTRATION: 9M-PME Amol 4/4/23 WORKPACK REF: 9M-PMF-15135 #1 ENGINE: REFER WORKPACK PCF-KB2399 AJL REF NO.: BASE/FACILITY: WASA WOLL REFER WORKPACK REFER WORKPACK #2 ENGINE: PCE-KB2395 OUT REFER SHEET: 1 OF 1 DATE IN: REFER WORKPACK NG/N1 NF/N2 Reason for raising: Raised by and date: Other requirements/information: INSPECTION TO BE CARRIED OUT LAW EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-CAMO; Hanis NIL MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42ND ISSUE DATE 2022-12-01 01/04/2023 UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS. Description Technician * Eng. CRS Item Date EASB 139-754 PART I COMPLIANCE 1 EASA AD 2023-0071 PARA (2), EASB 139-754 PART I TO CHECK THE PRESENCE OF GAP BETWEEN MR PITCH LINK UPPER ROD END ASSY BEARING AND PITCH CONTROL LEVER ASSY. IN CASE GAP IS DETECTED, THE AFFECTED UPPER ROD END ASSY SHALL BE REPLACED WITH A SERVICEABLE ONE. NOTE: 1) IF THE GAP IS PRESENT ON BOTH SIDES OR ONE SIDE, REPLACE THE UPPER ROD END ASSY P/N 3G6230A01133 WITH A SERVICEABLE ONE. COMPILE THE INSPECTION REPORT IN FIGURE 6 AND CONTACT LHD BEFORE THE RETURN TO FLIGHT. SEND THE AFFECTED UPPER ROD END ASSY TO 2) IF THERE IS NO GAP, PROCEED TO STEP 3 AND APPLY PART III OF THIS SERVICE BULLETIN IN ACCORDANCE WITH COMPLIANCE TIME REPORTED IN PARAGRAPH 1.B OF THIS SERVICE BULLETIN 3) COMPLIANCE WITH THE INSTRUCTIONS OF THIS SERVICE BULLETIN NO LATER THAN THE APPLICABLE DATE IN THE COMPLIANCE SECTION WILL BE ELIGIBLE TO RECEIVE REQUIRED MATERIALS ON FREE OF CHARGE BASIS, EXCEPT FOR CONSUMABLE MATERIALS AND SPECIAL TOOLS. REFERENCE: EASA AD 2023-0071 PARA (2), EASB 139-754 PART I UPPER ROD END ASSY REMARK ORANGE NIA SERIAL NUMBER: AWS 64069 NIA SERIAL NUMBER: AWS64065 WHITE NA SERIAL NUMBER: AWS 64 066 NA SERIAL NUMBER: AWS 64068 BLACK NIA AWS64067 SERIAL NUMBER: REMARKS: N/A DUE TO S/N NOT LISTED IN ANNEX A

EASB 139-754

Ø	*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work
	the aircraft / aircraft component is considered ready for release to service. Amo 2616/12
	*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with
_	and in respect to that work the aircraft / aircraft component is considered ready for release to service.

1		*			
ı	TICK V	WHERE	APPL	CARL	p



GALAXY AEROSPACE (M) SDN. BHD. [1040262-D] Subst 1-14, Helicopter Centre, Malaysia International Aerospace C Sultan Abdul Aze Shah Arnord, 47200 Subang, Setangdi, Malaysia, Tel: +803.7734.7226 [Fax: +803.7734.7526] www.galakyderospace.my|enquiry@galaxyderospace.my

PARTS REPORT

CLIENT/OWNER: ROYAL MALAYSIA SERIAL NO. HOURS LDG/CYCLE WORKSHEET NO: 15135-002 POLICE 31913 REFER WORKPACK WORK/INSP/DESC: EASB 139-754 PART I AIRCRAFT AIRCRAFT TYPE: AW139 PCE-KB2399 REFER WORKPACK WORKPACK REF: 9M-PMF-15135 #1 ENGINE: REGISTRATION: 9M-PMF AJL REF NO .: REFER WORKPACK BASE/FACILITY: WASA 144 BGG PCE-KB2395 REFER WORKPACK #2 ENGINE: DATE IN: REFER WORKPACK OUT: REFER WORKPACK SHEET: OF 1 NG/N1 NF/N2 Raised by and date: Other requirements/information: Reason for raising: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2023-0071-E PARA (2) NEW ISSUE DATED 31-CAMO: Hanis NII MAR-2023, EASB 139-754 PART 1 DATED 31-MAR-2023, IETP - 42ND ISSUE DATE 2022-12-01 01/04/2023 UPDATED: 2023-02-28 OR LATER APPROVED REVISIONS. Serial Number Lifed Item Information Part No. Description Qty Item Release Reference Position Reason TSN/TSO/DUE/TIMEX Off NAME FIRM SIGN & APPROVAL DATE 4/4/23 AMALLUDIN F. ABDUL RAHIM GAM Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service. Amv | 1/1/1/12 *Certifies that the work specified above, except as otherwise specified, was carried out in accordance with and in respect to that work the aircraft / aircraft component is considered ready for release to service. ☐ TICK WHERE APPLICABLE



Date			04/04/23		
Upper Rod End / P/N 3G6230A01		AWS64067,	S/N AWS64065, AWS64068	FH 932: 25	
Installed o	n Helic	opter	S	tock item	
S/N		FH	Installed on Pitch Link Ass P/N 3G6230A01033 S/N (if appli		
31913		932;25			
mension "X" meas	uremer	nt N/A			





Please send to the following address: Date: SERVICE BULLETIN COMPLIANCE FORM LEONARDO S.p.A. **CUSTOMER SUPPORT & SERVICES - ITALY** Number: EASB 139-754 PART PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 Revision: 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988 Customer Name and Address: Telephone: GALAXY AEROSPACE (M) SDN BHD 603-7734 7226 Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, 603-7734 7226 Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN B.T. Compliance Date: 4/4/23 S/N Total Number Total Hours T.S.O. Helicopter Model 932:25 AW139 31913 Remarks: Clo SATIS

Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.







