

A/C TYPE EC155B
 A/C REGN 9M-SAS S/N 6583
 TYPE OF CHECK _____



EUROCOPTER SOUTH EAST ASIA PTE LTD
 48 Loyang Way Singapore 508740

NO: **17012** FORM NO: M/003

JOB NO. _____

PAGE _____ OF _____

DEFECT AND RECTIFICATION WORKSHEET/CERTIFICATE OF RELEASE TO SERVICE

ITEM NO.	REPORTED BY DATE	DEFECT/WORK REQUIRED	ACTION TAKEN	COMPONENT CHANGES		G.I.N NO. OR O/HAUL REPORT NO.	MAN HOURS	MECH	LIC/ APP NO. DATE
				S/N OFF	S/N ON				
1.	STEW LAY 05/7/04	COMPLY WITH ASB 32A 004 R1 - WHEEL BRAKE HYDRAULIC HOSE BURSTING	N/A DUE EMERGENCY FLOATA- TION GEAR NOT INSTALLED						 A1719 5/7/04
2.	STEW LAY 05/7/04	COMPLY WITH ASB 52A 016 - CHECKING THE CONDITION OF SLIDING DOOR FWD FITTINGS AND THE POSITION OF SLIDING DOOR UPPER ROLLER AND FWD CENTERING PINS	N/A DUE SLIDING DOOR NOT FITTED						 A1719 5/7/04

THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING REQUIREMENTS FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT/ EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE:

- SINGAPORE AIR NAVIGATION ORDER
- MALAYSIAN CIVIL AVIATION REGULATIONS
- JAR 145 NO : F-04E
- MANUFACTURER'S PUBLICATIONS