

A/C TYPE EC155B
 A/C REGN 9M-SAS S/N 6583
 TYPE OF CHECK _____



EUROCOPTER SOUTH EAST ASIA PTE LTD
 48 Loyang Way Singapore 508740

NO: **17245** FORM NO: M/003
(CF 70 (RS #17521))
 JOB NO. _____
 PAGE _____ OF _____

DEFECT AND RECTIFICATION WORKSHEET/CERTIFICATE OF RELEASE TO SERVICE

ITEM NO.	REPORTED BY DATE	DEFECT/WORK REQUIRED	ACTION TAKEN	COMPONENT CHANGES		G.I.N.NO. OR O/HAUL REPORT NO.	MAN HOURS	MECH	LIC/ APP NO. DATE
				S/N OFF	S/N ON				
1.	STEWLAY 20/9/04	COMPLY WITH ASB 52A017 - REINFORCING THE SUPPORT OF FWD CENTERING PINS AND REPLACEMENTS ON SLIDING DOORS AND SLIDING DOOR JAMBES [REF. ADF-2004-157 (A)]	N/A DUE SLIDING DOOR NOT INSTALLED <i>By</i>				-		<i>By</i> A1719 20/9/04
2.	STEWLAY 20/9/04	COMPLY WITH ASB 53A 008 - IMPROVEMENT OF SLIDING DOOR FITTINGS AND RAILS [REF. ADF-2004-156 (A)]	N/A DUE SLIDING DOOR NOT INSTALLED <i>By</i>				-		<i>By</i> A1719 20/9/04
3.	STEWLAY 20/9/04	COMPLY WITH SB 32-001 - CORROSION CHECK OF BALL END-FITTING OF MLG & NLG BRACE STRUT ACTUATOR	SB 32-001 SUPERCEDED BY SB 32-005 <i>By</i>				-		<i>By</i> A1719 20/9/04

THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING REQUIREMENTS FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT/ EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE:

- SINGAPORE AIR NAVIGATION ORDER
- MALAYSIAN CIVIL AVIATION REGULATIONS
- JAR 145 NO : F-04E
- MANUFACTURER'S PUBLICATIONS

EUROCOPTER
DIRECTION TECHNIQUE SUPPORT
13725 MARGNANE CEDEX FRANCE

VERSION (S): B

SERVICE BULLETIN

No. 32-001

SUBJECT: LANDING GEAR Corrosion Check of the Ball End-Fitting for Main Landing Gear and Nose Landing Gear Brace Strut Assembly

LIST OF REVISED REVISIONS applicable	REVISION No. 0 APPROVED Date: February 22, 2001
--	---

**SUPERSEDED BY
SB No. 32-005**