

A/C TYPE EC155B
 A/C REGN 9M-SAS S/N 6583
 TYPE OF CHECK _____



EUROCOPTER SOUTH EAST ASIA PTE LTD
 48 Loyang Way Singapore 508740

NO: **16797** FORM NO: M/003
 JOB NO. _____
 PAGE _____ OF _____

DEFECT AND RECTIFICATION WORKSHEET/CERTIFICATE OF RELEASE TO SERVICE

ITEM NO.	REPORTED BY DATE	DEFECT/WORK REQUIRED	ACTION TAKEN	COMPONENT CHANGES		G.I.N.NO. OR O/HAUL REPORT NO.	MAN HOURS	MECH	LIC/ APP NO. DATE
				S/N OFF	S/N ON				
1.	29/4/04	STEWLAY (COMPLY WITH AD F-2004-04) (AB) - TA/RA VSI - T/CAS INDICATOR THALES AVIONICS	N/A DUE NOT FITTED						
	[19/4/04	REF. AD F-2004-053 (AB)]							
2.	11/5/04	STEWLAY COMPLY WITH ALT TLX 04A 007 (REF. TFS # 00000181) - NEVER EXCEED SPEED (VNE)	N/A DUE SLIDING DOOR NOT INSTALLED						
	[17/5/04	REF. TFS # 00000183]							
	[20/5/04	REF. AD F-2004-060(A)]							

THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING REQUIREMENTS FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT/ EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE:

- SINGAPORE AIR NAVIGATION ORDER
- MALAYSIAN CIVIL AVIATION REGULATIONS
- JAR 145 NO : F-04E
- MANUFACTURER'S PUBLICATIONS