

A/C TYPE EC155B
 A/C REGN 9M-SAS S/N 6583
 TYPE OF CHECK _____



EUROCOPTER SOUTH EAST ASIA PTE LTD
 48 Loyang Way Singapore 508740

NO: **17014** FORM NO: M/003
 JOB NO. _____
 PAGE _____ OF _____

DEFECT AND RECTIFICATION WORKSHEET/CERTIFICATE OF RELEASE TO SERVICE

ITEM NO.	REPORTED BY DATE	DEFECT/WORK REQUIRED	ACTION TAKEN	COMPONENT CHANGES		G.I.N.NO. OR O/H/AUL REPORT NO.	MAN HOURS	MECH	LIC/ APP NO. DATE
				S/N OFF	S/N ON				
1.	21/7/04	STEW LAY (COMPLY WITH AD F-2004-099 (A) - MLG - WHEEL BRAKE HOSE)	N/A DUE FLOATS NOT FITTED \$ Fuy.				-		 21/7/04
2.	21/7/04	STEW LAY (COMPLY WITH AD F-2004-106 (A) - MRB/TIP CAP JUNCTION)	ENTERED IN ERROR [REFER TO AWM (REF. AWM/024/01 #51)] \$ Fuy.						 21/7/04
3.	21/7/04	STEW LAY (COMPLY WITH AD F-2004-107 (A) - CABIN SLIDING DOORS)	N/A DUE SLIDING DOOR NOT FITTED \$ Fuy.				-		 21/7/04

THE WORK RECORDED ABOVE HAS BEEN CARRIED OUT IN ACCORDANCE WITH THE FOLLOWING REQUIREMENTS FOR THE TIME BEING IN FORCE AND IN THAT RESPECT THE AIRCRAFT/ EQUIPMENT IS CONSIDERED FIT FOR RELEASE TO SERVICE:

- SINGAPORE AIR NAVIGATION ORDER
- MALAYSIAN CIVIL AVIATION REGULATIONS
- JAR 145 NO : F-04E
- MANUFACTURER'S PUBLICATIONS