

DELIVERY NOTE WP

DELIVER TO :

GALAXY AEROSPACE (M) SDN. BHD.
CAMO DEPARTMENT
Lot 11, MRO Centre,
Malaysia International Aerospace Centre,
Sultan Abdul Aziz Shah Airport,
47200 Subang, Selangor
Malaysia.
Attn : Zaty Nadhira binti Mohamed Zuhari

DN NUMBER : GAM/DN/SAAS-22-038
OUR REFERENCE : 9M-SAAS-9194
WO REFERENCE : 2021-9194
DATE COMPLETION: 22 MARCH 2022
AJL NUMBER : 04767

A/C DETAILS							
A/C TYPE	AW139	A/C REG	9M-SAAS	A/C S/N	31903		
OWNER / OPERATOR	GADING AIR SERVICES SDN BHD	A/C TOTAL TIME	111:26	LANDINGS	199		
ENGINE #1 S/N	PCE-KB2390	T.S.N	111:26	T.S.O	-		
ENGINE #2 S/N	PCE-KB2380	T.S.N	111:26	T.S.O	-		
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES					
		*WS	*PR	*ARC	*S	*SBC	*OTH
ATA 62 – MAIN ROTOR BLADE LIGHTNING STRIP CORROSION PROTECTION IMPROVEMENT	001	1	1	-	-	-	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. AS ABOVE.							
NAME	NORZIAH SULAIMAN	SIGNATURE	<i>ngw</i>	DATE	25 MARCH 2022		
VERIFIED AND ACCEPTED BY			MUHAMMAD IHSAN MASRI CAMO Planner Galaxy Aerospace (M) Sdn. Bhd. (1040262-D)				
DATE			<i>25 / 03 / 2022</i>				

*WS – WORKSHEET

*PR – PART REPORT

*ARC – AUTHORISED RELEASE CERTIFICATE

*S – SERVICEABLE LABEL

*SBC – SERVICE BULLETIN COMPLIANCE

*OTH – OTHERS

WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p>Address: Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p>Attention: Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my</p>	<p>Work Order Number: 2021-9194</p> <p>Work Pack Reference: 9M-SAAS-9194</p> <p>Date Issued: 20/12/2021</p> <p>A/C Registration / SN: 9M-SAAS/31903</p> <p>Sheet: 1 of 1</p>
--	---

Description:

Item	Description/Task/Inspection	Reference	Man Hours
1	ATA 62 - MAIN ROTOR BLADE LIGHTNING STRIP CORROSION PROTECTION IMPROVEMENT		<u>2</u> (PLEASE ADVISE)

Remark/Notes:

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.
 Best Regards,

Zaty Nadhira Mohamed Zuhari
 Continuing Airworthiness Management Manager
 Email: zaty@galaxyaerospace.my



CLIENT/OWNER: GADING AIR SDN. BHD. AIRCRAFT TYPE: AW139 REGISTRATION: 9M-SAAS BASE/FACILITY: WMSA DATE IN: 21.03.22 OUT: 22.03.22		SERIAL NO.	HOURS	LDG/CYCLE		WORKPACK NO: 9M-SAAS-9194
	AIRCRAFT	31903	111:26	199		WORK/INSP/DESC: SB NO. 139-617, NEW
	#1 ENGINE:	PCE-KB2390	111:26			AERONET JOB NO.: 2021-9194
	#2 ENGINE:	PCE-KB2380	111:26			AJL REF NO.: 04767
				NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: SB NO. 139-617, NEW ISSUE COMPLIANCE TO BE CARRIED OUT	Raised by and date: Muhammad Ihsan Masri 20/12/2021	Other requirements/information: NIL
---	---	--

List of scheduled inspection and all work carried out under this workpack including individual reference.	Master Signature Schedule
---	---------------------------

NO.	INSPECTION / WORK	WORKSHEET REF	NAME	TECH/INITIAL	SIGNATURE	APP/STAMP
1	ATA 62 - MAIN ROTOR BLADE LIGHTNING STRIP ...	9194-001	MUHAMMAD IHSAN MASRI	-	[Signature]	[Stamp]

PART 145 - AMO RELEASE STATEMENT THIS IS TO CERTIFY THAT ALL WORK LISTED ABOVE HAS BEEN INSPECTED AND ACCOMPLISHED IN ACCORDANCE WITH CONTRACTED AMO EXPOSITION AND PROCEDURE LATEST REVISION, AND OEM PUBLICATION/ REVISION: IETP 40 ISSUE	NAME	FIRM	SIGN & APPROVAL	DATE
	MUHAMMAD IHSAN MASRI	GAM	[Signature]	22.03.22

PART M - CAMO ACCEPTANCE STATEMENT THIS IS TO CERTIFY THAT THE ABOVE MENTIONED WORK PACKAGE HAS BEEN REVIEWED, CHECKED FOR COMPLETION AND UPDATED IN THE MAINTENANCE SOFTWARE. ALL RELEVANT AIRCRAFT/ENGINE/ MODIFICATION LOGBOOK HAS BEEN UPDATED.	NAME	FIRM	SIGN & APPROVAL	DATE
	MUHAMMAD IHSAN MASRI CAMO Planner Galaxy Aerospace (M) Sdn. Bhd. (1040262-D)	GAM	[Signature]	28/03/2022



CLIENT/OWNER: GADING AIR SDN. BHD. AIRCRAFT TYPE: AW139 REGISTRATION: 9M-SAAS BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO: 9194-001
	AIRCRAFT	31903	REFER WORKPACK		WORK/INSP/DESC: ATA 62 - MAIN ROTOR
	#1 ENGINE:	PCE-KB2390	REFER WORKPACK		WORKPACK REF: 9M-SAAS-9194
	#2 ENGINE:	PCE-KB2380	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1
Reason for raising: SB NO. 139-617, NEW ISSUE COMPLIANCE TO BE CARRIED OUT ATA 62 - MAIN ROTOR BLADE LIGHTNING STRIP CORROSION PROTECTION IMPROVEMENT			Raised by and date: Muhammad Ihsan Masri 20/12/2021		Other requirements/information: NIL

Item	Description	Technician	* Eng. CRS	Date
1	PERFORM MAIN ROTOR BLADES LIGHTNING STRIP CORROSION PROTECTION INSPECTION REF: SB NO. 139-617, NEW ISSUE NOTE: CAMO TO REMARKS IMPLEMENTATION OF THIS SB INTO LOGCARDS REMARKS: TASK CLOUT FOUND SATIS	<i>[Signature]</i>	<i>[Signature]</i> 	22.03.22

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK WHERE APPLICABLE



FARTS LABELED & RETURNED	LD RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK	ADDITIONAL WORK SHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	LD STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	REM/COMP LOG CARD	MOD RECORD BOOK
--------------------------	-----------	-----------------	------------	-------------	------------	-----------------------	------------------	-------------------	--------------	---------------	-----------	-------------------	-----------------	--------------------	----------	-------------------	-----------------



CLIENT/OWNER: GADING AIR SDN. BHD. AIRCRAFT TYPE: AW139 REGISTRATION: 9M-SAAS BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO: 9194-001	
	AIRCRAFT	31903	REFER WORKPACK	WORK/INSP/DESC: ATA 62 - MAIN ROTOR	
	#1 ENGINE:	PCE-KB2390	REFER WORKPACK	WORKPACK REF: 9M-SAAS-9194	
	#2 ENGINE:	PCE-KB2380	REFER WORKPACK	AJL REF NO.: REFER WORKPACK	
			NG / N1	NF / N2	SHEET: 1 OF 1

REASON FOR RAISING: SB NO. 139-617, NEW ISSUE COMPLIANCE TO BE CARRIED OUT ATA 62 - MAIN ROTOR BLADE LIGHTNING STRIP CORROSION PROTECTION IMPROVEMENT	Raised by and date: Muhammad Ihsan Masri 20/12/2021	Other requirements/information: NIL
---	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
<i>(The entire table body is crossed out with a diagonal line)</i>									


NAME	FIRM	SIGN & APPROVAL	DATE
MUGODIM	GAM	 	22.03.22

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK WHERE APPLICABLE

PARTS LABELED & RETURNED	D/D RAISED	DUPLICATE INSP.	GROUND RUN	FLIGHT TEST	TORQUE CHK	ADDITIONAL WORKSHEET	MONITORED DEFECT	PLANNING FORECAST	DIARY UPDATE	STATUS UPDATE	D/D STATUS	AIRCRAFT LOG BOOK	ENGINE LOG BOOK	PROPELLER LOG BOOK	LOG CARD	OEM/COMP LOG CARD	MOD RECORD BOOK
--------------------------	------------	-----------------	------------	-------------	------------	----------------------	------------------	-------------------	--------------	---------------	------------	-------------------	-----------------	--------------------	----------	-------------------	-----------------



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 4

ATA Chapter

62

AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52)		3G6210A00131		ASSY S/N (53)		AW5249	
AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS				OPTIONAL BULLETINS			
AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)		OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)		ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	
		ASSY TOTAL LIFTS/CYCLES (57)				ASSY TOTAL LIFTS/CYCLES (57)	
				SB 139-617		111:26	
				NEW ISSUE	22.3.2022	199	GAM



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 1

ATA Chapter

62

DESCRIPTION (1) MAIN ROTOR BLADE	P/N (2) 3G6210A00131	S/N (3) AW5249	MANUFACTURER NAME (4) Leonardo S.p.A.	ASSEMBLY DATE (5) 02/2020	RETIREMENT LIFE / TIME LIMITS (6) 20000 FH
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11) 50200 Land.
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL							
DATE (12)	R. MARKS (13)	A/C		ASSY		ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (10)	A/C		ASSY		REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
		TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)	TOTAL FLIGHT HOURS (20)			ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
		TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)	TOTAL LANDINGS (20)			ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
03/2020	31903	00:00	00:00	NEW	Leonardo Helicopters 								

DATE (46)		TOTAL HOURS (47)	TOTAL LANDINGS (47)	TOTAL LIFTS/CYCLES (47)	TASKS (48)		ACTIVITIES (49)		ORGANIZATION (50)	STAMP AND SIGNATURE (51)
22.3.22		111:26	199		50 139-617, NEW ISSUE ATA 62 - MAIN ROTOR BLADE LIGHTNING CORROSION PROTECTION IMPROVEMENT		CARRIED OUT AS PER 50-139-617 REFER WORKPACK 9M-SAS-9194		G-AM	

ASSY P/N (44) 3G6210A00131 ASSY S/N (45) AW5249

ASSEMBLY ACTIVITY HISTORY



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter 62
Section 3

DESCRIPTION (28)	P/N (29)	S/N (30)	MANUFACTURING DATE (31)			RETIRESMENT LIFE / DATE (32)			ASSY			
			TOTAL HOURS (32)	TOTAL LANDINGS (33)	TOTAL LIFTS/CYCLES (34)	TOTAL HOURS (35)	TOTAL LANDINGS (36)	TOTAL LIFTS/CYCLES (37)	DATE (38)	STAMP AND SIGNATURE (37)	TOTAL HOURS (38)	TOTAL LANDINGS (39)
COMPONENT DATA												
INSTALLATION												
REMOVAL												

ASSY P/N (26) 3G6210A00131 ASSY S/N (27) AW5249

COMPONENTS INSTALLED ON ASSY



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter 62
Section 2

AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52) 3G6210A00131			ASSY S/N (53) AW5244						
AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS				OPTIONAL BULLETINS					
AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)			ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)		
		ASSY TOTAL LIFTS/CYCLES (57)							
					<i>SB 139-617</i>		<i>III: 26</i>	<i>GAM</i>	
					<i>NEW ISSUE</i>	<i>22-3-2022</i>	<i>199</i>		

DESCRIPTION (1) MAIN ROTOR BLADE	P/N (2) 3G6210A00131	S/N (3) AW5244	MANUFACTURER NAME (4) Leonardo S.p.A.	ASSEMBLY DATE (5) 02/2020	RETIREMENT LIFE / TIME LIMITS (6) 20000 FH
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11) 50200 Land.
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL							
DATE (12)	R. MARKS (13)	A/C		ASSY		ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C		ASSY		REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
		TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)	TOTAL FLIGHT HOURS (20)			ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
		TOTAL LANDINGS (15)	TOTAL LANDINGS (18)	LANDS SINCE OH (17)	TOTAL LANDINGS (20)			ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
	S/N (14)	TOTAL LIFTS/CYCLES (15)	TOTAL LIFTS/CYCLES (18)	LIFTS/CYCLES SINCE OH (17)		TOTAL LIFTS/CYCLES (20)	ACTUAL TOTAL LIFTS/CYCLES (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LIFTS/CYCLES SINCE OH (23)				
03/2020	31903	00:00	00:00	NEW									

COMPONENTS INSTALLED ON ASSY

ASSY P/N (26) 3G6210A00131 ASSY S/N (27) AW5244

COMPONENT DATA

INSTALLATION

REMOVAL

DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY				COMPONENT				ASSY				COMPONENT							
			S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)	TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)
					TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)									
					TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)	TOTAL LIFTS/CYCLES WITH PENALTY FACTOR (40)	LIFTS/CYCLES SINCE OH (41)										

ASSEMBLY ACTIVITY HISTORY

ASSY P/N (44) 3G6210A00131 ASSY S/N (45) AW5244

DATE (46)	TOTAL HOURS (47)	TASKS (48)	ACTIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)
	TOTAL LANDINGS (47)				
	TOTAL LIFTS/CYCLES (47)				
22.3.22	111:26 199	SB 139 - 617, NEW ISSUE, ATA 62 - MAIN ROTOR BLADE LIGHTNING CORROSION PROTECTION IMPROVEMENT	CARRIED OUT AS PER SB 139 - 617. REFER WORKPACK 9M-SAAS-9194	GAM	

AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52) **3G6210A00131**

ASSY S/N (53) **AW5227**

AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS

OPTIONAL BULLETINS

AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)				ORGANIZATION (58)	STAMP AND SIGNATURE (59)	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ISSUE / REVISION (55)			DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)			
		ASSY TOTAL LIFTS/CYCLES (57)					ASSY TOTAL LIFTS/CYCLES (57)			
							<i>SB 139 - 617</i>	<i>111:26</i>		
							<i>NEW ISSUE</i>	<i>199</i>	<i>GAM</i>	
							<i>22.3.2022</i>			


DESCRIPTION (1)	P/N (2)	S/N (3)	MANUFACTURER NAME (4)	ASSEMBLY DATE (5)	RETIREMENT LIFE / TIME LIMITS (6)
MAIN ROTOR BLADE	3G6210A00131	AW5227	Leonardo S.p.A.	02/2020	20000 FH
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL						
DATE (12)	R. MARKS (13)	A/C			ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C			REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)	
		TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)			TOTAL FLIGHT HOURS (20)	ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)			TIME SINCE OH (23)
		TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)			TOTAL LANDINGS (20)	ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)			LANDINGS SINCE OH (23)
03/2020	31903	00:00	00:00	NEW								

DATE (46)	TOTAL HOURS (47)	TOTAL LANDINGS (47)	TOTAL LIFTS/CYCLES (47)	TASKS (48)	ACTIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)	ASSY P/N (44)	3G6210A00131	ASSY S/N (45)	AWS227	ASSEMBLY ACTIVITY HISTORY			
												DATE (46)	TOTAL HOURS (47)	TOTAL LANDINGS (47)	
22.3.2022	111:26	199		58 139-617, NEW ISSUE ATA 62, MAIN ROTOR BLADE LIGHTNING CORROSION PROTECTION IMPROVEMENT	CARRIED OUT AS PER 58 139-617 REFER WORKPACK 9M-SAAS-9194	GRAM									




NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

LOG CARD

Section 3
ATA Chapter 62

DESCRIPTION (28)	P/N (29)	S/N (30)	MANUFACTURING DATE (31)	RETIREMENT LIFE / TIME LIMITS (32)	ASSY			ASSY			DATE (36)	STAMP AND SIGNATURE (37)	ASSY			DATE (42)	STAMP AND SIGNATURE (43)					
					TOTAL HOURS (33)	TOTAL LANDINGS (34)	TOTAL LIFTS/CYCLES (35)	TOTAL HOURS (38)	TOTAL LANDINGS (39)	TOTAL LIFTS/CYCLES (40)			TOTAL HOURS (41)	TOTAL LANDINGS (41)	TOTAL LIFTS/CYCLES (41)							
COMPONENTS INSTALLED ON ASSY																						
<table border="0" style="width: 100%;"> <tr> <td style="width: 33%;">COMPONENT DATA</td> <td style="width: 33%;">INSTALLATION</td> <td style="width: 34%;">REMOVAL</td> </tr> <tr> <td>ASSY P/N (26) 3G6210A00131</td> <td>ASSY S/N (27) AWS227</td> <td></td> </tr> </table>																	COMPONENT DATA	INSTALLATION	REMOVAL	ASSY P/N (26) 3G6210A00131	ASSY S/N (27) AWS227	
COMPONENT DATA	INSTALLATION	REMOVAL																				
ASSY P/N (26) 3G6210A00131	ASSY S/N (27) AWS227																					



NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

LOG CARD

Section 2
ATA Chapter 62



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 4

ATA Chapter 62

AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52) **3G6210A00131**

ASSY S/N (53) **AW5236**

AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS

OPTIONAL BULLETINS

AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)				ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ORGANIZATION (58)	STAMP AND SIGNATURE (59)
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ASSY TOTAL LIFTS/CYCLES (57)				ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)			



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 1

ATA Chapter 62

DESCRIPTION (1) MAIN ROTOR BLADE	P/N (2) 3G6210A00131	S/N (3) AW5236	MANUFACTURER NAME (4) Leonardo S.p.A.	ASSEMBLY DATE (5) 02/2020	RETIREMENT LIFE / TIME LIMITS (6) 20000 FH
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11) 50200 Land.
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL						
DATE (12)	A/C R. MARKS (13)	ASSY			ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C TOTAL FLIGHT HOURS (20)	ASSY			REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
		TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)				TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
	S/N (14)	TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)		TOTAL LANDINGS (20)	ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS. WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
03/2020	31903	00:00	00:00	NEW	Leonardo Helicopters AW 1979							



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 2

ATA Chapter 62

COMPONENTS INSTALLED ON ASSY

ASSY P/N (26)		3G6210A00131				ASSY S/N (27)		AW5236			
COMPONENT DATA			INSTALLATION				REMOVAL				
DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY		COMPONENT		ASSY		COMPONENT		
	S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)
			TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)
			TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)		LIFTS/CYCLES SINCE OH (41)	



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 3

ATA Chapter 62

ASSEMBLY ACTIVITY HISTORY

ASSY P/N (44)		3G6210A00131				ASSY S/N (45)		AW5236			
DATE (46)	TOTAL HOURS (47)	TASKS (48)	ACTIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)						
	TOTAL LANDINGS (47)										
	TOTAL LIFTS/CYCLES (47)										
22.3.2022	111:26 199	SB 139-617, NEW ISSUE ATA 62, MAIN ROTOR BLADE LIGHTNING CORROSION PROTECTION IMPROVEMENT	CARRIED OUT AS PER SB 139-617. REFER WORKPACK 9M-SAAS-9194	GAM							



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 4

ATA Chapter

62

AIRWORTHINESS DIRECTIVES AND BULLETINS COMPLIANCE

ASSY P/N (52)		3G6210A00131			ASSY S/N (53)		AW5240				
AIRWORTHINESS DIRECTIVE AND MANDATORY BULLETINS					OPTIONAL BULLETINS						
AIRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)		ORGANIZATION (58)	STAMP AND SIGNATURE (59)	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)		ORGANIZATION (58)	STAMP AND SIGNATURE (59)
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ASSY TOTAL LIFTS/CYCLES (57)			ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ASSY TOTAL LIFTS/CYCLES (57)		
						Sg 139-617	111:26			GAM	
						NEW ISSUE	22.3.2022				



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 1

ATA Chapter

62

DESCRIPTION (1)	P/N (2)	S/N (3)	MANUFACTURER NAME (4)	ASSEMBLY DATE (5)	RETIREMENT LIFE / TIME LIMITS (6)
MAIN ROTOR BLADE	3G6210A00131	AW5240	Leonardo S.p.A.	02/2020	20000 FH
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL							
DATE (12)	R. MARKS (13)	A/C		ASSY		ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C		ASSY		REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
		TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)	TOTAL FLIGHT HOURS (20)			ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
		TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)	TOTAL LANDINGS (20)			ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
03/2020	31903	00:00	00:00	NEW	Leonardo Helicopters								

DATE (46)		TOTAL HOURS (47)	TOTAL LANDINGS (47)	TOTAL LIFTS/CYCLES (47)	ASSY P/N (44)	ASSY S/N (45)	ASSY S/N (45)	STAMP AND SIGNATURE (51)
22.3.2022		111:26	199		3G6210A00131	AW5240	AW5240	
SB 139-617, NEW ISSUE ATA 62, MAIN ROTOR BLADE LIGHTNING CORROSION PROTECTION IMPROVEMENT		CARRIED OUT AS PER SB 139-617 REFER WORKPACK 9M-SAAS-9194		gpm				

ASSEMBLY ACTIVITY HISTORY



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter

Section 3

62

DESCRIPTION (28)	P/N (29)	S/N (30)	MANUFACTURING DATE (31)		RETIRED LIFE / TIME LIMITS (32)		ASSY COMPONENT		ASSY COMPONENT	
			TOTAL HOURS (33)	TOTAL LANDINGS (33)	TOTAL LIFTS/CYCLES (33)	TOTAL (33)	DATE (36)	STAMP AND SIGNATURE (37)	TOTAL HOURS (38)	TOTAL LANDINGS (38)
			INSTALLATION		REMOVAL					
COMPONENT DATA			INSTALLATION		REMOVAL		COMPONENT DATA		INSTALLATION	
COMPONENTS INSTALLED ON ASSY			INSTALLATION		REMOVAL		COMPONENTS INSTALLED ON ASSY		INSTALLATION	
ASSY P/N (26)			ASSY S/N (27)		ASSY S/N (27)		ASSY P/N (26)		ASSY S/N (27)	
3G6210A00131			AW5240		AW5240		3G6210A00131		AW5240	



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter

Section 2

62