



CLIENT/OWNER: YTL POWER GENERATION SDN BHD	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO: 6587-024
AIRCRAFT TYPE: AW139	AIRCRAFT 41358	REFER WORKPACK		WORK/INSP/DESC: 300H/12M (REPETITIVE)
REGISTRATION: 9M-YTL	#1 ENGINE: PCE-KB1443	REFER WORKPACK		WORKPACK REF: 9M-YTL-6587
BASE/FACILITY: WMSA	#2 ENGINE: PCE-KB1457	REFER WORKPACK		AJL REF NO.: REFER WORKPACK
DATE IN: REFER WORKPACK OUT: REFER WORKPACK			NG / N1	NF / N2
				SHEET: 1 OF 1

Reason for raising:
SCHEDULED INSPECTION TO BE CARRIED OUT I.A.W. AMP NO.YTLPG/CAMO/AMP/AW139 ISSUE 1
REV. 2, AW139 IETP - 39TH ISSUE: 2021-06-07, UPDATED: 2021-07-20, EMM PT6C-67C REVISION
NO. 26.1, DATED 2021-09-30, TO THE LATEST PUBLICATION ISSUE/REVISION/UPDATES. -
300H/12M (REPETITIVE) EASA AD No.: 2021-0044 PARA (2) (ASB139-661 REV.A) PART II

Raised by and date:
Mohd Nor Azlizan Nordin
30/09/2021

Other requirements/information:
NIL

COMPLIANCE - ATA 24 OVERHEAD PANEL INSPECTION

Item	Description	Technician	* Eng. CRS	Date
1	<p>EASA AD No.: 2021-0044 PARA (2) (ASB139-661 REV.A) PART II COMPLIANCE - ATA 24 OVERHEAD PANEL INSPECTION</p> <p>EASA AD No.: 2021-0044 PARA (2) (ASB139-661 REV.A) PART 2I COMPLIANCE - ATA 24 OVERHEAD PANEL INSPECTION COMPLIANCE TO BE CARRIED OUT I.A.W. EASA AD No.: 2021-0044 AND ASB139-661 REV.A ACCOMPLISHMENT INSTRUCTION.</p> <p>PART II OF THIS SERVICE BULLETIN IS DEVELOPED TO PRESCRIBE A RECURRENT INSPECTION INSIDE THE OVERHEAD PANEL IN ORDER TO CHECK THE TAPE CONDITION AND THE ABSENCE OF CHAFING.</p> <p>REFERENCE: EASA AD No.: 2021-0044 (ASB139-661 REV.A)</p> <p>NOTE: PLEASE FILL UP SB FORM AND ATTACH WITH THE WORKSHEET</p> <p>REMARK: CARRIED OUT. FOUND SATISFACTORY</p>	 8292	 	20/10/21

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

BRN	CD	DUPLICATE	ENGINE	FLIGHTS	ENGINE	ACUPTNA	MONITORED	TRAINING	ERRY	HAUT	ILL	APR	ENGINE	PROPELLER	U/S	GEN	WARRANTY
RETURNED	PISTON	IN P.	NOV		CH	WORKSHEET	PERIOD	OFFICER	UPPER	TRAIL	NOISE	LOG	BOOK	CONTR	CHG	DO COPY	BOOK



CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK		SERIAL NO.	HOURS	LDG/CYCLE		WORKSHEET NO:	6587-024
	AIRCRAFT	41358				WORK/INSP/DESC:	300H/12M (REPETITIVE)
	#1 ENGINE:	PCE-KB1443				WORKPACK REF:	9M-YTL-6587
	#2 ENGINE:	PCE-KB1457				AJL REF NO.:	REFER WORKPACK
						SHEET:	1 OF 1

REASON FOR RAISING: SCHEDULED INSPECTION TO BE CARRIED OUT I.A.W. AMP NO.YTLPG/CAMO/AMP/AW139 ISSUE 1 REV. 2, AW139 IETP - 39TH ISSUE: 2021-06-07, UPDATED: 2021-07-20, EMM PT6C-67C REVISION NO. 26.1, DATED 2021-09-30, TO THE LATEST PUBLICATION ISSUE/REVISION/UPDATES. - 300H/12M (REPETITIVE) EASA	Raised by and date: Mohd Nor Azlizan Nordin 30/09/2021	Other requirements/information: NIL
---	--	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
/									

NAME	FIRM	SIGN & APPROVAL	DATE
E. Emar	GAM		20/10/2021

*The work recorded above has been carried out in accordance with the requirements of the Malaysian Civil Aviation Regulation for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

*The work recorded above has been carried out in accordance with the requirements of the _____ for the time being in force and in that respect the aircraft / equipment is considered fit for release to service.

TICK ✓ WHERE APPLICABLE

LINE	QTY	DESCRIPTION	ISSUE	DATE	STATUS	REMARKS	APPROVED	DATE	BY
------	-----	-------------	-------	------	--------	---------	----------	------	----

Please send to the following address: LEONARDO S.p.A. CUSTOMER SUPPORT & SERVICES - ITALY PRODUCT SUPPORT ENGINEERING & LICENSES DEPT. Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	SERVICE BULLETIN COMPLIANCE FORM	Date: 20/10/2021
	Number: SBA139 - 661 REV. A PART II	
	Revision: -	

Customer Name and Address: GALAXY AEROSPACE (M) SDN BHD Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN	Telephone: 603-7734 7226
	Fax: 603-7734 7226
	B.T. Compliance Date: 20/10/2021

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
AW139	41358	1	275 : 17	-

Remarks:

CARRIED OUT AND FOUND SATISFACTORY.



Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.