


# DELIVERY NOTE WP

**DELIVER TO :**

GALAXY AEROSPACE (M) SDN. BHD.  
CAMO DEPARTMENT  
Lot 11, MRO Centre,  
Malaysia International Aerospace Centre,  
Sultan Abdul Aziz Shah Airport,  
47200 Subang, Selangor  
Malaysia.  
Attn : Zaty Nadhira binti Mohamed Zuhari

**DN NUMBER :** GAM/DN/YTL-22-094  
**OUR REFERENCE :** 9M-YTL-13059  
**WO REFERENCE :** 2022-13059  
**DATE COMPLETION:** 12 OCTOBER 2022  
**AJL NUMBER :** 1569

A/C DETAILS								
A/C TYPE	AW139	A/C REG	9M-YTL	A/C S/N	41358			
OWNER / OPERATOR	YTL POWER GENERATION SDN. BHD	A/C TOTAL TIME	348:40	LANDINGS	530			
ENGINE #1 S/N	PCE-KB1443	T.S.N	348:40	T.S.O	-			
ENGINE #2 S/N	PCE-KB1457	T.S.N	348:40	T.S.O	-			
LIST OF TASK PERFORMED	WP NUMBER	NUMBER OF PAGES						
		*WS	*PR	*TR	*ARC	*S	*SBC	*OTH
ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION EASA AD 2022-0209-E NEW ISSUE, EASB 139-731 REV./PART 1	9M-YTL-13059	1	1	1	-	-	1	-
*THIS IS TO CERTIFY THAT TASKS LISTED ABOVE HAS BEEN ACCOMPLISHED AS PER PO/WORK ORDER/SERVICE ORDER NO. 1AS ABOVE.								
NAME	NAAIM HAFIZ SHAH	SIGNATURE		DATE	17 OCTOBER 2022			
VERIFIED AND ACCEPTED BY				THAVAMALAR A/P KUMARAVELU CAMO Planner Galaxy Aerospace (M) Sdn Bhd (1040262-D)				
DATE				18/10/2022				

\*WS – WORKSHEET

\*S – SERVICEABLE LABEL

\*TR – TOOLS REPORT

\*PR – PART REPORT

\*SBC – SERVICE BULLETIN COMPLIANCE

\*ARC – AUTHORISED RELEASE CERTIFICATE

\*OTH – OTHERS

# WORK ORDER



To: GALAXY AEROSPACE (M) SDN. BHD.

<p><b>Address:</b> Lot 11-14, MRO Centre, Malaysia International Aerospace Centre, SAAS Airport, Subang Malaysia</p> <p><b>Attention:</b> Mr. Syafrul Yamani Engineering Manager syafrul@galaxyaerospace.my</p>	<p><b>Work Order Number:</b> 2022-13059</p> <hr/> <p><b>Work Pack Reference:</b> 9M-YTL-13059</p> <hr/> <p><b>Date Issued:</b> 12/10/2022</p> <hr/> <p><b>A/C Registration / SN:</b> 9M-YTL/41358</p> <hr/> <p><b>Sheet:</b> 1 of 1</p>
---	---

**Description:**

Item	Description/Task/Inspection	Reference	Man Hours
1	ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION EASA AD 2022-0209-E NEW ISSUE, EASB 139-731 REV./PART 1	EASA AD 2022-0209-E NEW ISSUE, SBEA 139-731 REV./ PART I	<u>4.0</u> (PLEASE ADVISE)

**Remark/Notes:**

1. State this Work Order reference on your Work Package. Should there is any additional job/defect (unless specified in the work package) the maintenance organization must notify GAM Continuing Airworthiness Manager prior to proceed with rectification.
2. Work must be carried out in accordance with approved data and perform by qualified personnel/ approved LAE from the maintenance organization.
3. Parts used must be written in Parts Report Form and accompanied by ARC, Serviceable Label or equivalent document.
4. Test report, parameter reading or any supporting data must be attached with the worksheet if applicable.
5. The maintenance organization shall be responsible for any damages made on the aircraft/ components during maintenance.
6. Softcopy of completed Work Package shall be submitted or as mutual agreed and GAM Continuing Airworthiness Manager must be informed once the aircraft is Release to Service.
7. Completed Work Package (original) must be submitted to GAM Continuing Airworthiness Manager office within 3 days of date of completion.

I hereby declare that an approved and up to date maintenance data has been referred for the issuance of this work order.

Thank you.  
Best Regards,

Zaty Nadhira Mohamed Zuhari  
Continuing Airworthiness Management Manager  
Email: zaty@galaxyaerospace.my







CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: REFER WORKPACK    OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	13059-001
	AIRCRAFT	41358	REFER WORKPACK	WORK/INSP/DESC:	EASA AD 2022-0209-E
	#1 ENGINE:	PCE-KB1443	REFER WORKPACK	WORKPACK REF:	9M-YTL-13059
	#2 ENGINE:	PCE-KB1457	REFER WORKPACK	AJL REF NO.:	REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

Reason for raising: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0209-E NEW ISSUE DATED 12-OCT-2022, SBEA 139-731 REV./ PART I, DATED 11-OCT-2022, AW139 IETP - 41ST ISSUE 2022-06-28 UPDATED 2022-09-08 OR LATER APPROVED REVISIONS.	Raised by and date: CAMO; Thavamalar 12/10/2022	Other requirements/information: NIL
---	---	--

Item	Description	Technician	* Eng. CRS	Date
1	ATA 00 FORWARD CABIN ROOF CEILING HARNESS INSPECTION  CARRY OUT INSPECTION AS PER EASA AD 2022-0209-E NEW ISSUE SBEA 139-731 REV./ PART I) NOT EXCEED 10 FH.  TO PERFORM PART 1, TO PRESCRIBE A ONE-OFF INSPECTION OF THE FORWARD CABIN ROOF CEILING HARNESSES INSTALLATION IN THE AREA BETWEEN STA 3120 AND 3400 TO VERIFY THE PROPER INSTALLATION OF THE CIAs IN THE AREA. ACCOMPLISH A BORESCOPE INSPECTION OF THE CABLE INSTALLATION INSIDE THE FORWARD CABIN ROOF CEILING, IN ACCORDANCE WITH THE INSTRUCTIONS OF SECTION 3 PART I OF THE ASB.	[Signature] 8349	[Signature] 	12/16/2022
	REMARKS: TASK CARRIED OUT, FOUND SATISFACTORY			

\*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service.

\*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with \_\_\_\_\_ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK ✓ WHERE APPLICABLE

DATE ISSUED	ISSUED BY	DUPLOE REP	SPARE P/L	LIGHTER	TOOLS	ADDITIONAL WORKSHEET	MINUTE SHEET	QUALITY CHECKED	DATE ISSUED	DATE WORKED	TO CHECK	APPROVED	ENGINEER SIGN	RELEASED	DATE	REVISIONS	REWORK
-------------	-----------	------------	-----------	---------	-------	----------------------	--------------	-----------------	-------------	-------------	----------	----------	---------------	----------	------	-----------	--------

# Tools Report



<b>Aircraft Serial No:</b>	41358	<b>Work Pack No:</b>	9M-YTL-13059
<b>Aircraft Type:</b>	AW139	<b>DESC:</b>	EASA AD 2022-0209-E
<b>Aircraft Reg:</b>	9M-YTL	<b>PAGE:</b>	1 Of 1

Description	Part No	Serial Number	Worksheet Ref No. / Item No.	Calibration Due Date

*Jr*  
 12/10/2022





CLIENT/OWNER: YTL POWER GENERATION SDN BHD AIRCRAFT TYPE: AW139 REGISTRATION: 9M-YTL BASE/FACILITY: WMSA DATE IN: REFER WORKPACK OUT: REFER WORKPACK	SERIAL NO.	HOURS	LDG/CYCLE	WORKSHEET NO:	13059-001
	AIRCRAFT	41358	REFER WORKPACK	WORK/INSP/DESC:	EASA AD 2022-0209-E
	#1 ENGINE:	PCE-KB1443	REFER WORKPACK	WORKPACK REF:	9M-YTL-13059
	#2 ENGINE:	PCE-KB1457	REFER WORKPACK	AJL REF NO.:	REFER WORKPACK
			NG / N1	NF / N2	SHEET: 1 OF 1

REASON FOR RAISING: INSPECTION TO BE CARRIED OUT I.A.W EASA AD 2022-0209-E NEW ISSUE DATED 12-OCT-2022, SBEA 139-731 REV/ PART I, DATED 11-OCT-2022, AW139 IETP - 41ST ISSUE 2022-06-28 UPDATED 2022-09-08 OR LATER APPROVED REVISIONS.	Raised by and date: CAMO; Thavamalar 12/10/2022	Other requirements/information: NIL
--	---	--

Item	Part No	Description	Serial Number		Qty	Position	Reason	Lifed Item Information TSN/TSO/DUE/TIMEX	Release Reference
			Off	On					
(Table content is crossed out with a diagonal line)									

NAME	FIRM	SIGN & APPROVAL	DATE
M. JAMIL SAMUDIN	GAM		12/10/2022

\*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with CAA Malaysia Requirements and in respect to that work the aircraft / aircraft component is considered ready for release to service.

\*Certifies that the work specified above, except as otherwise specified, was carried out in accordance with \_\_\_\_\_ and in respect to that work the aircraft / aircraft component is considered ready for release to service.

TICK ✓ WHERE APPLICABLE

PARTS LABEL & IDENTIFY	DI PARTS	CHECKLIST	GROUND	FLIGHT	TORQUE	ADDITIONAL	INSPECTED	PLANNING	DIARY	SPARE	DEL	AIRCRAFT	ENGINE	APPROVAL	LOG	REWORK	REC'D
------------------------	----------	-----------	--------	--------	--------	------------	-----------	----------	-------	-------	-----	----------	--------	----------	-----	--------	-------




Please send to the following address:  <b>LEONARDO S.p.A.</b> <b>CUSTOMER SUPPORT &amp; SERVICES - ITALY</b>  <b>PRODUCT SUPPORT ENGINEERING &amp; LICENSES DEPT.</b> Via Giovanni Agusta, 520 21017 Cascina Costa di Samarate (VA) - ITALY Tel.: +39 0331 225036 Fax: +39 0331 225988	<b>SERVICE BULLETIN COMPLIANCE FORM</b>	Date: <i>11 OCT 2022</i>
	Number: <i>139-731</i>	
	Revision: <i>-</i>	

Customer Name and Address: <b>GALAXY AEROSPACE (M) SDN BHD</b> Suite 11-14, Helicopter Centre, Malaysia International Aerospace Centre, Sultan Abdul Aziz Shah Airport, 47200 Subang, SELANGOR DARUL EHSAN	Telephone: <b>603-7734 7226</b>
	Fax: <b>603-7734 7226</b>
	B.T. Compliance Date: <i>12 / 10 / 2022</i>

Helicopter Model	S/N	Total Number	Total Hours	T.S.O.
<i>AW139</i>	<i>41358</i>			

Remarks: *PERFORMED SB 139-731 PART 1, FOUND SATISFACTORY.*

*[Signature]*



Information:

We request your cooperation in filling this form, in order to keep out statistical data relevant to aircraft configuration up-to-date. The form should be filled in all its parts and sent to the above address or you can communicate the application also via Technical Bulletin Application Communication Section placed in Leonardo AW Customer Portal - MyCommunications Area. We thank you beforehand for the information given.