10/3/24, 4:28 AM about:blank

AIRWORTHINESS DIRECTIVES FINAL RULES: 73-19-07

CITATION: This information is not available.

PAGE NUMBER:

DOCKET NUMBER: Unknown

AMENDMENT: 39-1715

AD NUMBER: 73-19-07

SUBJECT HEADING: DETROIT DIESEL ALLISON Model 250-C20 Engine

ACTION:

SUMMARY:

DATES: Effective September 14, 1973.

ADDRESSES:

FOR FURTHER INFORMATION CONTACT:

SUPPLEMENTARY INFORMATION:

REGULATORY TEXT: 73-19-07 DETROIT DIESEL ALLISON: Amdt. 39-1715. Applies to Detroit Diesel Allison Model 250- C20 engine.

Compliance required within the next fifty hours time in service unless already accomplished. To prevent failure of the P/N 6875621 power turbine governor-to-fuel control fuel tube, install the fuel tube supports specified in Allison Commercial Engine Bulletin 250-C20 CEB-1040, dated May 10, 1973, Revision 1, dated June 28, 1973, or later FAA approved revisions or an equivalent procedure approved by the Chief, Engineering and Manufacturing Branch, Great Lakes Region.

This amendment is effective September 14, 1973.

FOOTER:

about:blank 1/1