

AD/SB ID: 8138 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: SEALING RING DRIFT

Title/Subject: TSB NO. PW200-26, REVISION 1 - ENGINE NO. 1

Version No:

Reason For Raising:

URL:

Date: -- -- --

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
	TSB NO. PW200-26, REVISION 1	8138-1896.pdf

AD/SB ID: 8138 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-PEC	Untracked	-		0	-	-	INFO - MANDATORY

AD/SB ID: 8139 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: SEALING RING DRIFT

Title/Subject: TSB NO. PW200-26, REVISION 1 - ENGINE NO. 2

Version No:

Reason For Raising:

URL:

Date: -- -- --

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
	TSB NO. PW200-26, REVISION 1	8139-1897.pdf

AD/SB ID: 8139 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-PEC	Untracked	-		0	-	-	INFO - MANDATORY