

AD/SB ID: 8141 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS  Repetitive

Reference/Number: NO. 4 BEARING - REPLACEMENT OF

Title/Subject: SB NO. 13293R1 - ENGINE NO. 1

Version No:

Reason For Raising:

URL:

Date: 06 01 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	SB NO. 13293R1	8141-1899.pdf

AD/SB ID: 8141 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PTA	Not Applicable	-		0	-	-	Category 8	
	9M-PTB	Not Applicable	-		0	-	-	Category 8	
	9M-PTC	Not Applicable	-		0	-	-	Category 8	
	9M-PTD	Not Applicable	-		0	-	-	Category 8	
	9M-PTE	Not Applicable	-		0	-	-	Category 8	

General Config List Aircraft List Task List Linked To BOM

Type: SBS  Repetitive

Reference/Number: NO. 4 BEARING - REPLACEMENT OF

Title/Subject: SB NO. 13293R1 - ENGINE NO. 2

Version No:

Reason For Raising:

URL:

Date: 06 01 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
SB NO. 13293R1		8142-1900.pdf

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-PTA	Not Applicable	-		0	-	-	Category 8	
	9M-PTB	Not Applicable	-		0	-	-	Category 8	
	9M-PTC	Not Applicable	-		0	-	-	Category 8	
	9M-PTD	Not Applicable	-		0	-	-	Category 8	
	9M-PTE	Not Applicable	-		0	-	-	Category 8	