

## ADS AIRWORTHINESS DIRECTIVES (AD'S) STATUS LIST

Aircraft Registration:	9M-YTL	Serial No:	41358	Date:	24/08/2022	Page No:	1
Aircraft Hours:	345:34	Landings:	526.00	Engine 1:	345:34	Engine 2:	345:34

Types	AD Number	Subject	Last Done	Next Due	Interval/Status	Limitation Notes
<b>ADs</b>						
<b>Types</b>	<b>AD Number</b>	<b>Subject</b>	<b>Last Done</b>	<b>Next Due</b>	<b>Interval</b>	<b>Limitation Notes</b>
Repetitive ADs	EASA AD No.: 2018-0112R1 (SB139-450 PART III & IV) MR D	EASA AD No.: 2018-0112R1	-	00/00/0000	1	EVERY BFF/ALF - REFER TO MONTHLY WORK
Repetitive ADs	EASA AD 2022-0152-E PARA (2)(SBEA 139-725 REV/PART 2)	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT(WITHIN 10FH AND EVERY 50FH)	339:44	349:44	10	
Repetitive ADs	EASA AD 2022-0152 PARA 1 (EASB139-725 REV/ PART1	ATA 64-TAIL ROTOR DUPLEX BEARING INSPECTION AND REPLACEMENT (BFF AND EVERY 10FH)	339:44	349:44	10	TIC-AW139-22-0157 EASA AD 2022-0152E PARA (1), SBEA 139-725 PART 1 BFF CARRIED OUT ON 1-AUG-2022 (9M-YTL-12167) - AJL 1550 AT AFH 339:45FH  NOTE: TO BE REPEATED EVERY 10FH UNTIL TR DUPLEX BEARING REPLACEMENT
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	10/11/2021	09/11/2022	12	LAST DONE EASA AD 2021-0044 PARA (1), ASB139-661 PART 1 25FH ONCE OFF REFER TO 9M-YTL-5825 AT 255:15FH ON 06/04/2021 AFTER PARA 1// PART 1 COMPLIANCE, REPETITIVE 300H/1Y TO BER CARRIED OUT.  LAST DONE 9M-YTL-6587 AT 275:23FH ON 10-NOV-2021
Repetitive ADs	EASA AD 2021-0044 REV 1 PARA (2) (ASB139-661 REV. B)	ATA 24 OVERHEAD PANEL INSPECTION 300H/12M REPETITIVE PART II COMPLIANCE	275:24	575:24	300	