

Edit Limitation (A/C: 9M-PTA)

Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 1-PITCH CHANGE KNOB... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTA)

Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 2-PITCH CHANGE KNOB... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTB)

Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 1-PITCH CHANGE KNOB... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTB)

Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 2-PITCH CHANGE KNOB... Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTC)

**Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 1-PITCH CHANGE KNOB...** Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTC)

**Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 2-PITCH CHANGE KNOB...** Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTD)

**Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 1-PITCH CHANGE KNOB...** Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTD)

**Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 2-PITCH CHANGE KNOB...** Cancel Save

Based On: Not Applicable

Warning: 0

Warning Unit: Select

Completed: -

Due At: 0.00

Status: NOT APPLICABLE

Limitation Notes: NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED. REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTE)

Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 1-PITCH CHANGE KNOB...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: NOT APPLICABLE ▼

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED.  
REFER TIC-B300-23-0001 DATED 06/01/2023.

Edit Limitation (A/C: 9M-PTE)

Edit Limitation HC-SB-61-389, NEW ISSUE - PROPELLER NO. 2-PITCH CHANGE KNOB...

Based On: Not Applicable ▼

Warning: 0

Warning Unit: Select ▼

Completed: -

Due At: 0.00

Status: NOT APPLICABLE ▼

Limitation Notes:

NOT APPLICABLE DUE TO AIRCRAFT PROPELLER MODEL HC-B4MP-3C NOT AFFECTED.  
REFER TIC-B300-23-0001 DATED 06/01/2023.