

HIGHLIGHT

AMM AMMPM-B2B3-HIGHLIGHT

Publication Title AMM AS350 B2-B3 NR025**Publication Date** 2024.07.01

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 00-00-00	LIST OF ILLUSTRATIONS	N	2024.07.01			No
AMM 05-40-00,6-7	P inspection - Daily Checks	R	2024.05.31	I	Information added	No
AMM 05-40-00,6-7A	P inspection PRE MOD 074302 - Daily Checks	R	2024.05.31	I	Information added	No
AMM 05-40-00,6-7B	P inspection POST MOD 074302 - Daily Checks	R	2024.05.31	I	Information added	No
AMM 05-40-00,6-9	Check Before the First Flight of the Day - Optional equipment - Daily Checks	R	2024.05.16	M	Aircraft build standard changed	Yes
AMM 05-40-00,6-10	Check After the Last Flight of the Day - Optional Equipment - Daily Checks	R	2024.04.25	C	Discrepancy corrected	Yes
AMM 05-50-00,6-4	Procedure After Overtorque - Unscheduled Inspections	R	2024.05.24	C	Discrepancy corrected	No
AMM 05-50-00,6-4A	Actions to take if there is overtorque PRE MOD 074302 - Unscheduled Inspections	R	2024.05.31	I	Information added	No
AMM 05-50-00,6-4B	Procedure if there is overtorque POST MOD 074302 - Unscheduled Inspections	R	2024.05.31	I	Information added	No
AMM 05-50-00,6-5A	Procedure after a hard landing PRE MOD 074302 - Unscheduled Inspections	R	2024.05.31	I	Information added	No
AMM 05-50-00,6-5B	Procedure after a hard landing POST MOD 074302 - Unscheduled Inspections	R	2024.05.31	I	Information added	No
AMM 05-50-00,6-6	Procedure if there is an impact on the main rotor blades - Unscheduled Inspections	R	2024.05.31	I	Information added	No
AMM 05-50-00,6-7	Measures to be Taken After Impact / Unbalance on the Tail Rotor Blade - Unscheduled Inspections	R	2024.05.21	C	Discrepancy corrected	No
AMM 05-60-00,6-1	Mechanical assemblies - Main Rotor Drive / Tail Rotor Drive - Calendar Inspections	R	2024.04.10	C	Discrepancy corrected	Yes
AMM 09-10-00,3-1A	Towing - Helicopter with hydraulic dual wheels taxiing device PRE MOD 0720142 - Towing and Taxiing	R	2024.05.06	I	Information added	Yes
AMM 09-10-00,3-1B	Towing - Helicopter with hydraulic dual wheels for prepared ground - Towing and Taxiing	R	2024.05.06	I	Information added	Yes
AMM 09-10-00,3-1C	Towing - Helicopter with hydraulic taxiing device POST MOD 0720142 - Towing and Taxiing	R	2024.05.06	I	Information added	Yes
AMM 10-10-00,3-3	Short-term immobilization - Helicopter - Parking and Picketing	R	2024.03.15	C	Discrepancy corrected	Yes
AMM 23-12-53,1-1	GNC 215 VHF Installation - GNC 215 VHF Installation	N	2024.05.02	R	New document unit	Yes
AMM 23-12-53,4-1	Removal / Installation GNC 215 - GNC 215 VHF Installation	N	2024.03.19	R	New document unit	Yes
AMM 23-12-53,4-2	Removal / Installation VHF Antenna - GNC 215 VHF Installation	N	2024.03.19	R	New document unit	Yes
AMM 23-12-53,5-1	Functional Tests - GNC 215 Installation - GNC 215 VHF Installation	N	2024.05.02	R	New document unit	Yes
AMM 23-12-53,7-1	Cleaning of the screen - GNC 215 VHF installation - GNC 215 VHF Installation	N	2024.05.02	R	New document unit	Yes
AMM 24-60-01,4-1	Removal / Installation - GSB 15 - DUAL USB GSB 15	N	2024.04.08	R	New document unit	Yes
AMM 24-60-01,5-1	Functional tests - GSB 15 - DUAL USB GSB 15	N	2024.04.08	R	New document unit	Yes
AMM 24-90-00,4-1	Removal / Installation - ECIS 1 unit - Relay cards (ECIS)	N	2024.04.08	R	New document unit	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 24-90-00.4-2	Removal / Installation - ECIS 2 unit - Relay cards (ECIS)	N	2024.04.08	R	New document unit	Yes
AMM 24-90-00.4-3	Removal / Installation - ECIS card - Relay cards (ECIS)	N	2024.04.08	R	New document unit	Yes
AMM 24-90-00.5-1	LH1 card functional tests (ECIS) - Relay cards (ECIS)	N	2024.03.13	R	New document unit	Yes
AMM 24-90-00.5-2	LH2 card functional tests (ECIS) - Relay cards (ECIS)	N	2024.03.13	R	New document unit	Yes
AMM 24-90-00.5-3	LH3 card functional tests (ECIS) - Relay cards (ECIS)	N	2024.03.13	R	New document unit	Yes
AMM 24-90-00.5-4	LH4 card functional tests (ECIS) - Relay cards (ECIS)	N	2024.03.13	R	New document unit	Yes
AMM 24-90-00.5-5	LH5 card functional tests (ECIS) - Relay cards (ECIS)	N	2024.03.13	R	New document unit	Yes
AMM 25-66-02.5-1	DELETED	D	2010.02.04			No
AMM 25-96-00.6-1	Check - External mirror - External mirrors	R	2024.03.25	I	Information added	Yes
AMM 25-96-00.6-3	Check - Electrical external mirror - External mirrors	N	2024.03.25	R	New document unit	Yes
AMM 29-00-00.2-1	Hydraulic Power Supply on the Ground - General	R	2024.03.18	I	Information added	No
AMM 29-00-00.2-1A	Hydraulic Power Supply on the Ground PRE MOD OP3082 or PRE MOD OP3346 - General	R	2024.03.18	I	Information added	No
AMM 29-00-00.2-1B	Hydraulic power supply on the ground POST MOD OP3082 or POST MOD OP3346 - General	R	2024.03.18	I	Information added	No
AMM 29-11-00.4-2	Removal / Installation - Hydraulic reservoirs - Main Hydraulic Dual Generation	R	2023.12.21	C	Discrepancy corrected	Yes
AMM 29-11-00.4-4	Removal / Installation - Hydraulic circuit ground power receptable manifold - Main Hydraulic Dual Generation	R	2024.05.28	R	New document unit	Yes
AMM 29-11-00.5-2A	Functional tests - Hydraulic Circuit PRE MOD 074622 - Main Hydraulic Dual Generation	R	2024.03.15	I	Information added	No
AMM 29-11-00.5-2B	Functional tests - Hydraulic Circuit POST MOD 074622 - Main Hydraulic Dual Generation	R	2024.03.15	I	Information added	No
AMM 29-12-01.4-1	Removal / Installation - Belt-driven hydraulic pump PRE MOD OP3082 or PRE MOD OP3346 or POST MOD 0770004 - Belt-driven hydraulic pump	R	2024.05.15	I	Information added	Yes
AMM 29-12-02.4-1	Removal / Installation - MGB hydraulic pump POST MOD 0770000 - MGB Hydraulic pump	R	2024.05.15	I	Information added	Yes
AMM 29-12-02.4-1	Removal / Installation - MGB hydraulic pump POST MOD 0770004 - MGB Hydraulic pump	R	2024.05.15	I	Information added	Yes
AMM 31-32-01.1-1	DELETED	D	2022.11.28			No
AMM 31-32-01.1-1	Fault isolation - FDRS - Flight Data Recording System	N	2024.04.15	R	New document unit	Yes
AMM 31-33-01.1-1A	Fault isolation - AIRS-400 camera - AIRS-400 Camera	N	2024.05.16	I	Information added	Yes
AMM 31-33-01.4-1A	Removal / Installation - AIRS-400 camera - AIRS-400 Camera	N	2024.05.16	I	Information added	Yes
AMM 31-33-01.4-2A	Removal / Installation - GPS antenna - AIRS-400 Camera	N	2024.03.29	R	New document unit	Yes
AMM 31-33-01.4-3A	Removal / Installation - SD card - AIRS-400 Camera	N	2024.05.16	I	Information added	Yes
AMM 31-33-01.5-1A	Configuration - AIRS-400 camera - AIRS-400 Camera	N	2024.05.16	R	New document unit	Yes
AMM 31-33-01.6-1A	Check of the data - AIRS-400 camera - AIRS-400 Camera	N	2024.05.16	R	New document unit	Yes
AMM 31-33-01.7-1A	Cleaning - Lens - AIRS-400 Camera	N	2024.03.29	R	New document unit	Yes
AMM 31-41-00.8-1	DELETED	D	2010.02.04			No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 31-41-00.8-1A	Replacement - ASU board PRE MOD 0720207 - Ancillary System Unit (ASU)	N	2024.04.08	R	New document unit	Yes
AMM 31-41-00.8-1B	Replacement - ASU boards POST MOD 0720207 - Ancillary System Unit (ASU)	N	2024.04.08	R	New document unit	Yes
AMM 31-42-00.8-1A	Replacement - Push-button PRE MOD 073273 PRE MOD 073274 - Control unit	R	2024.05.28	R	New document unit	Yes
AMM 31-42-00.8-3	Replacement of a Push-button bulb PRE MOD 073273 PRE MOD 073274 - Control unit	R	2024.05.28	R	New document unit	Yes
AMM 33-00-00.6-1	Check - Lighting System - Lighting System	R	2024.05.06	I	Information added	Yes
AMM 33-12-00.5-1D	Functional Tests POST MOD 0720207 - Instrument panel lighting - Instrument Panel Lighting	N	2024.05.06	R	New document unit	Yes
AMM 33-43-03.4-1	Removal / Installation - LED landing light - Fixed Light	N	2024.03.28	R	New document unit	Yes
AMM 33-43-03.4-2	Removal / Installation - LED taxiing light - Fixed Light	N	2024.03.28	R	New document unit	Yes
AMM 33-43-03.5-1	Functional tests - LED lights and PULSE function - Fixed Light	N	2024.04.19	R	New document unit	Yes
AMM 33-43-03.8-1	Replacement - Front face kit - Fixed Light	N	2024.03.28	R	New document unit	Yes
AMM 34-25-32.1-1	Fault Isolation - GI275 - GI275	R	2024.04.25	I	Information added	Yes
AMM 34-25-32.5-1	Functional Tests - GI275 - GI275	R	2024.04.25	I	Information added	Yes
AMM 34-51-40.1-1	GTX 345R Transponder - GTX 345R Transponder	N	2024.05.02	R	New document unit	Yes
AMM 34-51-40.4-1	Removal / Installation - GTX 345R Transponder - GTX 345R Transponder	N	2024.04.25	R	New document unit	Yes
AMM 34-51-40.4-2	Removal / Installation - Antenna - GTX 345R Transponder	N	2024.04.25	R	New document unit	Yes
AMM 34-51-40.5-1	Functional Tests - GTX 345R Transponder - GTX 345R Transponder	N	2024.05.02	R	New document unit	Yes
AMM 34-58-03.4-2	Removal / Installation - GLIDE Antenna - GNC 255 VOR / LOC / GLIDE installation	N	2023.09.05	C	Discrepancy corrected	Yes
AMM 34-58-16.1-1	Fault Isolation - GNC 215 - GNC 215 VOR / LOC / GLIDE installation	N	2024.03.19	R	New document unit	Yes
AMM 34-58-16.4-1	Removal / Installation - VOR / LOC antenna - GNC 215 VOR / LOC / GLIDE installation	N	2024.03.19	R	New document unit	Yes
AMM 34-58-16.4-2	Removal / Installation - GLIDE antenna - GNC 215 VOR / LOC / GLIDE installation	N	2024.03.19	R	New document unit	Yes
AMM 34-58-16.5-1	Functional tests - GNC 215 - GNC 215 VOR / LOC / GLIDE installation	N	2024.03.19	R	New document unit	Yes
AMM 52-12-00.4-4A	Removal - Installation of the locking mechanism PRE MOD 074267 / PRE MOD OP4268 - Sliding Door	R	2024.05.06	I	Information added	No
AMM 52-12-00.4-4B	Removal - Installation of the locking mechanism POST MOD 074267 or POST MOD OP4268 - Sliding Door	R	2024.05.06	I	Information added	No
AMM 52-12-00.5-1	Adjustment / Test - Sliding Door - Sliding Door	R	2024.05.06	C	Discrepancy corrected	No
AMM 52-12-00.6-1	Inspection criteria - Sliding door - Sliding Door	R	2024.04.16	I	Information added	Yes
AMM 52-13-00.4-2	Removal / Installation - Sleeves and support on subdoor - Flap Door	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 53-00-00.6-1	Check - Fuselage - Fuselage	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 53-10-00.8-38	Repair - 7° bulkhead - Structure	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 53-10-00.8-39	Replacement of the RH and LH Cabin Floor Baseboards - Structure	R	2024.05.24	I	Information added	No
AMM 53-31-00.8-1	General Rules in Force Applicable for Repair on Tail Boom - Rear fuselage	R	2024.01.31	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 53-51-00.8-1	Repair - Internal Skin of the Engine Cowling - Cowlings	R	2024.05.22	C	Discrepancy corrected	Yes
AMM 55-11-00.8-1	Repair - Tailing edge of the stabilizer - Horizontal stabilizer	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 56-11-00.4-2	Removal / Installation - Window PRE MOD 072507 - Windshield / Windows / Door windows	R	2024.05.16	I	Information added	No
AMM 56-11-00.4-2	Removal / Installation - Glazed Panel - Windshield / Windows / Door windows	R	2024.05.16	I	Information added	No
AMM 56-11-00.4-6	Removal / Installation - Enlarged Field of Vision Window - Windshield / Windows / Door windows	R	2024.05.16	I	Information added	No
AMM 60-00-00.6-4	Check of the magnetization of the electrical or non-electrical magnetic plugs - General instructions - Mechanical assemblies	R	2024.02.15	C	Discrepancy corrected	No
AMM 62-00-00.5-1A	Adjustment - Check and Correction of the Vertical Z and Horizontal Y Vibrations - Main Rotor	R	2024.05.31	I	Information added	No
AMM 62-11-00.6-1	Inspection Criteria - Main Rotor Blades - Main rotor blades	R	2024.02.15	C	Discrepancy corrected	No
AMM 62-11-00.6-3	Visual Inspection Criteria - Blade Skin and Leading Edge - Main rotor blades	R	2023.12.21	C	Discrepancy corrected	No
AMM 62-11-00.8-8	Replacement of the target-holder insert - Main rotor blades	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 62-11-00.8-18	Repair - Minor Paint Touch-Ups - Main rotor blades	R	2023.12.21	C	Discrepancy corrected	No
AMM 62-21-00.4-1	Removal - Main Rotor Hub - Main rotor hub	R	2024.03.15	I	Information added	No
AMM 62-21-00.4-2	Installation - Main Rotor Hub POST MOD 076120 - Main rotor hub	R	2024.03.15	I	Information added	No
AMM 62-21-00.4-4A	Assembly - Main Rotor Hub PRE MOD 076232 - Main rotor hub	R	2024.04.29	C	Discrepancy corrected	No
AMM 62-21-00.4-4B	Assembly - Main Rotor hub POST MOD 076232 - Main rotor hub	R	2024.04.29	C	Discrepancy corrected	No
AMM 62-21-00.4-4C	Assembly - Main rotor hub POST MOD 072668 - Main rotor hub	R	2024.04.29	C	Discrepancy corrected	No
AMM 62-21-00.4-5	Removal / Installation - Spring Anti-Vibrator - Main rotor hub	R	2024.03.15	C	Discrepancy corrected	No
AMM 62-21-00.6-20	Check of the tightening torque of the sleeves / stops / adapters attachments - Main rotor hub	R	2024.04.18	I	Information added	Yes
AMM 62-31-00.4-2	Disassembly - Main rotor mast PRE MOD 076120 (single hydraulic) - Rotor mast	R	2024.05.16	I	Information added	No
AMM 62-31-00.4-3	Assembly - Main rotor mast POST MOD 076120 (Dual hydraulics) - Rotor mast	R	2024.02.29	C	Discrepancy corrected	No
AMM 62-31-00.4-3	Assembly - Main rotor mast PRE MOD 076120 (single hydraulic) - Rotor mast	R	2024.05.16	I	Information added	No
AMM 62-31-00.6-7	Detailed inspection criteria - Scissors driver - Rotor mast	R	2023.12.21	C	Discrepancy corrected	No
AMM 63-21-00.4-8	Removal / Installation - MGB pump drive (Abex pump) - MGB	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 63-32-00.6-1	Inspection criteria - MGB bar - MGB Bar	R	2024.02.15	C	Discrepancy corrected	Yes
AMM 63-52-00.4-1A	Removal / Installation - Rotor brake ball-type control POST MOD 072816 PRE MOD 073080 - Rotor Brake Control	R	2024.04.17	C	Discrepancy corrected	No
AMM 63-52-00.4-1B	Removal / Installation - Rotor brake ball-type control POST MOD 072816 POST MOD 073080 - Rotor Brake Control	R	2024.04.17	C	Discrepancy corrected	No
AMM 64-10-00.6-6	Inspection Criteria - Edge tab - Tail rotor blades	R	2023.12.21	C	Discrepancy corrected	No
AMM 65-11-00.4-2	Installation - Front section - Tail drive line	R	2024.05.17	I	Information added	No
AMM 65-11-00.6-1	Detailed Inspection Criteria - Front Shaft Section Assembly - Tail drive line	R	2024.01.31	C	Discrepancy corrected	Yes
AMM 65-11-00.6-5	Detailed Inspection criteria - Bearings - Tail drive line	R	2024.02.15	C	Discrepancy corrected	Yes

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 65-11-00.6-13	Visual Inspection Criteria - Rear Shaft Section - Tail drive line	R	2024.05.22	C	Discrepancy corrected	No
AMM 65-11-00.6-27	Check of the tightening torque of the Flexible coupling attachment screws - Tail drive line	N	2024.05.16	R	New document unit	Yes
AMM 65-11-00.6-29	Inspection criteria for the inside of the rear section - Tail drive line	N	2024.04.02	R	New document unit	Yes
AMM 65-21-00.4-2	Installation - TGB - Tail Gear Box	R	2024.05.21	C	Discrepancy corrected	Yes
AMM 65-21-00.6-13	Inspection Criteria - TGB housing - Tail Gear Box	R	2024.03.25	I	Information added	Yes
AMM 65-21-00.6-18	DELETED	D	2018.09.26			No
AMM 65-21-00.6-18	Torque Check - Tail Gear Box	N	2024.03.27	R	New document unit	Yes
AMM 65-21-00.6-24	Inspection criteria - Control lever bushes and yoke lug - Tail Gear Box	R	2024.02.08	I	Information added	Yes
AMM 65-21-00.6-27	Inspection criteria - Control lever (with removal) - Tail Gear Box	R	2024.02.08	I	Information added	Yes
AMM 65-21-00.8-5	Replacement of the control lever bushes - Tail Gear Box	R	2024.02.08	I	Information added	Yes
AMM 67-10-00.4-2	Tear-down / Build-up - Single / Dual control installation - Main Rotor Flight Controls	R	2024.04.25	C	Discrepancy corrected	No
AMM 67-10-00.4-3	Removal / Installation - Flight controls under the transmission deck - Main Rotor Flight Controls	R	2024.05.21	C	Discrepancy corrected	Yes
AMM 67-10-00.6-2	DELETED	D	2019.05.15			No
AMM 67-10-00.6-2	Check of the eccentricity of the rods - Main Rotor Flight Controls	N	2024.02.01	R	New document unit	Yes
AMM 67-10-00.6-3	DELETED	D	2020.12.17			No
AMM 67-10-00.6-3	Clearances and tolerances for the Cyclic Controls - Main Rotor Flight Controls	N	2024.02.01	R	New document unit	Yes
AMM 67-10-00.6-4	DELETED	D	2019.04.18			No
AMM 67-10-00.6-4	Clearances and tolerances for the mixing unit assembly - Main Rotor Flight Controls	N	2024.02.01	R	New document unit	Yes
AMM 67-10-00.6-5	DELETED	D	2018.06.21			No
AMM 67-10-00.6-5	Clearances and tolerances for the Controls on the Transmission Deck - Main Rotor Flight Controls	N	2024.02.01	R	New document unit	Yes
AMM 67-10-00.6-6	DELETED	D	2022.01.21			No
AMM 67-10-00.6-6	Clearances and tolerances for the Collective Control - Main Rotor Flight Controls	N	2024.02.01	R	New document unit	Yes
AMM 67-10-00.8-4	Replacement of the intermediate lever bush - Main Rotor Flight Controls	R	2024.02.15	C	Discrepancy corrected	No
AMM 67-11-00.4-1	Removal / Installation - Cyclic Sticks - Cyclic Control	R	2024.02.12	I	Information added	No
AMM 67-11-00.4-1	Removal / Installation - Cyclic sticks - Cyclic Control	R	2024.02.12	I	Information added	No
AMM 67-21-00.4-4	Removal / Installation - Yaw rods / pedal block / intermediate lever - Tail Rotor Flight Controls	R	2024.02.15	I	Information added	Yes
AMM 67-21-00.6-3	DELETED	D	2022.07.31			No
AMM 67-21-00.6-3	Check - Inspection of the eccentricity of the rods with or without Autopilot - Tail Rotor Flight Controls	N	2024.02.01	R	New document unit	Yes
AMM 67-34-00.4-1	Removal / Installation - Equipped load compensator PRE MOD 074957 - Load compensator	R	2024.02.16	C	Discrepancy corrected	No
AMM 67-34-00.4-1	Removal / Installation - Equipped load compensator POST MOD 074957 - Load compensator	R	2024.02.16	C	Discrepancy corrected	No

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION

Documentary Unit	Title	NRD	Publication Date	Type of change	Reason for update	Maintenance Work Affected
AMM 71-00-00.6-2	Detailed inspection criteria - Splined flange - Power Plant	N	2024.03.22	R	New document unit	Yes
AMM 71-31-00.4-2	Removal / Installation - Rear firewall - Firewall	R	2024.05.17	I	Information added	No
AMM 76-12-01.4-3	Removal / installation - Collective assembly ball-type control - ARRIEL 1D1 Twist Grip	R	2024.05.28	I	Information added	No
AMM 76-12-04.4-1B	Removal / Installation - Twist grip switches POST MOD 074782 - ARRIEL 2D twist grip	R	2024.04.25	C	Discrepancy corrected	No
AMM 76-12-04.5-2	Adjustment - Twist grip load - ARRIEL 2D twist grip	R	2024.04.25	I	Information added	No
AMM 76-21-00.4-1A	Removal / Installation - Fuel shut-off ball-type control POST MOD 072816 PRE MOD 073080 - Fuel shut-off control	R	2024.05.28	I	Information added	No
AMM 76-21-00.4-1B	Removal / Installation - Fuel shut-off ball-type control POST MOD 073080 - Fuel shut-off control	R	2024.05.28	I	Information added	No
AMM 77-00-00.5-1	Functional Tests - Engine Parameter Indicators POST MOD 074302 - Engine parameter indicators	R	2024.04.24	C	Discrepancy corrected	Yes
AMM 77-00-00.5-1	DELETED	D	2019.11.06			No

© Copyright - Airbus

THE DOCUMENT REFERENCE IS AVAILABLE ONLINE. PLEASE CHECK IF THE ONLINE DOCUMENTATION CORRESPONDS TO THE PRINTED VERSION