



## SUMMARY OF CHANGES

MRBR ISSUE O

MRBR has been amended to address the introduction of new kits and design improvements. Main changes included in this issue are: extension of task for lower cable cutter (optional kit), Trakka task applicability correction, starter generator task applicability amendment, deletion of SSI 186002 tasks due to SSI reclassification as other structures.

## SECTION A

No change

## SECTION B

Par.2: updated pag.27 to explicitate the statement about mandatory retirement of components i.a.w. engine and helicopter ALS section.

## SECTION C

## TASK TABLE:

REV CODE (R,N,D)	MRBR TASK REFERENCE	CHANGE DESCRIPTION
R	242000M-07	TASK INTERVAL NOTE MODIFIED TO INCLUDE NEW STARTER GEN. P/Ns.
R	334200M-07	TASK APPLICABILITY AMENDED.
R	334200M-08	TASK APPLICABILITY AMENDED.
R	334200M-10	TASK APPLICABILITY AMENDED.
R	334200M-12	TASK APPLICABILITY AMENDED.
R	954000M-01	TASK APPLICABILITY AMENDED TO INCLUDE INSPECTION OF LOWER CUTTER (OPTIONAL INSTALLATION)

## SECTION D

## TASK TABLE:

REV CODE (R,N,D)	MRBR TASK REFERENCE	CHANGE DESCRIPTION
D	186002S-01	TASK DELETED. SSI RECLASSIFIED AS OTHER STRUCTURES SIMILARLY OTHER VIBRATION PASSIVE ATTENUATION ASSIES.
D	186002S-02	TASK DELETED. SSI RECLASSIFIED AS OTHER STRUCTURES SIMILARLY OTHER VIBRATION PASSIVE ATTENUATION ASSIES.
R	259105S-01	TASK SOURCE AMENDED: ADDED ACCIDENTAL DAMAGE.
R	521103S-01	TASK SOURCE AMENDED: ADDED ACCIDENTAL DAMAGE.
R	521301S-01	TASK TITLE MINOR CHANGE (SPECIFIED "VISIBLE") AND TASK SOURCE AMENDED ADDING ACCIDENTAL DAMAGE.

## SECTION E

No change

## SECTION F

No change

## SECTION G

No change

## APPENDIXES

- Appendix 3: Updated list of ISC and WG participants
- Appendix 6: Update list of MSI, SSI and Other structures
- Appendix 7: Update list of deleted tasks