

EASA AD NO. 2021-0041, NEW ISSUE | ATA 52 - DOORS - PLACARDS - INSTALLATION - ROTORCRAFT FLIGHT MANUAL - SECTION EMERGENCY PROCEDURES - AMENDMENT

Aeronet Galaxy aerospace > Modifications > Edit - Google Chrome

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft_configuration&mode=edit&template=no&ope...

AD/SB ID: 8143 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

Type: ADS Repetitive

Reference/Number: ATA 52 - DOORS - PLACARDS - INSTALLATION - ROTORCRAFT FLIGHT MANUAL - SECTION EMERGENCY PROCEDURES - AMENDMENT

Title/Subject: EASA AD NO. 2021-0041, NEW ISSUE

Version No:

Reason For Raising:

URL:

Date: -- -- -- --

Tolerance: 0 % (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
		8143-2108.pdf

EASA AD NO. 2021-0041, NEW ISSUE | ATA 52 - DOORS - PLACARDS - INSTALLATION - ROTORCRAFT FLIGHT MANUAL - SECTION EMERGENCY PROCEDURES - AMENDMENT

Aeronet Galaxy aerospace > Modifications > Edit - Google Chrome

galaxy aerospace.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft_configuration&mode=edit&template=no&ope...

AD/SB ID: 8143 Close Update Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Model	Based On	Period	Warning	Warning Unit
	AS365N3		-	0	