



LOG CARD

Section 1

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.

Chapter n° 64
Part n°

DESCRIPTION (1) TAIL ROTOR ASSY.	P/N (2) 3G6420A00133	S/N (3) R396	MANUFACTURER NAME (4) AGUSTA	ASSEMBLY DATE (5) OCTOBER 09	RETIREMENT LIFE (6) ON CONDITION
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	DATE OF CHANGE (10)	RETIREMENT LIFE (11)

NOTES (12)

ASSEMBLY HISTORICAL RECORD

INSTALLATION							REMOVAL							
DATE (13)	A/C		ASSY			ORGANIZATION (19)	STAMP AND SIGNATURE (20)	DATE (21)	A/C TOTAL TIME (22)	ASSY		REASON OF REMOVAL (25)	ORGANIZATION (26)	STAMP AND SIGNATURE (27)
	R. MARKS (14)	N/C (15)	TOTAL TIME (16)	TOTAL TIME (17)	TIME SINCE OH (18)					TOTAL TIME (23)	TIME SINCE OH (24)			
DEC. 09		31289	00.00	00.00	NEW	AGUSTA								



LOG CARD

Section 2

Chapter n° 64
 Part n°

NOTICE: WHEN THIS ASSY IS RETURNED FOR ANY REASON TO AN AGUSTA GROUP FACILITY, PLEASE SEND THIS FORM UPDATED.
 REF. P/N: 3G6420A00133 S/N: R396

LIMITED LIFE COMPONENTS INSTALLED ON ASSY

COMPONENT DATA				INSTALLATION				REMOVAL			
DESCRIPTION (28)	P/N (29)	S/N (30)	RETIREMENT LIFE (31)	ASSY TOTAL TIME (32)	COMP. TOTAL TIME (33)	COMP. TIME SINCE OH (34)	STAMP AND SIGNATURE (35)	ASSY TOTAL TIME (36)	COMP. TOTAL TIME (37)	COMP. TIME SINCE OH (38)	STAMP AND SIGNATURE (39)
DAMPER BRACKET	3G6420A00832	R1439	4 Years Insp.	00.00	00.00	NEW	A1 262				
DAMPER BRACKET	3G6420A00832	R1438	4 Years Insp.	00.00	00.00	NEW	A1 262				
DAMPER BRACKET	3G6420A00832	R1437	4 Years Insp.	00.00	00.00	NEW	A1 262				
DAMPER BRACKET	3G6420A00832	R1436	4 Years Insp.	00.00	00.00	NEW	A1 262				
TAIL ROTOR HUB ASSY RLO34	3G6420A00332	R396	7500 FH	00.00	00.00	NEW	A1 262				
			11250 FH or 67500 LDGS								