

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 09.11.2021
<b>REFERENCE NO.:</b> CAMO/MEMO/2021/90	

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	CAAM	CAN 013/2021 NEW ISSUE	30.10.2021	ALL OPERATORS IN MALAYSIA	NOTICE OF EXTENSION TO THE APPLICABILITY DATE FOR PARAGRAPHS 2.5 AND 15 OF CAD 6805 - AIRCRAFT MASS AND BALANCE PROGRAMME	<a href="#">1</a>
2.	CAAM	AI 14/2021 NEW ISSUE	02.11.2021	ALL OPERATORS IN MALAYSIA	POLICY ON REPATRIATION FLIGHTS	<a href="#">2</a>
3.	LEONARDO	MANUAL NO. MAN-8G6320G01033 REV. A	23.09.2021	AW189	TOOL KIT, MGB DRIVE SEAL REPLACEMENT P/N 8G6320G01033	<a href="#">3</a>
4.	LEONARDO	MANUAL NO. MAN-8G2590G00131 REV. A	22.09.2021	AW189	ADAPTER, DUAL RSQ HST OPERATOR CP P/N 8G2590G00131	<a href="#">4</a>

5.	LEONARDO	MANUAL NO. MAN-3G6305G26631 REV. A	27.09.2021	AW189	PIN, MGB ANTI-TORQUE INSTALLATION KIT P/N 3G6305G26631	<a href="#">5</a>
6.	LEONARDO	MANUAL NO. MAN-8G4900G00531 REV. A	27.09.2021	AW189	ADAPTER ASSY, WASHING APU LINE P/N 8G4900G00531	<a href="#">6</a>
7.	LEONARDO	MANUAL NO. MAN-8G2592G00132 REV. A	23.09.2021	AW189	LOAD INDICATOR TEST CABLE P/N 8G2592G00132	<a href="#">7</a>
8.	LEONARDO	MANUAL NO. MAN-8G2420G03431 REV. A	28.09.2021	AW189	DCGU FIPS TEST CONNECTORS P/N 8G2420G03431	<a href="#">8</a>
9.	LEONARDO	MANUAL NO. MAN-3G2405G00231 REV. A	22.09.2021	AW189	AUXILIARY CABLE P/N 3G2405G00231	<a href="#">9</a>
10.	FAA	SAIB AIR-21-18 NEW ISSUE	02.11.2021	ALL OPERATORS IN MALAYSIA	RISK OF POTENTIAL ADVERSE EFFECTS ON RADIO ALTIMETER	<a href="#">10</a>
11.	LEONARDO	TMI NO. 139-549 NEW ISSUE	29.10.2021	AW139	EROSION SHIELD (TAIL ROTOR BLADE ASSEMBLY) - REPLACEMENT (REMOVE AND INSTALL A NEW ITEM)	<a href="#">11</a>
12.	LEONARDO	BASIC ISSUE	01.10.2020	AW139	A/C RECHARGE STATION AIR- NEX P/N GB983-970-500	<a href="#">12</a>

13.	LEONARDO	MANUAL NO. MAN-3G5305G00332 REV. A	27.09.2021	AW139	SLING, FWD SLIDING COWLING LIFTING P/N 3G5305G00332	<a href="#">13</a>
14.	LEONARDO	MANUAL NO. MAN-3G6305G26631 REV. A	27.09.2021	AW139	PIN, MGB ANTI-TORQUE INSTALLATION KIT P/N 3G6305G26631	<a href="#">14</a>
15.	LEONARDO	MANUAL NO. MAN-3G6505G00831 REV. A	28.09.2021	AW139	TROLLEY ADAPTER, TGB SUPPORT P/N 3G6505G00831	<a href="#">15</a>
16.	LEONARDO	MANUAL NO. MAN-3G6505G01751 REV. A	27.09.2021	AW139	BEARING SUPPORT, FLANGES PROTECTION P/N 3G6505G01751	<a href="#">16</a>
17.	LEONARDO	MANUAL NO. MAN-3G6505G00151 REV. A	27.09.2021	AW139	EYEBOLT, TAIL GEARBOX LIFTING P/N 3G6505G00151	<a href="#">17</a>
18.	LEONARDO	MANUAL NO. MAN-8G2592G00132 REV. A	23.09.2021	AW139	LOAD INDICATOR TEST CABLE P/N 8G2592G00132	<a href="#">18</a>
19.	LEONARDO	MANUAL NO. MAN-3G2405G00231 REV. A	22.09.2021	AW139	AUXILIARY CABLE P/N 3G2405G00231	<a href="#">19</a>
20.	LEONARDO	MANUAL NO. MAN-3G6505G00331 REV. A	27.09.2021	AW139	BLANK KIT, IGB / TGB P/N 3G6505G00331	<a href="#">20</a>
21.	BELL TEXTRON	BHT-429-FMS-7 REVISION 1	29.10.2021	429	COMBINED COCKPIT VOICE/FLIGHT DATA RECORDER	<a href="#">21</a>
22.	BELL TEXTRON	BHT-429-FMS-19 REVISION 6	28.10.2021	429	GARMIN GTN 750/650 NAV/COM/GPS AND GTX 33H ES TRANSPONDER	<a href="#">22</a>
23.	BELL TEXTRON	BHT-429-FMS-50 REVISION 2	28.10.2021	429	STANDBY ATTITUDE MODULE KIT	<a href="#">23</a>

24.	BELL TEXTRON	BHT-429-FMS-53 REVISION 2	28.10.2021	429	TRANSPONDER GARMIN GTX 345R	<a href="#">24</a>
-----	-----------------	------------------------------	------------	-----	--------------------------------	--------------------

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**NUR NABILLA MOHD HASNAN  
TECHNICAL PUBLICATION,  
CAMO DEPARTMENT,  
GALAXY AEROSPACE (M) SDN. BHD.**