

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

**TO:** GAM AMO Dept, GAM CAMO Dept. **FROM:** Technical Publication

**CC:** GAM AM, GAM QAM **DATE:** 29.11.2021

REFERENCE NO.: CAMO/MEMO/2021/95

Dear all,

Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	TEXTRON	MTL-32-02 REVISION 1	17.11.2021	B300	LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT	1
2.	PRATT AND WHITNEY CANADA	REV. 27.0	08.11.2021	PT6C-67C	ENGINE MAINTENANCE MANUAL DOC. REF.: 3045332	2
3.	LEONARDO	SIL NO. S-GEN-21-011 NEW ISSUE	19.11.2021	ALL LEONARDO PRODUCTS	ENGINEERING SERVICES FOUNDATION (ESF) ANNOUNCEMENT	<u>3</u>
4	TEXTRON	TEMPORARY CHANGE 13	JUNE 2021	B300	PILOT'S OPERATING HANDBOOK AND FAA APPROVED TEMPORARY CHANGE - ADDED FMS LIMITATIONS FOR TEMPERATURE COMPENSATION IN SECTION 2 - LIMITATIONS	4



5.	TEXTRON	ME - TP-0028 NEW ISSUE	NOV 2021	B300	ATA 00 - CABIN AND COCKPIT NOISE LEVELS, ATA 00 - OVER FLY NOISE LEVELS, ATA 21 - ENVIRONMENTAL BLEED AIR BYPASS VALVE BUTTERFLY, ATA 24 - STARTER GENERATOR RELIABILITY IMPROVEMENT, ATA 30 - TYPE IV DE-ICING FLUIDS, ATA 54 - TURTLE BACK FASTENERS, ATA 76 - PEDESTAL ENGINE CONTROL SWITCH LOCATIONS AND IDENTIFICATION ATA 76 - ADJUSTMENT OF POWER LEVER QUADRANT MICRO SWITCHES	<u>5</u>
6.	CAAM	AI 17/2021 NEW ISSUE	26.11.2021	ALL OPERATORS IN MALAYSIA	USAGE OF DEFINED ATS ROUTES WITHIN THE SIMFEROPOL FIR	<u>6</u>
7.	CAAM	SI 07/2021 NEW ISSUE	26.11.2021	ALL OPERATORS IN MALAYSIA	HARMFUL INTERFERENCE TO GLOBAL NAVIGATION SATELLITE SYSTEM (GNSS) AND ITS IMPACTS ON FLIGHT OPERATIONS	<u>7</u>

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

Thank you and stay safe!

NUR NABILLA MOHD HASNAN **TECHNICAL PUBLICATION**,

CAMO DEPARTMENT,

GALAXY AEROSPACE (M) SDN. BHD.