

## CONTINUING AIRWORTHINESS MANAGEMENT OFFICE MEMO

<b>TO:</b> GAM AMO Dept, GAM CAMO Dept.	<b>FROM:</b> Technical Publication
<b>CC:</b> GAM AM, GAM QAM	<b>DATE:</b> 22.11.2021
<b>REFERENCE NO.:</b> CAMO/MEMO/2021/93	

Dear all,


Please be informed that the following publication/s has/have been issued and uploaded to GAM server. Kindly refer all publication below for your acknowledgement and to take action.

NO.	VENDOR	REV. NO.	ISSUE/REV DATE	EFFECTIVITY	SUBJECT	LINK TO GAM SERVER
1.	TEXTRON	MTL-32-02 REVISION 1	17.11.2021	B300	LANDING GEAR- MAIN LANDING GEAR TORQUE- KNEE PINS REPLACEMENT	<a href="#">1</a>
2.	PRATT AND WHITNEY CANADA	REV. 27.0	08.11.2021	PT6C-67C	ENGINE MAINTENANCE MANUAL DOC. REF.: 3045332	<a href="#">2</a>
3.	LEONARDO	SIL NO. S-GEN-21-011 NEW ISSUE	19.11.2021	ALL LEONARDO PRODUCTS	ENGINEERING SERVICES FOUNDATION (ESF) ANNOUNCEMENT	<a href="#">3</a>
4	TEXTRON	TEMPORARY CHANGE 13	JUNE 2021	B300	PILOT'S OPERATING HANDBOOK AND FAA APPROVED TEMPORARY CHANGE - ADDED FMS LIMITATIONS FOR TEMPERATURE COMPENSATION IN SECTION 2 - LIMITATIONS	<a href="#">4</a>

5.	TEXTRON	ME - TP-0028 NEW ISSUE	NOV 2021	B300	ATA 00 - CABIN AND COCKPIT NOISE LEVELS, ATA 00 - OVER FLY NOISE LEVELS, ATA 21 - ENVIRONMENTAL BLEED AIR BYPASS VALVE BUTTERFLY, ATA 24 - STARTER GENERATOR RELIABILITY IMPROVEMENT, ATA 30 - TYPE IV DE-ICING FLUIDS, ATA 54 - TURTLE BACK FASTENERS, ATA 76 - PEDESTAL ENGINE CONTROL SWITCH LOCATIONS AND IDENTIFICATION ATA 76 - ADJUSTMENT OF POWER LEVER QUADRANT MICRO SWITCHES	<u>5</u>
----	---------	---------------------------	----------	------	--	----------

Please be advised, all engineering and CAMO staff shall update their working computer (control computer) effected immediately.

*Thank you and stay safe!*



**NUR NABILLA MOHD HASNAN**  
**TECHNICAL PUBLICATION,**  
**CAMO DEPARTMENT,**  
**GALAXY AEROSPACE (M) SDN. BHD.**