



LOG CARD

Section 1

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter


31

DESCRIPTION (1) CRASH POSITION INDICATOR	P/N (2) 503-16GPS	S/N (3) 480	MANUFACTURER NAME (4) HR-SMITH	ASSEMBLY DATE (5) 05/2019	RETIREMENT LIFE / TIME LIMITS (6) ON CONDITION
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)
	P/N (7)	S/N (8)	MANUFACTURER NAME (9)	ASSEMBLY DATE (10)	RETIREMENT LIFE / TIME LIMITS (11)

NOTE

ASSEMBLY HISTORICAL RECORD

INSTALLATION						REMOVAL							
DATE (12)	A/C		ASSY			ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	A/C		ASSY		REASON OF REMOVAL (24)	ORGANIZATION, STAMP AND SIGNATURE (25)
	R. MARKS (13)	TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH (17)	TOTAL FLIGHT HOURS (20)			ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22)	TIME SINCE OH (23)			
		TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS SINCE OH (17)	TOTAL LANDINGS (20)			ACTUAL TOTAL LANDINGS (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LANDINGS SINCE OH (23)			
S/N (14)	TOTAL LIFTS/CYCLES (15)	TOTAL LIFTS/CYCLES (16)	LIFTS/CYCLES SINCE OH (17)	TOTAL LIFTS/CYCLES (20)	ACTUAL TOTAL LIFTS/CYCLES (21)	TOTAL LANDS WITH PENALTY FACTOR (22)	LIFTS/CYCLES SINCE OH (23)						
05/2019	N861AH 31867	01.40	00.00	NEW	Leonardo Helicopters	15 Dec 2021	203002 2028:38	NEW	ELT BATTERY REPLACEMENT	Aramco			



LOG CARD

Section 2

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

ATA Chapter _____

31

COMPONENTS INSTALLED ON ASSY

ASSY P/N (26)

503-16GPS

ASSY S/N (27)

480

COMPONENT DATA

INSTALLATION


REMOVAL

DESCRIPTION (28)	P/N (29)	MANUFACTURING DATE (31)	ASSY				COMPONENT				ASSY				COMPONENT			
			TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY FACTOR (40)	TIME SINCE OH (41)	DATE (42)		
			TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE (37)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)	TOTAL LANDINGS (38)	TOTAL LANDINGS (39)	TOTAL LANDINGS WITH PENALTY FACTOR (40)	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)		
	S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	LIFTS/CYCLES SINCE OH (35)		TOTAL LIFTS/CYCLES (38)	TOTAL LIFTS/CYCLES (39)		TOTAL LIFTS/CYCLES SINCE OH (41)								
CPI Beacon battery (Li-SO2)	A01577	05/2019	00.00	00.00	NEW	05/2019	2028:38	/	/	NEW	26/05/22							
	==	5 Y I/D or EXP./D 05/2024																
CPI BATTERY	A01577	05/2022	2028:38	/	NEW	26/05/22												
	is/n: 130252	05/2027	/	/	/													

A1
286

26/05/22
HRS
156 JK

HRS
156 JK



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 3

ATA Chapter

31

ASSEMBLY ACTIVITY HISTORY

ASSY P/N (44)

503-16GPS

ASSYS/N (45)

480

DATE (46)	TOTAL HOURS (47)	TASKS (48)	ACTIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)	
	TOTAL LANDINGS (47)					
	TOTAL LIFTS/CYCLES (47)					
26/05/22	2028:38 — —	REPAIR	BATTERY, GASKET & SPECIAL BOLT REPLACEMENT.	HR SMITH	<table border="1"><tr><td>HRS 156</td></tr></table> JK	HRS 156
HRS 156						

