

TIC-AW139-21-0284

EASA - AW139 EMERGENCY AIRWORTHINESS DIRECTIVES

ATA 78- EXHAUST - TAILPIPE ASSEMBLY - INSPECTION/REPAIR/REPLACEMENT

EAD NO. 2006-0360-E, NEW ISSUE

AD/SB ID: 16




General | Config List | Aircraft List | Task List | Linked To | BOM

Type : ADS Repetitive

























Reference/Number: ATA 78 - EXHAUST - TAILPIPE ASSEMBLY -
INSPECTION/REPAIR/REPLACEMENT

Title/Subject: EASA AD NO 2006-0360-E

AD/SB ID: 16

 Close
  Update
  Save & Close

General | Config List | Aircraft List | Task List | Linked To | BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BFU	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	
	9M-JPM	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMA	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMB	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMC	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMD	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	
	9M-PME	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-PMF	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-SAAS	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	
	9M-SBH	Airframe Hours	-	Hours	0	-	-	NOT APPLICABLE	
	9M-YPG	Not Applicable	-		0	-	-	NOT APPLICABLE	
	9M-YTL	Not Applicable	-		0	-	-	NOT APPLICABLE	