

AIRWORTHINESS DIRECTIVEreleased by **DIRECTION GENERALE DE L'AVIATION CIVILE***Inspection and/or modifications described below are mandatory. No person may operate a product to which this**Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive*

Translation of 'Consigne de Navigabilité'

ref.: **84-045-022(B)R4**In case of any difficulty, reference should
be made to the French original issue.**EUROCOPTER FRANCE****AS 355 Helicopters**

Tail rotor blade spars

The present Airworthiness Directive applies to AS 355 helicopters, all
versions fitted with tail rotor blades assemblies P/N :

- 350A12.0030)	
- 355A12.0031	(all dash
- 355A12.0040)	numbers
- 355A12.0050	(

Further to the discovery in service of several cases of cracks at the blade
root on the spar of tail rotor blade assemblies possibly resulting in a
severe unbalance, the following measures have been rendered mandatory :

- 1/ From the effective date of the present Airworthiness Directive and at
intervals not exceeding 30 flight hours, without removing any
components, perform the check specified in paragraph 1C(1) of the
referenced EUROCOPTER FRANCE AS 355 Service Bulletin N° 05-06
Revision 6.
- 2/ Should abnormal noise be detected during the check required by
paragraph 1/ above, before resuming flights, perform the check with
component removal specified in paragraph 1C(2) of the referenced
Service Bulletin.
- 3/ Each time the laminate half-bearings are replaced and in the event of
balancing difficulties or of an incident which could adversely affect
the tail rotor, perform the check with component removal specified in
paragraph 1C(2) of the referenced Service Bulletin.

.../...

February 02, 1994

EUROCOPTER FRANCE
AS 355 Helicopters**84-045-022(B)R4**

Ref. : EUROCOPTER FRANCE AS 355 Service Bulletin N°05-06 Rev.6.

The present Revision 4 replaces the Airworthiness Directive 84-045-022(B)R3 dated December 23, 1992.

EFFECTIVE DATES :

Original AD and Rev. 1 & 2 : APRIL 4, 1984
Revision 3 : JANUARY 02, 1993
Revision 4 : FEVRIER 12, 1994