**BUREAU VERITAS** 

## **AIRWORTHINESS DIRECTIVE**

released by DIRECTION GÉNÉRALE DE L'AVIATION CIVILE

Inspections and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of "Consigne de Navigabilité" Réf.: 89-082-038(B) In case of any difficulty, reference should be made to the French original issue.

## **AEROSPATIALE AS 355 E helicopters**

Spherical thrust bearings P/N 704A 33-633-109

This Airworthiness Directive covers AEROSPATIALE AS 355 E helicopters.

Subsequent to problems involving excessive control loads without hydraulic assistance encountered in operation at temperatures below minus 30 degrees centigrade, the use of an aircraft fitted with spherical thrust bearings P/N 704 A 33-633-109 is prohibited at temperatures below minus 25 degrees centigrade, at the effective date of this directive.

## Remarks:

- This prohibition forms the subject of a revision of the Flight Manual and of Chapter 5.99 of the Master Servicing Recommendations.
- When spherical thrust bearings P/N 704 A 33-633-028 (or 579045) or P/N 704 A 33-633-030 are installed, the aircraft may be used in temperatures as low as minus 40 degrees centigrade.

Cf.: AEROSPATIALE Telex Service nº 01-25

**EFFECTIVE DATE: MAY 27TH 1989** 

May 17,1989 AEROSPATIALE AS 355 E helicopters Ref.: 89-082-038(B)