BUREAU VERITAS

AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

inspections and/or modifications described below are mandatory. No person may operate a product to which this

Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.

Translation of 'Consigne de Navigabilité'
Réf.: 90-061-040(B)

In case of any difficulty, reference should be made to the French original Issue.

AEROSPATIALE AS 355 helicopters

Fuel lines

The present Airworthiness Directive applies to AEROSPATIALE AS 355 helicopters, versions E, F, F1 and F2 fitted with the fuel flow meter system, subject of modification AMS 350 A 07.0791.

Subsequent to reports of leaks encountered in service on certain batches of LH engine fuel supply lines (AEROSPATIALE P/N 704 A 34.416.031, manufacturer's P/N: PRECISAVIA 80472) installed on the aircraft in question, the following measures are rendered mandatory:

- 1. Upon receipt of this Directive, identify the batch and the date of manufacture of the incriminated fuel line.
- If the line is included in the following list, replace it with a line which is not in the list as soon as possible and before May 1, 1990 at the latest.

Lot NR 7445 -	Date of manufacture =	October 1988
Lot NR 7446 -	Date of manufacture =	October 1988
Lot NR 7571 -	Date of manufacture =	December 1988
Lot NR 7572 -	Date of manufacture =	December 1988
Lot NR 7806 -	Date of manufacture =	April 1989
Lot NR 7975 -	Date of manufacture =	June 1989

All lines listed above must be returned to AEROSPATIALE.

Ref.: AEROSPATIALE Telex Service Nº 01.28

EFFECTIVE DATE : UPON RECEIPT

March 21, 90	AEROSPATIALE AS 355 helicopters	90-061-040(B)
	<u>.</u>	