

# AIRWORTHINESS DIRECTIVE

released by DIRECTION GENERALE DE L'AVIATION CIVILE

*Inspection and/or modifications described below are mandatory. No person may operate a product to which this Airworthiness Directive applies except in accordance with the requirements of this Airworthiness Directive.*

Translation of 'Consigne de Navigabilité' ref. : 92-144-061(B)  
In case of any difficulty, reference should be made to the French original issue.

## EUROCOPTER FRANCE

### AS 350 helicopters

"JOLLIET" Emergency Locator Transmitter Antenna

This Airworthiness Directive applies to AS 350 helicopters, versions B, BA, B1, B2 and D, fitted with the "JOLLIET" emergency locator transmitter system, not modified per AMS 350A.07.2492.

In order to improve the antenna resistance to vibrations and prevent any risk of loss in flight, the following measures are rendered mandatory :

- Within the next 400 flying hours without exceeding April 1, 1993, apply EUROCOPTER AS 350 Service Bulletin N° 25.45 (if this has not already been done).

---

REF. : EUROCOPTER AS 350 Service Bulletin N° 25.45

---

EFFECTIVE DATE : JULY 18, 1992

e/W

July 08, 1992

EUROCOPTER FRANCE  
AS 350 helicopters

92-144-061(B)