
ALERT TELEX – AIRBUS HELICOPTERS – ALERT TELEX – AIRBUS HELICOPTERS – ALERT TELEX



T.F.S. No.00000292 dated October 11, 2023 Airbus Helicopters Etablissement de Marignane Direction Ventes et Relations Client 13725 MARIGNANE CEDEX FRANCE



1.A.2. Non-installed equipment:

Not applicable.

L

1.B. ASSOCIATED REQUIREMENTS

Not applicable.

Export Control: US Export Control - No US content. This Item does not contain any U.S. origin ITAR or EAR content. FR Export Control - Not Listed. This Item is not listed against the EC regulations in the EU/FR.

Page 1 of 2

ALERT TELEX – AIRBUS HELICOPTERS – ALERT TELEX – AIRBUS HELICOPTERS – ALERT TELEX

Export Control: US_EC_NoUScontent - FR_EC_NotListed



T.F.S. No.00000292 dated October 11, 2023 Airbus Helicopters Etablissement de Marignane Direction Ventes et Relations Client 13725 MARIGNANE CEDEX FRANCE

1.C. REASON

I

Revision 0:

To declare spherical thrust bearings, P/No. 7050A3622036, with serial numbers listed in paragraph 1.A., unfit for flight.

Revision 1:

Revision 1 of this Alert Telex informs that this Alert Telex is no longer applicable following the integration of its contents in the documentation: Airworthiness Limitation Section (ALS) RN015 of 2006.12.08.

1.D. DESCRIPTION

Not applicable.

1.E. COMPLIANCE

Not applicable.

2. ACCOMPLISHMENT INSTRUCTIONS

2.A. GENERAL

Not applicable.

2.B. OPERATIONAL PROCEDURE

Not applicable.

2.C. IDENTIFICATION

Not applicable.

Page 2 of 2

ALERT TELEX – AIRBUS HELICOPTERS – ALERT TELEX – AIRBUS HELICOPTERS – ALERT TELEX