

81-17-01

Aeronet Galaxy aerospace2 > Modifications > Update - Mozilla Firefox

https://galaxy aerospace2.aeronet.nz/index.html

AD/SB ID: 3769

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: ADS Repetitive

Reference/Number: STARTING VIBRATORS ASSEMBLIES - 5 - CONTACT
BUSHING STARTER VIBRATORS (BENDIX SB 614)

Title/Subject: 81-17-01

Version No:

Reason For Raising:

URL:

Date: -- -- --

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document:

	Title	Filename
	81-17-01	3769-1506.pdf

AD/SB ID: 3769

Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status	
	9M-BGG	Date (Days)	-	Days	0	-	-	NOT APPLICABLE	

