

GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/22/036
Subject	LEONARDO HELICOPTERS - AW139 IETP
Revision No.	: ISSUE 41, UPDATE 002
Revision Date	: 16 NOVEMBER 2022

You may click Google Drive link below to view and download the attachment.

1. [AW139 IETP, UPDATE 002](#)

39-A-ACCP-00-X	Corrosion Control Publication	2022-06-28
39-A-IPCP-00-X	Ice Protection Control Publication	2018-09-26
39-A-AFIP-00-X	Fault Isolation Publication	2022-06-28
39-A-AMDI-00-X	Material Data Information	2022-06-28
CSPP-A-CSPP-00-X	Common Standard Practices Publication	2022-10-18
39-A-AMP-00-X	Maintenance Publication	2022-06-28
39-A-AMPI-00-P (EASA)	Maintenance Planning Information (EASA)	2022-09-08
39-A-AMPI-00-P (FAA)	Maintenance Planning Information (FAA)	2022-09-08
39-A-AMPI-00-P (IAC AR)	Maintenance Planning Information (IAC AR)	2017-01-26
39-A-AMPI-00-P (FATA)	Maintenance Planning Information (FATA)	2022-09-08
CSRP-A-CSRP-00-X	Common Structural Repair Publication	2022-11-16
39-A-ASRP-00-X	Structural Repair Publication	2022-06-28
39-A-AWDP-00-X	Wiring Data Publication	2022-06-28
39-A-CR&OP-00-X	Component Repair & Overhaul Publication	2022-06-28
39-A-IPD-00-X	Illustrated Parts Data Publication	2022-06-28
39-A-ITEP-00-X	Illustrated Tools and Equipment Publication	2022-06-28

© 2022 ALL RIGHTS RESERVED

IETP - 41st Issue: 2022-06-28

PUBLICATION CODE 502500016y IETP Update: 2022-11-16

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.