

GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/22/040
Subject	: PRATT AND WHITNEY CANADA - PW206C MAINTENANCE MANUAL MANUAL PART NO.: 3043322
Revision No.	: REV. 46
Revision Date	: 05 DECEMBER 2022

You may click Google Drive link below to view and download the attachment.

1. [PW06C MAINTENANCE MANUAL, REV. 46](#)

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.

Engine Model(s): PW200

HIGHLIGHTS

Revision	CH/SE/SU	Pageblock Title	Description of Change
46.0	Front	LIST OF CHAPTER/SECTION/SUBJECTS	The chapter section subjects list has been updated to add 05-20-01 (Inspections/Maintenance Intervals for Environments).
46.0	Front	SPECIAL TOOLS/FIXTURES AND EQUIPMENT	The special tools list has been updated to add adapter (PWC64059), gage (PWC64327), gage (PWC64598), holding fixture (PWC65444) and gage (PWC65845).
46.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	The hot section inspection procedure has been revised to update the instructions for HSI.
46.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	The procedure for recommended maintenance tasks based on operating environment has been deleted.
46.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The general instructions procedure has been added.
46.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The definitions procedure and graphics have been added.
46.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The scheduled inspections/maintenance intervals procedure has been added.
46.0	05.50.00 Unscheduled Maintenance Checks	05-50-00 UNSCHEDULED MAINTENANCE CHECKS	The non-preserved engine procedure has been revised to add the

Revision	CH/SE/SU	Pageblock Title	Description of Change
			binding instructions for 8 to 29 days and to delete the binding instructions for 29 to 90 days.
46.0	72.00.00 Engine General	72-00-00 ENGINE, GENERAL - INSPECTION	The table for compressor inlet case inspection has been revised to add chapter 72-21-00 reference.
46.0	72.00.00 Engine General	72-00-00 ENGINE, GENERAL - DESCRIPTION AND OPERATION	The table of approved lubricating oils, MIL-PRF-23699 and SAE-AS5780 - type II has been revised to replace oil type from 2389 to 2380 for eastman turbo oil, BP turbo oil, exxon turbo oil and to delete castrol 5000 and turbonycoil 525-2A.
46.0	72.00.30 Hot Section Refurbishment (PW206C (Pre-SB28187))(Heavy Maintenance)	72-00-30 HSI (PW206C (PRE-SB28187)) - HEAVY MAINTENANCE	The inspection procedure of the CT disk tip-clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.00.30 Hot Section Refurbishment (PW206C (Pre-SB28187))(Heavy Maintenance)	72-00-30 HSI (PW206C (PRE-SB28187)) - HEAVY MAINTENANCE	The inspection procedure of the CT disk tip clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.00.31 Hot Section Refurbishment (PW206C (Post-SB28187) and PW207C)(Heavy Maintenance)	72-00-31 HSI (PW206C (Post-SB28187), PW207C) - HEAVY MAINTENANCE	The inspection procedure of the CT disk tip-clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.00.31 Hot Section	72-00-31 HSI (PW206C (Post-	The inspection procedure

Revision	CH/SE/SU	Pageblock Title	Description of Change
	Refurbishment (PW206C (Post-SB28187) and PW207C)(Heavy Maintenance)	SB28187), PW207C) - HEAVY MAINTENANCE	of the CT disk tip clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.21.00 Air Inlet	72-21-00 AIR INLET - MAINTENANCE PRACTICES	The compressor inlet case repair procedure has been revised to add instruction for raised material.
46.0	72.21.00 Air Inlet	72-21-00 AIR INLET - INSPECTION/CHECK	The visual inspection procedure of compressor inlet case has been revised.

Engine Model(s): PW200

HIGHLIGHTS

Revision	CH/SE/SU	Pageblock Title	Description of Change
46.0	Front	LIST OF CHAPTER/SECTION/SUBJECTS	The chapter section subjects list has been updated to add 05-20-01 (Inspections/Maintenance Intervals for Environments).
46.0	Front	SPECIAL TOOLS/FIXTURES AND EQUIPMENT	The special tools list has been updated to add adapter (PWC64059), gage (PWC64327), gage (PWC64598), holding fixture (PWC65444) and gage (PWC65845).
46.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	The hot section inspection procedure has been revised to update the instructions for HSI.
46.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	The procedure for recommended maintenance tasks based on operating environment has been deleted.
46.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The general instructions procedure has been added.
46.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The definitions procedure and graphics have been added.
46.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The scheduled inspections/maintenance intervals procedure has been added.
46.0	05.50.00 Unscheduled Maintenance Checks	05-50-00 UNSCHEDULED MAINTENANCE CHECKS	The non-preserved engine procedure has been revised to add the

Revision	CH/SE/SU	Pageblock Title	Description of Change
			binding instructions for 8 to 29 days and to delete the binding instructions for 29 to 90 days.
46.0	72.00.00 Engine General	72-00-00 ENGINE, GENERAL - INSPECTION	The table for compressor inlet case inspection has been revised to add chapter 72-21-00 reference.
46.0	72.00.00 Engine General	72-00-00 ENGINE, GENERAL - DESCRIPTION AND OPERATION	The table of approved lubricating oils, MIL-PRF-23699 and SAE-AS5780 - type II has been revised to replace oil type from 2389 to 2380 for eastman turbo oil, BP turbo oil, exxon turbo oil and to delete castrol 5000 and turbonycoil 525-2A.
46.0	72.00.30 Hot Section Refurbishment (PW206C (Pre-SB28187))(Heavy Maintenance)	72-00-30 HSI (PW206C (PRE-SB28187)) - HEAVY MAINTENANCE	The inspection procedure of the CT disk tip-clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.00.30 Hot Section Refurbishment (PW206C (Pre-SB28187))(Heavy Maintenance)	72-00-30 HSI (PW206C (PRE-SB28187)) - HEAVY MAINTENANCE	The inspection procedure of the CT disk tip clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.00.31 Hot Section Refurbishment (PW206C (Post-SB28187) and PW207C)(Heavy Maintenance)	72-00-31 HSI (PW206C (Post-SB28187), PW207C) - HEAVY MAINTENANCE	The inspection procedure of the CT disk tip-clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.00.31 Hot Section	72-00-31 HSI (PW206C (Post-	The inspection procedure

Revision	CH/SE/SU	Pageblock Title	Description of Change
	Refurbishment (PW206C (Post-SB28187) and PW207C)(Heavy Maintenance)	SB28187), PW207C) - HEAVY MAINTENANCE	of the CT disk tip clearance has been revised to add feeler gage as an alternate to wire gage to measure the tip clearance.
46.0	72.21.00 Air Inlet	72-21-00 AIR INLET - MAINTENANCE PRACTICES	The compressor inlet case repair procedure has been revised to add instruction for raised material.
46.0	72.21.00 Air Inlet	72-21-00 AIR INLET - INSPECTION/CHECK	The visual inspection procedure of compressor inlet case has been revised.