

GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/23/052
Subject	: PRATT AND WHITNEY CANADA - PT6C-67C MAINTENANCE MANUAL
Revision No.	: MANUAL PART NO.: 3045332, REV. 32.0
Revision Date	: 06 NOVEMBER 2023

You may click Google Drive link below to view and download the attachment.

1. [. PT6C-67C MAINTENANCE MANUAL, REV 32.0 DATED 6 NOV 2023](#)

HIGHLIGHTS

Revision	CH/SE/SU	Pageblock Title	Description of Change
32.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB41103 no effect to effect.
32.0	Front	SERVICE BULLETIN LIST	Service Bulletin list has been updated to revise SB4119R4 to SB4119R5.
32.0	05.20.00 Scheduled Maintenance Checks	05-20-00 SCHEDULED MAINTENANCE CHECKS	The steps and guidelines to obtain a recommendation for fleet TBO escalation has been revised to update the TBO request submission in My&PWC Power portal, and to delete the TBO evaluation sample request form.
32.0	05.20.01 Inspections/Maintenance Intervals for Environments	05-20-01 INSPECTIONS/MAINTENANCE INTERVALS FOR ENVIRONMENTS	The table for P&WC recommended engine wash interval based on operating environment has been revised to update the maintenance interval in moderate environment condition for compressor performance recovery wash.
32.0	72.30.04 Gas Generator Case	72-30-04 GAS GENERATOR CASE - MAINTENANCE PRACTICES	The procedure for removal and installation of P2.8 transfer tube has been revised to add pre and post-SB41103 condition for the air bleed check valve. Editorial corrections done.
32.0	74.20.00 Igniters and Ignition Cables	74-20-00 IGNITERS AND IGNITION CABLES - MAINTENANCE PRACTICES	The procedure for inspection of the ignition cables has been revised to delete the retention test instructions and table.

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.