

GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/24/037
Subject	: LEONARDO HELICOPTERS - AW139 INTERACTIVE ELECTRONIC TECHNICAL PUBLICATION (IETP)
Revision No.	: ISSUE 45
Revision Date	: 13 JUNE 2024

You may click Google Drive link below to view and download the attachment.

- [LEONARDO HELICOPTERS - AW139 INTERACTIVE ELECTRONIC TECHNICAL PUBLICATION \(IETP\)](#)

Copies of this publication may be obtained by contacting:

LEONARDO LEONARDO HELICOPTERS

CUSTOMER SUPPORT & SERVICES - ITALY
Via Indipendenza, 2
21019 Sesto Calende (VA) - ITALY
<http://www.leonardo.com> - e-mail: gestpubs@leonardo.com

39-A-ACCP-00-X Corrosion Control Publication 2024-06-13

39-A-IRCP-00-X Ice Protection Control Publication 2022-12-01

39-A-IFCP-00-X Fault Isolation Publication 2024-06-13

39-A-AMD-00-X Material Data Information 2024-06-13

CSPP-A-CSPP-00-X Common Standard Practices Publication 2022-10-30

39-A-AMP-00-X Maintenance Publication 2024-06-13

39-A-AMPI-00-P (EASA) Maintenance Planning Information (EASA) 2024-05-16

39-B-AMPI-00-P (FAA) Maintenance Planning Information (FAA) 2024-05-16

39-C-AMPI-00-P (IAC AR) Maintenance Planning Information (IAC AR) 2017-01-26

39-D-AMPI-00-P (FATA) Maintenance Planning Information (FATA) 2024-05-16

CSRP-A-CSRP-00-X Common Structural Repair Publication 2022-11-16

39-A-ASRP-00-X Structural Repair Publication 2024-06-13

39-A-ANOP-00-X Wiring Data Publication 2024-06-13

39-A-IPD-00-X Illustrated Parts Data Publication 2024-06-13

39-A-ITEP-00-X Illustrated Tools and Equipment Publication 2024-06-13

LEONARDO

AMERIGO 5

AW139 IETP
INTERACTIVE ELECTRONIC TECHNICAL PUBLICATIONS

THIS PUBLICATION IS ISSUED BY LEONARDO S.p.A.

This document contains proprietary data and information and shall not be disclosed, reproduced in whole or in part for any purpose, other than helicopter operation or maintenance, without prior written authorization from Leonardo S.p.A.

This package replaces and supersedes all the previous issues. Upon receipt/download of a new package, the old ones MUST be destroyed/destroyed.

IETP - 45th Issue: 2024-06-13
PUBLICATION CODE: SCS00296y

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.