


GAM PUBLICATION - GOOGLE DRIVE LINK

GD Link No.	: GDLINK/CAMO/24/079
Subject	: PRATT AND WHITNEY CANADA - PT6A-60A MAINTENANCE MANUAL DOC. REF.: P/N 3034342
Revision No.	: REV. 63
Revision Date	: 07.10.2024

You may click Google Drive link below to view and download the attachment.

1. [PT6A-60A MAINTENANCE MANUAL DOC. REF.: P/N 3034342](#)



MyP&WC POWER Light Mode Customer First Center | US & CAN: 1-800-268-8000 | INTL: +8000-268-8000 | Contacts and Locations

MAINTENANCE MANUAL
MODEL(s): PT6A-60A, PT6A-60AG, PT6A-61
Manual Part No. 3034342, ISSUE NO. 63.0, Dated Oct-07-2024

RSVP

HIGHLIGHTS

Revision	CH/SE/SU	Pageblock Title	Description of Change
63.0	72.00.00 Engine	72-00-00 ENGINE, TURBOPROP - INSPECTION	The procedure for unscheduled inspection for overspeed condition has been revised to add the cross-reference for Ng and Np exceedance limits and editorial corrections made.
63.0	72.50.01 Compressor Turbine Stator	72-50-01 COMPRESSOR TURBINE STATOR - MAINTENANCE PRACTICES	The procedure for inspection or check has been revised to update the postal code of the repair address and to remove the receiving area information.
63.0	72.50.03 Power Turbine Interstage	72-50-03 POWER TURBINE INTERSTAGE - MAINTENANCE PRACTICES	The procedure for inspection or check has been revised to update the postal code of the repair address and to remove the receiving area information.
63.0	72.50.04 Power Turbine	72-50-04 POWER TURBINE - MAINTENANCE PRACTICES	The procedure for inspection or check has been revised to update the postal code of the repair address and to remove the receiving area information.
63.0	73.10.05 Simplex Fuel Manifold	73-10-05 SIMPLEX FUEL MANIFOLD - MAINTENANCE PRACTICES	The procedure for installation of fuel manifold adapters has been revised to add the caution for the fuel nozzle tip assemblies, and editorial corrections done in cautions.

Note: Do not hesitate to contact Technical Publication from CAMO department for any further inquiry.