

AC TYPE	AD/SB TYPE	SB TITLE	SB DESCRIPTION	COMPLIANCE TIME	APPLICABILITY	EFFECTIVITY	WORKPACK/ ASB REFERENCE	REMARKS	OPERATOR ACTION	STATUS	ANALYSIS
AW139	AIRFRAME ASB	ASB NO. 139-734, REV A 28 APRIL 2023	ATA 25 – LIFE RAFT INFLATION SYSTEM REPLACEMENT THIS SERVICE BULLETIN IS ISSUED IN ORDER TO REPLACE A SPECIFIC BATCH OF INFLATION SYSTEMS PART OF LIFE RAFT KITS P/N 3G9560F00111, P/N 3G9560F00112 OR P/N 4G2360F00811.	WITHIN AND NOT LATER THAN 300 FLIGHT HOURS OR 1 YEAR WHICHEVER OCCURS FIRST FROM THE FIRST ISSUE DATE OF THIS SERVICE BULLETIN.	NOT APPLICABLE			4 MMH		CLOSED	
AW189	AIRFRAME SB	SB NO. 189-377 28 APRIL 2023	ATA 31 - NR1 AZIMUTH CONNECTIONS RETROMOD THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION ON HOW TO PERFORM THE "NR1 AZIMUTH CONNECTIONS RETROMOD" P/N 8G3130P0111.	OPTIONAL	APPLICABLE	BOE AND BOF		16 MMH	NOT TO BE COMPLIED WITH	CLOSED	SB IS ONLY SUGGESTED IF OPERATOR EXPERIENCED NR1 TAHCOMETER READING PROBLEM
AW189	ENGINE SB	SB NO. 79-0002, REV. 00_00 25 MAY 2023	OIL SYSTEM - GENERAL (79-00-00) - APPROVED OILS THIS SERVICE BULLETIN DESIGNATES LUBRICATION OILS WHICH ARE APPROVED FOR USE IN CT7-2E1 ENGINES AND TO INTRODUCE TURBONYCOIL 600 AS AN APPROVED OIL TO STANDARDIZE MANUAL FORMATTING ACROSS CT7 ENGINE MODELS.	CATEGORY 9: FOR INFORMATION ONLY	APPLICABLE	BOE AND BOF				CLOSED	
AW189	APU SB	SB NO. 342-49-051, ISSUE 001 27 APRIL 2023	UPDATE OF MANDATORY SCHEDULED INSPECTION ON CRITICAL PARTS THE PURPOSES OF THIS MODIFICATION IS TO UPDATE THE MANDATORY SCHEDULED INSPECTION ON CRITICAL PARTS (CHAPTER 4 – AIRWORTHINESS LIMITATIONS IN THE MAINTENANCE MANUALS), THE PURPOSE OF THIS SERVICE BULLETIN IS TO INTRODUCE MODIFICATIONS N°342/419.	CATEGORY 3: RECOMMENDED COMPLIED WITH, AMP UPDATED	APPLICABLE	BOE AND BOF				CLOSED	
AW189	APU SB	SB NO. 342-49-050, ISSUE 001 27 APRIL 2023	INTRODUCTION OF NEW REAR MOUNT REFERENCE THE PURPOSES OF THIS MODIFICATION IS TO INTRODUCE NEW REAR MOUNT REFERENCE TO IMPROVE THE INTERFACE BETWEEN THE CARRIER AND THE APU. THE PURPOSE OF THIS SERVICE BULLETIN IS TO INTRODUCE MODIFICATIONS N°342/419.	CATEGORY 5: SPARE PARTS INFORMATION	APPLICABLE	BOE AND BOF				CLOSED	
AW189	APU SB	SB NO. 342-49-049, ISSUE 001 27 APRIL 2023	UPDATE OF REMOVAL AND INSTALLATION PROCEDURES FOLLOWING THE RELEASE OF SB 342-49-048 THE PURPOSES OF THIS MODIFICATION IS TO INTRODUCE THE MODIFICATION OF THE FOLLOWING PROCEDURES FOR APPLICABLE TO OPERATORS AND MRO CENTERS: REMOVAL OF THE IGNITION MANIFOLD, INSTALLATION OF THE IGNITION MANIFOLD, REMOVAL OF THE BURNER MANIFOLD, INSTALLATION OF THE BURNERS MANIFOLD, INSTALLATION OF THE IGNITER PLUGS, REMOVAL OF THE DRAIN VALVE, INSTALLATION OF THE DRAIN VALVE, REMOVAL OF THE EXHAUST GAS TEMPERATURE PROBE T4-1, INSTALLATION OF THE EXHAUST GAS TEMPERATURE PROBE T4-1, REMOVAL OF THE EXHAUST GAS TEMPERATURE PROBE T4-2 AND INSTALLATION OF THE EXHAUST GAS TEMPERATURE PROBE T4-2. APPLICABLE ONLY TO MRO CENTERS: DISASSEMBLY OF THE GAS GENERATOR AND ASSEMBLY OF THE GAS GENERATOR.	CATEGORY 3: RECOMMENDED INFORMATION ONLY	APPLICABLE	BOE AND BOF				CLOSED	
AW189	APU SB	SB NO. 342-49-048, ISSUE 001 27 APRIL 2023	INTRODUCTION OF NEW COMBUSTOR CASING REFERENCE THE PURPOSES OF THIS MODIFICATION IS TO INTRODUCE NEW COMBUSTOR CASING REFERENCE TO IMPROVE LOCKING AND REPARABILITY OF THE COMPONENT. THE PURPOSE OF THIS SERVICE BULLETIN IS TO INTRODUCE MODIFICATIONS N°342/231 AND 342/396.	CATEGORY 5: SPARE PARTS INFORMATION	APPLICABLE	BOE AND BOF				CLOSED	
AW189	APU SB	SB NO. 342-49-046, ISSUE 001 27 APRIL 2023	INTRODUCTION OF AN ALTERNATIVE TURBINE SHROUD REFERENCE THE PURPOSES OF THIS MODIFICATION IS TO INTRODUCE AN ALTERNATIVE TURBINE SHROUD REFERENCE TO MAINTAIN REPAIR CAPABILITY OF THE GAS GENERATORS. THE PURPOSE OF THIS SERVICE BULLETIN IS TO INTRODUCE MODIFICATIONS N°342/445.	CATEGORY 5: SPARE PARTS INFORMATION	APPLICABLE	BOE AND BOF				CLOSED	
AW189	APU SB	SB NO. 342-49-047, ISSUE 001 27 APRIL 2023	UPDATE OF GAS GENERATOR CONFIGURATION THE PURPOSES OF THIS MODIFICATION IS TO MAINTAIN REPAIR CAPABILITY OF THE GAS GENERATORS BY REGULARIZING THE GAS GENERATOR CONFIGURATION. THE PURPOSE OF THIS SERVICE BULLETIN IS TO INTRODUCE MODIFICATION N°342/445.	CATEGORY 3: RECOMMENDED	APPLICABLE	BOE	WORK ORDER TO BE ISSUED	0.5 MMH		OPEN	
AW139	AIRFRAME AD	AD NO. 2023-0088 26 APRIL 2023	ATA 11 – PLACARDS AND MARKINGS – STRETCHER UNIT / PLACARD – INSTALLATION STRETCHER KIT P/N 139084-501 FITTED BY AEROLITE AG STC ON AB139 AND AW139 HELICOPTERS HAS A DESIGN DEFICIENCY THAT AFFECTS BOTH THE AFFECTED PRIMARY STRETCHER UNIT AND THE AFFECTED STRETCHER. IN CASE OF EMERGENCY LANDING, THIS COULD LEAD TO FAILURE OF THE POSSIBLY RESULTING IN INJURY TO HELICOPTER OCCUPANTS IF NOT CORRECTED.	NOT TO COMPLY	NOT APPLICABLE					CLOSED	
AW139	AIRFRAME SB	SB NO. 139-688 26 APRIL 2023	ATA 31 - KIT FAMILY HUMS INSTALLATION THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION ON HOW TO PERFORM THE INSTALLATION OF THE KIT FAMILY HUMS P/N 4G3130F00611.	OPTIONAL	NOT APPLICABLE			PART I: 250 MMH PART II: 80 MMH, WEIGHT CHANGE		CLOSED	

AW189	AIRFRAME AD	AD NO. 2021-0131R1 25 APRIL 2023	ATA 11 – PLACARDS AND MARKINGS – STRETCHER UNIT / PLACARD – INSTALLATION DESIGN DEFICIENCY TO THE PRIMARY STRETCHER UNIT, P/N 002-0217037-501, OF THE 3-STRETCHER KIT P/N 189-0213100-501 INSTALLED BY AEROLITE AG STC ON AW189 HELICOPTERS. IF NOT CORRECTED, COULD LEAD, IN CASE OF AN EMERGENCY LANDING, TO FAILURE OF THE PRIMARY STRETCHER, POSSIBLY RESULTING IN INJURY TO HELICOPTER OCCUPANTS.		NOT APPLICABLE						CLOSED
AW189	APU SB	SB NO. 342-49-045, ISSUE 001 13 APRIL 2023	RETURN TO SERVICE FOR CIVILIAN USE OF AN EAPU60 AUXILIARY POWER UNIT, APU ACCESSORY OR ELECTRONIC CONTROL UNIT, WHICH COMES FROM A USER NOT CONTROLLED BY A CIVIL AUTHORITY (MILITARY, INTEGRATOR DEVELOPMENT TEST SPECIMEN, ETC.) THE PURPOSE OF THIS MAINTENANCE IS TO ALLOW THE RETURN TO SERVICE OF AN EAPU60 AUXILIARY POWER UNIT, APU ACCESSORY OR ELECTRONIC CONTROL UNIT FOR CIVILIAN USE (UNDER CIVIL AUTHORITY) WHEN A HELICOPTER COMPONENT (APU, APU ACCESSORIES, ECU) IS COMING FROM A USER NOT CONTROLLED BY A CIVIL AUTHORITY.	CATEGORY 2: HIGHLY RECOMMENDED	NOT APPLICABLE						CLOSED
AW189	AIRFRAME SB	SB NO. 189-345 13 APRIL 2023	ATA 63 - MGB ROD ASSY RETROMOD INSTALLATION THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION ON HOW TO PERFORM THE INSTALLATION OF "MGB ROD RETROMOD" P/N 866330P00111.	PART I: WITHIN AND NOT LATER THAN ONE HUNDRED (100) FLIGHT HOURS OR THREE (3) MONTHS WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN. PART II: EVERY TEN (10) FLIGHT HOURS FOR THE FIRST FIFTY (50) FLIGHT HOURS AFTER THE COMPLIANCE WITH PART I OF THIS SERVICE BULLETIN AND THEN EVERY FIFTY (50) FLIGHT HOURS.	APPLICABLE	BOE AND BOF	9M-BOE-15421 9M-BOF-15436	PART I: APPROXIMATELY 2 MMH PART II: APPROXIMATELY 1 MMH			OPEN
AW139	AIRFRAME ASB	ASB NO. 139-734 13 APRIL 2023	ATA 25 – LIFE RAFT INFLATION SYSTEM REPLACEMENT THIS SERVICE BULLETIN IS ISSUED IN ORDER TO REPLACE A SPECIFIC BATCH OF INFLATION SYSTEMS PART OF LIFE RAFT KITS P/N 3G9560F00111, P/N 3G9560F00112 OR P/N 4G2560F00811.	WITHIN AND NOT LATER THAN 300 FLIGHT HOURS OR 1 YEAR WHICHEVER OCCURS FIRST AFTER THE ISSUE OF THIS SERVICE BULLETIN.	NOT APPLICABLE			4 MMH			CLOSED
AW139	AIRFRAME SB	SB NO. 139-684, REV. B 4 APRIL 2023	ATA 93 - TURRET FLIR UNIT REPLACEMENT THIS SERVICE BULLETIN IS ISSUED IN ORDER TO PROVIDE THE NECESSARY INSTRUCTION ON HOW TO PERFORM THE REPLACEMENT OF THE TURRET FLIR UNIT.	OPTIONAL	NOT APPLICABLE			24 MMH			CLOSED