

GENERAL SERVICE LETTER

SUPPORT AND SERVICE DIVISION
40220 Tarnos – France
Tel. (33) (0) 5 59 74 40 00

JFE/CJ/BB

General Service Letter No. 3115/23

Subject: All engines.

Withdrawal of the Type Certificate and end of the support of ARTOUSTE IIID, ASTAZOU IIA, ASTAZOU IIA2, ASTAZOU IIAF, ASTAZOU IIAF2, ASTAZOU IIIC2, ASTAZOU XVI G and TURMO IV B engines.

Dear Sir or Madam,

Safran Helicopter Engines has noticed for several years that there are no more requests for technical support, repair and order of spare parts for ARTOUSTE IIID, ASTAZOU IIA, ASTAZOU IIA2, ASTAZOU IIAF, ASTAZOU IIAF2, ASTAZOU IIIC2, ASTAZOU XVI G and TURMO IV B engines.

Hence, as of April 2024, Safran Helicopter Engines will no longer provide technical and logistical support for the afore-mentioned engine variants, and will request from Certification Authorities that the Type Certificate of the relevant variants be withdrawn.

However, if one (or more) of these engine variants is (are) still in operation in your fleet, please contact us to help us update our database of in-service engines and examine with you possible solutions.

To do so, you can contact either your Field Representative or our nearest subsidiary, or you can contact us at the following address:

Safran Helicopter Engines
Support and Services Division
Avenue Clément Ader
40220 TARNOS - FRANCE

Please contact us if you require further information or assistance.

Yours sincerely,

Technical Support Department



J.F. ESCURET

007321_02