

SB NO. 647, NEW ISSUE

Aeronet Galaxy aerospace2 > Modifications > Edit - Mozilla Firefox

https://galaxy.aeronet.nz/index.html?function=aircraft_templates&opener_name=aircraft&mode=edit&templ: ...

AD/SB ID: 3762 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

Type: SBS Repetitive

Reference/Number: INCORRECT MARKINGS ON SERVICE TOOLS #ST-310

Title/Subject: LYCOMING SB 647

Version No:

Reason For Raising:

URL:

Date: 14 12 2021

Tolerance: 0% (Whole numbers only)

Creep Type: Creep on Completion Unit

Document	Title	Filename
LYCOMING SB 647		3762-1480.pdf
SPECIAL TOOLS R44		3762-1481.pdf
SL-ST-29 1		3762-1482.pdf
SL-ST-29 2		3762-1483.pdf

AD/SB ID: 3762 Close Update Save & Close

General Config List Aircraft List Task List Linked To BOM

@	Aircraft	Based On	Period	Warning Unit	Warning	Last Done	Next Due	Status
	9M-AMA	Not Applicable	-		0	-	-	NOT APPLICABLE