

LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 4

ATA Chapter

		AIRWOR	THINESS D	IRECTIVES A	AND BULLETINS CO	OMPLIANCE				
ASSY P/N (52)	3G3210V01031		ASSY S/N (53)	25451			BALLE:			
AIRWO	RTHINESS DIRECTI	VE AND MANDATORY	BULLETINS	OPTIONAL BULLETINS						
IRWORTHINESS DIRECTIVE/MANDATORY BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)		OT 115 AND	OPTIONAL BULLETIN NUMBER (54)		ASSY TOTAL HOURS (57)	ODCANIZATION	STAMP AND	
		ASSY TOTAL LANDINGS (57)		STAMP AND SIGNATURE (59)	IDOUE (DEVIDION (SE)	DATE OF COMPLIANCE (56)	ASSY TOTAL LANDINGS (57)	ORGANIZATION (58)	SIGNATURE (59)	
ISSUE / REVISION (55)	DATE OF COMPLIANCE (56)	ASSY TOTAL LIFTS/CYCLES (57)			ISSUE / REVISION (55)		ASSY TOTAL LIFTS/CYCLES (57)			
South Section										
						NAME OF STREET				
			B SELECT	73.73.850						
						经 对作品等66%				
MANAGES AND		ALEXE STREET								

E LEONARDO HELICOPTERS

CPR.073.15 F01 - Issue 02 - 28.07.2016

LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Secuon 1 ATA Chapter

Pag. 4 of 4

RETIREMENT LIFE / TIME LIMITS (6) ASSEMBLY DATE (5) P/N (2) S/N (3) MANUFACTURER NAME (4) 10/2019 Ref Assy LIEBHERR 3G3210V01031 25451 Main Shock Absorber Assy LH RETIREMENT LIFE / TIME LIMITS (11) MANUFACTURER NAME (9) ASSEMBLY DATE (10) P/N (7) S/N (8) RETIREMENT LIFE / TIME LIMITS (11) P/N (7) S/N (8) MANUFACTURER NAME (9) ASSEMBLY DATE (10)

NOTE

DESCRIPTION (1)

						ASSEMBL	Y HISTORIC	AL RECORD					
INSTALLATION					REMOVAL								
	,	VC	A	SSY			A/C	Tale 1	ASSY		REASON OF REMOVAL (24)		
	R. MARKS	TOTAL FLIGHT HOURS (15)	TOTAL HOURS (16)	TIME SINCE OH	ORGANIZATION, STAMP AND SIGNATURE (18)	DATE (19)	TOTAL FLIGHT HOURS (20)	ACTUAL TOTAL HOURS (21)	TOTAL HOURS WITH PENALTY FACTOR (22) TOTAL LANDS. WITH PENALTY FACTOR (22)	TIME SINCE OH (23)		ORGANIZATION, STAMP AND	
DATE (12)	(13)	TOTAL LANDINGS (15)	TOTAL LANDINGS (16)	LANDS, SINCE OH (17)			TOTAL LANDINGS (20)	ACTUAL TOTAL LANDINGS (21)		LANDINGS SINCE OH (23)		STAMP AND SIGNATURE (25)	
	S/N (14)	TOTAL LIFTS/CYCLES (15)	TOTAL LIFTS/CYCLES (16)	LIFTS/CYCLES SINCE OH (17)			TOTAL LIFTS/CYCLES (20)	ACTUAL TOTAL LIFTS/CYCLES (21)		LIFTS/CYCLES SINCE OH (23)			
		00.00	00.00	NEW	Leonardo Helicopters								
02/2020	31913				1990								
								79.15					
TO THE REAL PROPERTY.					STARTED LAND	PER STAR		Research to	public to the	ALERCU, LINE	the Property of the Control of the C		



LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 2

ATA Chapter

32

			СО	MPONENTS	INSTALLE	ON ASS	SY						
ASSY P/N (26)	3G3210V01031				ASSY	' S/N (27) 2	25451						
COMPONENT DATA				INSTALL	ATION		S DESIGNATION	REMOVAL					
			ASSY		COMPONENT	A STATE OF LINE	ASSY		СОМ	PONENT			
	P/N (29)	MANUFACTURING DATE (31)	TOTAL HOURS (33)	TOTAL HOURS (34)	TIME SINCE OH (35)	DATE (36)	TOTAL HOURS (38)	TOTAL HOURS (39)	TOTAL HOURS WITH PENALTY	TIME SINCE OH (41)	DATE (42)		
DESCRIPTION (28)	S/N (30)	RETIREMENT LIFE / TIME LIMITS (32)	TOTAL LANDINGS (33)	TOTAL LANDINGS (34)	LANDINGS SINCE OH (35)	STAMP AND SIGNATURE	AND TOTAL LANDINGS URE (38)	TOTAL LANDINGS (39) TOTAL LIFTS/CYCLES (39)	FACTOR (40) TOTAL LANDINGS	LANDINGS SINCE OH (41)	STAMP AND SIGNATURE (43)		
			TOTAL TOTAL LIFTS/CYCLES (33)	TOTAL LIFTS/CYCLES (34)	TAL LIFTS/CYCLES CYCLES SINCE OH (35)	(37)	TOTAL LIFTS/CYCLES (38)		WITH PENALTY FACTOR (40)	LIFTS/CYCLES SINCE OH (41)			
		7. 6. 6. 6.					REPUBLISHE						
						BREEKIN							
							# EXTENSE						
			White Street										



CPR.073.15 F01 - Issue 02 - 28.07.2016

LOG CARD

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

Section 3

Pag. 2 of 4

ATA Chapter 32

		AS	SEMBLY ACTIVITY HISTORY			
ASSY P/I	N (44) 3G3210V01031		ASSY S/N (45)	25451		
DATE (46)	TOTAL HOURS (47) TOTAL LANDINGS (47) TOTAL LIFTS/CYCLES (47)	TASKS (48)	AC	TIVITIES (49)	ORGANIZATION (50)	STAMP AND SIGNATURE (51)