

NOTICE: THIS FORM, DULY UPDATED, MUST FOLLOW THE ASSY

|  |                                |                         |   |                                     |  |
|--|--------------------------------|-------------------------|---|-------------------------------------|--|
| DESCRIPTION (1)<br><b>MAIN GEARBOX ASSY SUPER SILENT</b> | P/N (2)<br><b>3G6320A00135</b> | S/N (3)<br><b>AW212</b> | MANUFACTURER NAME (4)<br><b>Leonardo S.p.A.</b> | ASSEMBLY DATE (5)<br><b>12/2019</b> | RETIREMENT LIFE / TIME LIMITS (6)<br><b>6000 FH OH</b> |
|  | P/N (7)                        | S/N (8)                 | MANUFACTURER NAME (9)                           | ASSEMBLY DATE (10)                  | RETIREMENT LIFE / TIME LIMITS (11)                     |
|  | P/N (7)                        | S/N (8)                 | MANUFACTURER NAME (9)                           | ASSEMBLY DATE (10)                  | RETIREMENT LIFE / TIME LIMITS (11)                     |

NOTE

### ASSEMBLY HISTORICAL RECORD

| INSTALLATION |                                     |                         |                         |                            |  | REMOVAL   |                         |                                |                                      |                            |                        |  |
|--------------|-------------------------------------|-------------------------|-------------------------|----------------------------|--|-----------|-------------------------|--------------------------------|--------------------------------------|----------------------------|------------------------|--|
| DATE (12)    | A/C<br>R MARKS (13)<br><br>S/N (14) | ASSY                    |                         |                            | ORGANIZATION,<br>STAMP AND<br>SIGNATURE (18) | DATE (19) | A/C                     |                                | ASSY                                 |                            | REASON OF REMOVAL (24) | ORGANIZATION,<br>STAMP AND<br>SIGNATURE (25) |
|              |                                     | TOTAL FLIGHT HOURS (16) | TOTAL HOURS (16)        | TIME SINCE OH (17)         |  |           | TOTAL FLIGHT HOURS (20) | ACTUAL TOTAL HOURS (21)        | TOTAL HOURS WITH PENALTY FACTOR (22) | TIME SINCE OH (23)         |                        |  |
|              |                                     | TOTAL LANDINGS (15)     | TOTAL LANDINGS (14)     | LANDS SINCE OH (17)        |  |           | TOTAL LANDINGS (20)     | ACTUAL TOTAL LANDINGS (21)     | TOTAL LANDS SINCE OH (23)            | LANDINGS SINCE OH (23)     |                        |  |
|              |                                     | TOTAL LIFTS/CYCLES (15) | TOTAL LIFTS/CYCLES (14) | LIFTS/CYCLES SINCE OH (17) |  |           | TOTAL LIFTS/CYCLES (20) | ACTUAL TOTAL LIFTS/CYCLES (21) | TOTAL LANDS WITH PENALTY FACTOR (22) | LIFTS/CYCLES SINCE OH (23) |                        |  |
| 01/2020      | 31903                               | 00:00                   | 00:00                   | NEW                        | Leonardo Helicopters<br><i>AP 3079</i>       |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |
|              |                                     |                         |                         |                            |  |           |                         |                                |                                      |                            |                        |  |



## Annex 2 - BOLLETTINI TECNICI STATUS LIST

Helicopter type: AW139  
S/N: 31903

Date: 16/12/2020  
Signature: Zantomio

| B.T.                    | REV. | DATE       | TYPE                   | TITLE   | STATUS | NOTES   |
|-------------------------|------|------------|------------------------|---|--------|---|
| <a href="#">139-597</a> |      | 20/01/2020 | SERVICE BULLETIN       | ATA 31 - KIT FAMILY HUMS RETROMOD                                     | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-598</a> |      | 17/03/2020 | SERVICE BULLETIN       | ATA 78 – INSTALLATION OF EXHAUST NOZZLE BLANKET                       | N.C.W. | AT CUSTOMER OPTION  |
| <a href="#">139-599</a> |      | 09/10/2020 | SERVICE BULLETIN       | ATA 18 - ACTIVE VIBRATION CONTROL SYSTEMS (AVCS) OMNI CONTROL PANEL & | N.A.   | DIFFERENT P/N INSTALLED                                       |
| <a href="#">139-603</a> |      | 06/09/2019 | SERVICE BULLETIN       | ATA 93 – FLIR SS380HDC TFU VARIANT                                    | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-604</a> |      | 14/04/2020 | SERVICE BULLETIN       | ATA 66 – INSTALLATION OF KIT MOORING                                  | N.C.W. | AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER |
| <a href="#">139-605</a> |      | 04/06/2020 | SERVICE BULLETIN       | ATA 32 - ELECTRICAL WHEEL BRAKE CABLE ASSY REPLACEMENT                | C.W.   | COMPLIANT WITH BT 139-137 REV. C                              |
| <a href="#">139-607</a> |      | 20/12/2019 | SERVICE BULLETIN       | ATA 21 - INSTALLATION OF DUAL ZONE HEATING CABIN DUCT VARIANT         | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-608</a> |      | 14/05/2020 | SERVICE BULLETIN       | ATA 53 – INSPECTION OF BL 275 (LH/RH) AT STA 3500                     | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-609</a> |      | 18/12/2019 | SERVICE BULLETIN ALERT | ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT                             | N.C.W. | MGB having logged less than 26000 landings from new           |
| <a href="#">139-610</a> |      | 17/12/2019 | SERVICE BULLETIN ALERT | ATA 95 - EMERGENCY FLOTATION SYSTEM, FLOAT SUPPLY HOSE INSPECTION OF  | N.A.   | DIFFERENT P/N INSTALLED                                       |
| <a href="#">139-612</a> |      | 19/02/2020 | SERVICE BULLETIN       | ATA 11 - FAST ROPING DECAL REPLACEMENT                                | N.A.   | KIT NOT INSTALLED.  |
| <a href="#">139-614</a> |      | 19/12/2019 | SERVICE BULLETIN ALERT | ATA 26 – FIRE EXTINGUISHER INSPECTION AND REPLACEMENT                 | N.A.   | COMPONENT NOT AFFECTED  |
| <a href="#">139-620</a> | B    | 23/11/2020 | SERVICE BULLETIN       | ATA 31 - INSTALLATION OF MPFR P/N D51615-142-090                      | C.W.   | COMPONENT INSTALLED   |
| <a href="#">139-621</a> |      | 18/02/2020 | SERVICE BULLETIN       | ATA 71 - INSTALLATION OF EAPS REMOVABLE PARTS                         |        |   |

C.W. = Compliant With  
N.C.W. = Not Complied With  
N.A. = Not Applicable



## Annex 2 - BOLLETTINI TECNICI STATUS LIST

Helicopter type: AW139  
S/N: 31903

Date: 16/12/2020  
Signature: Zantomio

| B.T.                    | REV. | DATE       | TYPE                   | TITLE   | STATUS | NOTES   |
|-------------------------|------|------------|------------------------|---|--------|---|
| <a href="#">139-560</a> |      | 11/02/2019 | SERVICE BULLETIN       | ATA 25 - INSTALLATION OF THE TWO-PIECE DRESS COVER AND CUSHION ON OFFSHORE PASSENGER SEAT | N.A.   | DIFFERENT P/N INSTALLED                                       |
| <a href="#">139-561</a> |      | 20/02/2019 | SERVICE BULLETIN       | ATA 93 – VIDEO CUSTOMIZATION AND CB PANEL REPLACEMENT                                     | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-563</a> |      | 26/03/2020 | SERVICE BULLETIN       | ATA 93 – AVIONIC VARIANT  | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-566</a> |      | 14/02/2019 | SERVICE BULLETIN       | ATA 99 - EWP/CDU SOFTWARE UPGRADE   | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-567</a> | B    | 18/10/2019 | SERVICE BULLETIN ALERT | ATA 63 - MGB BEARING LOCK-NUT REPLACEMENT   | N.A.   | CANCELLED AND SUPERSEDED BY SB 139-609                        |
| <a href="#">139-569</a> | A    | 27/02/2019 | SERVICE BULLETIN ALERT | ATA 64 – TAIL ROTOR SLIDER ASSY DETAILED INSPECTION                                       | N.C.W. | slider assy having NOT logged more than 2400 FH               |
| <a href="#">139-570</a> |      | 09/04/2020 | SERVICE BULLETIN       | ATA 95 – EFS FLOAT ASSY INFLATION SYSTEM NEW THERMOMANOMETER                              | N.A.   | AT CUSTOMER'S OPTION - NOT REQUESTED BY CONTRACTED WORK ORDER |
| <a href="#">139-571</a> |      | 01/02/2019 | SERVICE BULLETIN ALERT | ATA 64 – DUPLEX BEARING P/N 3G6430V00153 RECALL   | N.A.   | COMPONENT NOT AFFECTED  |
| <a href="#">139-572</a> |      | 22/07/2019 | SERVICE BULLETIN       | ATA 25 – FORWARD FACING 1ST ROW PASSENGER SEATS   | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-573</a> |      | 28/06/2019 | SERVICE BULLETIN       | ATA 31 - KIT HUMS COMPLETION  | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-579</a> |      | 26/11/2019 | SERVICE BULLETIN       | ATA 99 - INSTALLATION OF KIT SIAP AND RWR AND LWR   | N.A.   | NOT APPLICABLE BY HELICOPTER S/N                              |
| <a href="#">139-580</a> |      | 19/03/2019 | SERVICE BULLETIN ALERT | ATA 64 – FIPS TAIL ROTOR BLADES INSPECTION  | N.A.   | KIT FIPS NOT INSTALLED  |

C.W. = Compliant With  
N.C.W. = Not Complied With  
N.A. = Not Applicable