



MODIFICATION RECORD SHEET – MODIFICATION

	DOCUMENT TITLE:	MODIFICATION LIST	A/C TYPE:	EC 120 B	A/C REGN:	9M-HFA	A/C S/N:	1487	APU TYPE:	-
			ENG. TYPE	TURBOMECA ARRIUS 2F	ENG #1 S/N:	34553	ENG #2 S/N:	-	APU S/N:	-


NO.	MOD REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
AIRCRAFT YEAR OF MANUFACTURER: 1 ST JUNE 2007. ALL MODIFICATION EMBODIED BEFORE THIS DATE HAVE BEEN REVIEWED AND ACCOMPLISHED WHERE APPLICABLE BY THE MANUFACTURER BEFORE DELIVERY OF THE ENGINE. REFER TO 9M-HFA INDIVIDUAL INSPECTION LOG BOOK FOR THE MODIFICATION EMBODIMENT.				
1	EC120-53-70-10	REPAIR OF CRACK ON THE BATTERY SUPPORT STRUCTURE	RDAS REF.: EC120-53-70-10 WORK REPORT REF.: 358/2010 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	REPAIRED ON 23.07.2010
2	EASA STC NO. 10027406	NSE - BRITE SAVER 2 - USAGE MONITORING SYSTEM	WORK ORDER REF.: HFA/1-51 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 28.06.2017
3	EASA STC NO. 10016732	SFIM TWO AXIS VFR AUTOPILOT SYSTEM (SAGEM PA85)	WORK ORDER REF.: HFA/1-52 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 11.07.2017
4	EASA MINOR CHANGE APPROVAL 10027255	ADF KR-87 AND RADAR ALTIMETER KRA-405B	WORK ORDER REF.: HFA/1-50 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 03.07.2017
5	EASA MINOR CHANGE APPROVAL 100027227	HELIDAX CHRONOMETER INSTALLATION	WORK ORDER REF.: HFA/1-50 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 03.07.2017
6	AEROTEC MODIFICATION 17034	EC120B ANCILLARY CONSOLE EXTENSION	WORK ORDER REF.: HFA/1-54 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 10.07.2017
7	BABCOCK MODIFICATION 386	VHF SYSTEM W/ 8.33KHZ STANDARD	WORK ORDER REF.: HFA/1-54 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 28.06.2017

MODIFICATION RECORD SHEET – MODIFICATION

	DOCUMENT TITLE:	MODIFICATION LIST	A/C TYPE:	EC 120 B	A/C REGN:	9M-HFA	A/C S/N:	1487	APU TYPE:	-
			ENG. TYPE	TURBOMECA ARRIUS 2F	ENG #1 S/N:	34553	ENG #2 S/N:	-	APU S/N:	-

NO.	MOD REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
8	BABCOCK MODIFICATION 394	AVIONIC (MASTER) SWITCH & EMERGENCY SWITCH	WORK ORDER REF.: HFA/1-42 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 1 OF 2	COMPLETED ON 04.07.2017
9	BABCOCK MODIFICATION 385	DME, GPS, XPDR (ELS)	WORK ORDER REF.: HFA/1-42 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 2 OF 2	COMPLETED ON 19.07.2017
10	EASA STC 10027509	SAGEM INTERGRATED COCKPIT DISPLAY SYSTEM ICDS-8A	WORK ORDER REF.: HFA/1-53 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 2 OF 2	COMPLETED ON 07.07.2017
11	ESI/EC120B/091	INSTALLATION OF DUAL LANGUAGE PLACARD, AIRCRAFT REGISTRATION NUMBER & MALAYSIAN FLAG PLACARD, AND OWNER'S IDENTIFICATION PLATE	WORK ORDER REF.: MD/EC120B/17/10/018/9M-HFA MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 2 OF 2	COMPLETED ON 14.11.2017
12	ESI/EC120B/180	REPAIR OF THE MGB LOWER HOUSING (P/N C632A2117101)	RDAS REF.: 120-63-1362-19 WORK REPORT REF.: 358/2010 MYCOPTER MODIFICATION COMPLIANCE SUMMARY PAGE 2 OF 2	REPAIRED ON 10.07.2019

MODIFICATION RECORD SHEET – MODIFICATION

	DOCUMENT TITLE:	MODIFICATION LIST	A/C TYPE:	EC 120 B	A/C REGN:	9M-HFA	A/C S/N:	1487	APU TYPE:	-
			ENG. TYPE	TURBOMECA ARRIUS 2F	ENG #1 S/N:	34553	ENG #2 S/N:	-	APU S/N:	-

NO.	MOD REF.	DESCRIPTION	COMPLIANCE REF. & DATE	REMARKS
-----	----------	-------------	---------------------------	---------

- END OF PAGE -

PREPARED BY: CHE NOR AMANI HUSNA CHE HASSAN

DATE: 7TH AUGUST 2020

SIGN & STAMP: 

VERIFIED BY: ZAHY NADHIRA BINI MOHAMED ZUHARI

DATE: 12 AUG 2020

SIGN & STAMP:  