

SUMMARY OF CHANGES

SECTION C

TASK TABLE:

REV CODE (R,N,D)	MRBR TASK REFERENCE	CHANGE DESCRIPTION
R	252100M-02	TASK TITLE MINOR CHANGE. THIS TASK COVER ALL SEAT BELTS INCLUDING PREVIOUS 252400M-04
R	252100M-03	TASK TITLE MINOR CHANGE. THIS TASK COVER ALL SEAT BELTS INCLUDING PREVIOUS 252400M-05
N	252100M-06	NEW TASK ADDED. THIS TASK REPLACED PREVIOUS 252400M-01
N	252100M-07	NEW TASK ADDED. THIS TASK REPLACED PREVIOUS 252400M-02
N	252100M-08	NEW TASK ADDED. THIS TASK REPLACED PREVIOUS 252400M-06
N	252100M-09	NEW TASK ADDED. THIS TASK REPLACED PREVIOUS 252400M-07
N	252100M-10	NEW TASK ADDED. THIS TASK REPLACED PREVIOUS 252400M-08
D	252400M-01	TASK DELETED BECAUSE COVERED BY 252100M-06
D	252400M-02	TASK DELETED BECAUSE COVERED BY 252100M-07
D	252400M-03	TASK DELETED BECAUSE COVERED BY 252100M-05
D	252400M-04	TASK DELETED BECAUSE COVERED BY 252100M-02
D	252400M-05	TASK DELETED BECAUSE COVERED BY 252100M-03
D	252400M-06	TASK DELETED BECAUSE COVERED BY 252100M-08
D	252400M-07	TASK DELETED BECAUSE COVERED BY 252100M-09
D	252400M-08	TASK DELETED BECAUSE COVERED BY 252100M-10
R	526200M-01	TASK TYPE CHANGE (WAS GVI) AND INTERVAL AMENDED FOLLOWING IN SERVICE FEEDBACKS.
R	623000M-10	TASK TYPE CHANGE (WAS GVI) AND DISMOUNTING REQUIREMENT ADDEDD FOLLOWING IN SERVICE FEEDBACKS.
R	642000M-10	TASK TYPE CHANGE (WAS GVI) AND DISMOUNTING REQUIREMENT ADDEDD FOLLOWING IN SERVICE FEEDBACKS. INTERVAL MOVED TO 800FH.
R	643000M-05	TASK TYPE CHANGE (WAS GVI) AND DISMOUNTING REQUIREMENT ADDEDD FOLLOWING IN SERVICE FEEDBACKS. INTERVAL MOVED TO 800FH.
R	781000M-03	TASK INTERVAL MOVED TO 800FH FOLLOWING SERVICE FEEDBACKS.

SECTION C – ROTORCRAFT SYSTEMS AND POWERPLANT

5. LIST OF TASKS

REV.	MRB-R TASK NUMBER	TASK CODE	TASK TITLE	SOURCE	INTERVAL	SAM P-LING	FEC	APPLICABILITY		ZONE	ACCESS & REMARKS	JBPM AW189 APPLICABILITY	
								AW189	AW189ER			49045	49053
MSI 25-21-00: PASSENGER/OPERATING CREW													
R	252100M-02	DI	DETAILED INSPECTION OF CABIN SEAT BELT	MSI	1 YR	-	8	YES	YES	-	-	YES	YES
R	252100M-03	OC	OPERATIONAL CHECK OF CABIN SEAT BELT LOCKING AND INERTIAL MECHANISM	MSI	1 YR	-	8	YES	YES	-	-	YES	YES
N	252100M-06	DI	DETAILED INSPECTION OF TROOP SEAT ASSEMBLY	MSI	2 YR	-	8	WITH FOLDING TROOP SEATS	WITH FOLDING TROOP SEATS	-	-	NO	NO
N	252100M-07	DI	DETAILED INSPECTION OF TROOP SEAT FLOOR / CEILING SEAT TRACK	MSI	2 YR	-	8	WITH FOLDING TROOP SEATS	WITH FOLDING TROOP SEATS	-	-	NO	NO
N	252100M-08	DI	DETAILED INSPECTION OF 4TH ROW (REAR ROW) CENTRE CABIN SEAT FOLDING INSTALLATION	MSI	1 YR	-	8; 9	WITH 4TH ROW FOLDING CABIN SEATS	WITH 4TH ROW FOLDING CABIN SEATS	-	-	NO	NO
N	252100M-09	FC	FUNCTIONAL CHECK (GAP MEASUREMENT) OF TROOP SEAT ENERGY ABSORBING DEVICE	MSI	1 YR	-	8	WITH FOLDING TROOP SEATS	WITH FOLDING TROOP SEATS	-	-	NO	NO
N	252100M-10	DIS	DISCARD TROOP SEAT RESTRAINT SYSTEM INTERVAL NOTE: 12 YR FROM MANUFACTURING	MSI	NOTE	-	8	WITH FOLDING TROOP SEATS	WITH FOLDING TROOP SEATS	-	-	NO	NO

MSI 25-24-00: SAR CABIN INTERIOR KIT

D	252400M-01	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-02	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-03	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-04	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-05	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-06	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-07	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-
D	252400M-08	-	TASK DELETED WITH MRBR ISSUE P	-	-	-	-	-	-	-	-	-	-

MSI 52-62-00: PASSENGER ELECTRICAL FOLDABLE FOOTSTEPS KIT

R	526200M-01	DI	DETAILED INSPECTION OF ELECTRICAL FOLDABLE FOOTSTEP MECHANISM	MSI	100 FH; 6 MH	-	6	WITH ELECTRICAL FOLDABLE FOOTSTEP KIT	NO	-	-	NO	NO
---	------------	----	---	-----	--------------	---	---	---------------------------------------	----	---	---	----	----

MSI - RDSI 62-30-00: ROTATING CONTROLS ROTOR SHAFT(S) / SWASH PLATE ASSEMBLIES

R	623000M-10	DI	DETAILED INSPECTION OF THE MAIN ROTOR ROTATING SCISSORS ASSEMBLY	MSI; RDSI (ED) ; CPCP	1600 FH	-	5	YES	YES	-	-	YES	YES
---	------------	----	--	-----------------------	---------	---	---	-----	-----	---	---	-----	-----

MSI - RDSI 64-20-00: ROTOR HEAD

R	642000M-10	DI	DETAILED INSPECTION OF THE TAIL ROTOR HUB SCISSOR INTERFACE NOTE: SHOULD BE ACCOMPLISHED IN	RDSI (ED) ; CPCP	800 FH	-	5	YES	YES	430	ACCESS: EXTERNAL	YES	YES
---	------------	----	--	------------------	--------	---	---	-----	-----	-----	------------------	-----	-----

			CONJUNCTION WITH TASK 643000M-05										
MSI - RDSI 64-30-00: ROTATING CONTROL													
R	643000M-05	DI	DETAILED INSPECTION OF THE TAIL ROTOR SCISSORS LINK BUSHES AND SLEEVES NOTE: SHOULD BE ACCOMPLISHED IN CONJUNCTION WITH TASK 642000M-10	MSI; RDSI (ED); CPCP	800 FH	-	5	YES	YES	430	ACCESS: EXTERNAL	YES	YES
MSI 78-10-00: COLLECTOR / NOZZLE													
R	781000M-03	DI	DETAILED INSPECTION OF EJECTOR NOZZLE INCLUDING WELDS, MOUNTINGS AND ATTACHMENT SCREWS	MSI	800 FH	-	9	YES	YES	-	-	YES	YES